



Adelaide
Environmental Health Associates, Inc.

1511 Route 22, Suite C24
Brewster, NY 10509 845.278.7710
90 State Street, Suite 700
Albany, NY 12207 518.874.0617
1967 Wehrle Drive, Suite One
Buffalo, NY 14221 716.402.4580
E-mail: adelaidemail@adelaidellc.com
Fax: 845.278.7750

RENOVATION SURVEY FOR ASBESTOS CONTAINING MATERIALS AND LEAD BASED PAINT

PERFORMED AT:

SUNY Purchase – Heritage Site
735 Anderson Hill Road
Purchase, New York 10577
Adelaide Project# PGA:15100.02-IN

PREPARED FOR:

Mr. Ken Pojman, RA, AIA
Peter Gisolfi Associates
566 Warburton Avenue
Hastings on Hudson, New York 10706

PREPARED BY:

Jason Fullum
April 18, 2016
June 1, 2016 Amended

REVIEWED BY:

Stephanie A. Soter
President

RENOVATION SURVEY FOR ASBESTOS CONTAINING MATERIALS AND LEAD BASED PAINT

TABLE OF CONTENTS

1.0	Background/Purpose	1
2.0	Executive Summary of Inspection Results	1
2.1	Summary of Asbestos Containing Materials	1
2.2	Summary of Lead Based Paint	4
2.3	Negative Materials List	6
3.0	Asbestos Field Procedures and Analysis Methodology	9
3.1	Inspection	9
3.2	Sampling	9
3.3	Analysis	10
4.0	Conclusions and Recommendations	11
5.0	Areas not Accessible	11
6.0	Report Certifications	11
7.0	Transmittal of Building Survey	11

APPENDICES

Asbestos Analytical Results and Chain of Custody Forms	Appendix A
XRF Readings	Appendix B
Personnel and Laboratory Certifications	Appendix C
Sample Location Map and Photos	Appendix D
Affected Area Maps	Appendix E
NYS DOL Guidelines for Contaminated Areas	Appendix F

1.0 BACKGROUND/PURPOSE

Adelaide Environmental Health Associates, Inc. (Adelaide) was retained by Peter Gisolfi Associates to perform an investigative asbestos and lead based paint survey at SUNY Purchase in Purchase, New York. This survey was based on the scope provided by Peter Gisolfi Associates for renovation work in the Administration Building, Human Resources Building, Business Annex, Facilities Building and the Gate House. The inspection was performed on March 23, 2016 through March 25, 2016 and April 13, 2016 by Adelaide representative Jason Fullum (NYS Asbestos Inspector and EPA Lead Based Paint Inspector). Additional inspections were performed on May 13, 2016 and May 27, 2016 by Adelaide representatives Robert See and Jason Fullum (NYS Asbestos Inspectors and EPA Lead Based Paint Inspectors).

2.0 EXECUTIVE SUMMARY OF INSPECTION RESULTS

Following the scope of work that was given to us, Adelaide inspected the interior and exterior of each building for the future renovation work. Adelaide collected three hundred and one (301) asbestos samples and two hundred and forty five (245) XRF readings from the above mentioned areas. Nineteen (19) samples/homogenous areas tested positive for asbestos and seventy five (75) XRF readings are positive for lead based paint.

There was no suspect wire insulation in the Facilities Building or Human Resources Building.

There was no access to the Presidents Apartment in the Administration Building. Only plaster samples were taken from this area during the additional inspection.

During the additional inspections, Adelaide collected ninety (90) asbestos samples from areas throughout the Administration Building. Four (4) samples/homogenous areas tested positive for asbestos.

2.1 SUMMARY OF ASBESTOS CONTAINING MATERIALS

Samples collected by Adelaide March 23, 2016 – March 25, 2016 and April 13, 2016 **Administration Building**

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
10 & 281	Wall Plaster – Base Coat	10,000 SF	Sig. Damaged	Northwest Side of the Basement and First Floor Center Section – The Basement is Significantly Damaged and Falling on the Floor. See Appendix F.

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
24	Ceiling Plaster – Base Coat	5,000 SF	Sig. Damaged	Basement Northwest Section – The Basement is Significantly Damaged and Falling on the Floor. See Appendix F.
39	Joint Compound	250 SF	Damaged	Basement Area 0007
49	Material Behind Heat Shield for Radiators	60 SF	Damaged	Basement Area 0004
52	Pipe Insulation Debris	2 SF	Sig. Damaged	Basement Area 0004 – Pipe Insulation is Assumed to Exist Within Wall Cavities

Human Resources Building

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
154	Pipe Insulation	25 LF	Damaged	Basement Area – Pipe Insulation is Assumed to Exist Within Wall Cavities
157	Debris on Metal Support	1 SF	Sig. Damaged	Crawlspace Area
Assumed	Boiler Flue Sealant	4 SF	Damaged	Unable to Test as the Boiler Was Still Active
Assumed	Roofing Materials		Good	No Access at Time of Inspection

Gate House Building

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
196	Linoleum and Mastic	250 SF	Damaged	1 st Floor – West Room (Kitchen)
202	Pipe Insulation	50 LF	Sig. Damaged	Basement – Some Pipe Insulation in the Crawlspace has Become Loose and is Laying on the Ground. See Appendix F.
205	Mudded Fitting	1 LF	Damaged	Basement
211	Flue Sealant	4 SF	Damaged	Basement

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
212	9x9 Floor Tile and Mastic	40 SF	Damaged	2 nd Floor Bathroom

Facilities Building

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
216	Floor Tile – Beige with Streaks	70 SF	Good	1 st Floor – Area 1009
226	Cement Board	300 SF	Damaged	1 st Floor – Area 1005 Boiler Room
228	Flue Sealant	4 SF	Damaged	1 st Floor – Area 1005 Boiler Room
246	Cementitious Siding	1,500 SF	Damaged	Exterior
250	Pipe Insulation	150 LF	Sig. Damaged	Crawlspace
253	Debris	100 SF	Sig. Damaged	Crawlspace – See Appendix F

Samples collected by Adelaide May 13, 2016 and May 27, 2016

Administration Building

Sample #	Material Sampled	Approximate Quantity	Condition	Areas Affected
16	Wall Plaster – Top Coat	7,500 SF	Sig. Damaged	Basement Center Section – The Basement is Significantly Damaged and Falling on the Floor. See Appendix F.
24	Ceiling Plaster – Top Coat	5,000 SF	Sig. Damaged	Basement Center Section – The Basement is Significantly Damaged and Falling on the Floor. See Appendix F.
28	Wall Plaster – Base Coat	5,000 SF	Damaged	Presidents Apartment
88	Ceiling Plaster – Base Coat	5,000 SF	Damaged	3 rd Floor Center Section

2.2 SUMMARY OF LEAD BASED PAINT

XRF Readings collected by Adelaide March 23, 2016 – March 25, 2016

Administration Building

Sample #	Sample Location	Material Sampled	mg/cm ²
9	Basement 0004	Door – Brown – Metal	11.25
12	Basement 0009	Wall – White – Plaster	13.05
31	1 st Floor 1005	Wall – White – Plaster	27.60
32	1 st Floor 1005	Ceiling – White – Plaster	5.25
33	1 st Floor 1005D	Wall – White – Plaster	27.45
43	2 nd Floor 2020	Radiator – White – Metal	5.10
47	2 nd Floor 2012	Door – White – Wood	18.75
48	2 nd Floor 2012	Door Frame – White – Wood	7.00
49	2 nd Floor 2012	Wall – Beige – Plaster	20.40
50	2 nd Floor 2010	Wall – Yellow – Plaster	26.10
51	2 nd Floor 2010	Door Frame – Brown – Wood	46.65
52	2 nd Floor 2010	Door – Brown – Wood	48.30
53	2 nd Floor 2011	Wall – Beige – Plaster	28.65
54	2 nd Floor 2011	Door Frame – White – Wood	37.05
55	2 nd Floor 2011	Door – White – Wood	24.90
68	2 nd Floor 2008a	Wall – Green – Plaster	15.60
69	2 nd Floor 2008a	Door Frame – White – Wood	25.05
70	2 nd Floor 2007	Door Frame – White – Wood	2.10
71	2 nd Floor 2007	Door – White – Wood	23.55
74	3 rd Floor 3005	Wall – Beige – Plaster	20.70
75	3 rd Floor 3011	Wall – Beige – Plaster	24.75
76	3 rd Floor 3001	Wall – Beige – Plaster	16.20
80	3 rd Floor 3001	Ceiling – White – Plaster	7.50
92	1 st Floor 1001	Door – White – Wood	5.60
98	1 st Floor 1001c	Wall – Beige – Plaster	20.85
99	1 st Floor 1001c	Wall – White – Wood	38.25
100	1 st Floor 1001c	Door Frame – White – Wood	29.85
101	1 st Floor 1001c	Door – White – Wood	24.60
218	Exterior	Wall – White – Wood	46.95
227	Exterior	Column – Gray – Metal	1.40

Human Resources Building

Sample #	Sample Location	Material Sampled	mg/cm ²
102	3 rd Floor 3004	Stair Newel – White – Wood	14.55
103	3 rd Floor 3004	Stair Baluster – White – Wood	14.10
104	3 rd Floor 3004	Wall – White – Plaster	5.80
105	3 rd Floor 3004	Door Frame – White – Wood	19.65
106	3 rd Floor 3004	Door – White – Wood	15.15
107	3 rd Floor 3004	Ceiling – White – Plaster	4.50
108	3 rd Floor 3004	Window Case – White – Wood	18.00
112	3 rd Floor 3002	Window Case – White – Wood	18.30
115	3 rd Floor 3002	Door Frame – White – Wood	13.80
116	3 rd Floor 3002	Door – White – Wood	19.95
118	2 nd Floor 2001	Door Frame – White – Wood	14.70
120	2 nd Floor 2001	Door – White – Wood	20.70
122	2 nd Floor 2002	Window Case – White – Wood	16.50
124	2 nd Floor 2003	Wall – Beige – Plaster	16.50
125	2 nd Floor 2003	Door Frame – White – Wood	20.70
126	2 nd Floor 2003	Door – White – Wood	19.35
133	1 st Floor 1001	Wall – Beige – Plaster	25.50
138	1 st Floor 1003	Wall – Beige – Plaster	11.25
140	1 st Floor 1003a	Door Frame – White – Wood	15.75
141	1 st Floor 1003a	Door – White – Wood	20.10
231	Exterior	Wall – White – Wood	54.75
232	Exterior	Door Frame – Blue – Wood	56.40
233	Exterior	Door – Blue – Wood	48.75
235	Exterior	Wall – White – Brick	1.80
236	Exterior	Window Case – Blue – Wood	4.30
237	Exterior	Door Frame – Blue – Wood	2.80

Business Annex Building

Sample #	Sample Location	Material Sampled	mg/cm ²
155	1 st Floor 1001	Wall – White – Plaster	13.20
157	1 st Floor 1002	Wall – Beige – Plaster	11.40
161	1 st Floor 1002	Ceiling – White – Plaster	3.90

Gate House Building

Sample #	Sample Location	Material Sampled	mg/cm ²
166	Living Room	Wall – Yellow – Plaster	19.35
167	Living Room	Door Frame – Yellow – Wood	27.00
169	Living Room	Door – Yellow – Wood	27.15
170	Kitchen	Wall – Yellow – Plaster	25.65
171	Kitchen	Window Case – Yellow – Wood	28.20
172	Kitchen	Window Sash – Yellow – Wood	29.25
173	Kitchen	Cabinet – Yellow – Wood	24.90
175	Living Room	Wall – White – Plaster	22.35
177	Bedroom 1	Wall – White – Plaster	23.85
180	Bedroom 1	Door Frame – White – Wood	25.80
181	Bedroom 1	Door – White – Wood	19.65

Facilities Building

Sample #	Sample Location	Material Sampled	mg/cm ²
189	2 nd Floor 2001a	Wall – White – Wood	20.85
194	2 nd Floor	Stair Newel – White – Wood	17.40
195	2 nd Floor	Stair Baluster – White – Wood	21.75
207	Exterior	Wall – White – Concrete	5.70
211	Exterior	Wall – White – Wood	4.20

2.3 NEGATIVE MATERIALS LIST:**Administration Building**

- Tar Paper Behind Wood
- Wall Plaster Top Coat
- Ceiling Plaster Top Coat
- Stair Covering
- Flue Sealant
- Stone Mortar

- Drywall
- Red Firestop
- Ceramic Floor Grout
- Concrete
- Black Wall Mastic
- Brick Mortar
- Fireplace Stone and Brick Mortar
- Black Border Floor Tile
- Tan with Swirls Floor Tile
- Black Floor Mastic
- Beige Flooring and Felt
- Small Black and Brown Flooring
- Black Flooring on Concrete
- 12x12 Beige Floor Tile
- Beige with Brown Streaks Floor Tile
- 12x12 Gray Floor Tile
- 12x12 White Floor Tile
- 12x12 Black Floor Tile
- 4" Vinyl Covebase and Mastic
- Textured Ceiling
- Brown Floor Mastic
- 9x9 Ceramic Floor Mortar
- Blown In Insulation
- Canvas Wrap Over Horsehair Insulation
- Roof Shingles and Felt
- Window Caulk
- Wire Insulation

Human Resources Building

- Wall Plaster – Top and Base Coats
- Ceiling Plaster – Top and Base Coats
- Multicolored Linoleum and Flooring Underneath
- 12x12 Gray Floor Tile
- 12x12 White Floor Tile
- Black Mastic
- Sink Coating
- Fireplace Stone Mortar
- CMU Mortar
- Drywall
- Joint Compound
- Debris on Galvanized Elbow
- Window Caulk

Business Annex

- Skim Coat on Concrete
- Concrete
- Black Mastic Under Carpet
- Drywall
- Joint Compound
- Brick Mortar
- Roof Shingles and Felt
- Wire Insulation

Gate House Building

- 12x12 Ceiling Tile
- Glue Dabs
- Drywall
- Wall Plaster – Top and Base Coats
- Brick Mortar
- Back Splash
- Debris on Ground in Boiler Room
- Concrete
- Joint Compound
- Roof Shingle and Felt
- Window Caulk
- Wire Insulation

Facilities Building

- Mastic Under Floor Tile
- Ceramic Grout
- 12x12 Spline Ceiling Tile
- Drywall
- Joint Compound
- 4" Covebase and Mastic
- Wood Floor Laminate
- Fiberboard Walls
- Window Caulk
- Roof Shingles and Felt

3.0 ASBESTOS FIELD PROCEDURES AND ANALYSIS METHODOLOGY

3.1 INSPECTION

Guidelines used for the inspection were established by the U.S. Environmental Protection Agency (EPA) in the Guidance for Controlling Asbestos Containing Materials in Buildings, Office of Pesticides and Toxic Substances, DOC# 560/5-85-024 and 40 CFR Part 763, Asbestos Hazard Emergency Response Act (AHERA). Field information was organized as per the AHERA concept of a homogeneous area (HA); that is, suspect Asbestos Containing Materials (ACM) with similar age, appearance, and texture were grouped together, sampled and assessed for condition.

For the purposes of this inspection, suspect ACM has been placed in three material categories: thermal, surfacing, and miscellaneous.

Surfacing materials are those that are sprayed on, troweled on or otherwise applied to surfaces for fireproofing, acoustical, or decorative purposes (e.g., wall and ceiling plaster).

Thermal materials are those applied to heat pipes or other structural components to prevent heat loss or gain or prevent water condensation (e.g., pipe and fitting insulation, duct insulation, boiler flue).

Miscellaneous materials are interior building materials on structural components, structural members or fixtures, such as floor and ceiling tiles, etc. and do not include surfacing material or thermal system insulation.

3.2 SAMPLING

SURFACING MATERIALS

Surfacing materials were grouped into homogeneous sampling areas. A homogeneous area contains material that is uniform in color and texture and appears identical in every other respect. Materials installed at different times belong to different sampling areas. Homogeneous areas were determined on per floor basis.

The following protocol was used for determining the number of samples to be collected:

- At least three bulk samples were collected from each homogeneous area that is 1,000 square feet or less.
- At least five bulk samples were collected from each homogeneous area that is greater than 1,000 square feet but less than or equal to 5,000 square feet.
- At least seven bulk samples were collected from each homogeneous area that is greater than 5,000 square feet.

THERMAL SYSTEM INSULATION (TSI)

The concept of homogeneous sampling areas applies equally well to thermal insulation as to surfacing material. A "typical" building may contain multiple insulated pipe runs from any combination of the following categories:

- Hot water supply and/or return
- Cold water supply
- Chilled water supply
- Steam supply and/or return
- Roof or system drain

The following protocol was used for determining the number of samples to be collected.

- Collect at least three bulk samples from each homogeneous area of thermal system insulation.
- Collect at least one bulk sample from each homogeneous area of patched thermal system insulation if the patched section is less than 6 linear or square feet.
- In a manner sufficient to determine whether the material is ACM or not ACM, collect a minimum of three bulk samples from each homogeneous insulated mechanical system tee, elbow, and valve.

Bulk samples are not collected from any homogeneous area where the certified inspector has determined that the thermal system insulation is fiberglass, foam glass, or rubber.

MISCELLANEOUS MATERIALS

Miscellaneous materials are grouped into different homogeneous areas and at least two bulk samples are collected from each homogeneous area as per the clarification letter from the EPA and the Professional Abatement Contractors of New York, Inc in November of 2007.

3.3 ANALYSIS

Bulk samples of suspect ACM were analyzed by Polarized Light Microscopy (PLM) with dispersion staining, as described in 40CFR Part 763 and the National Emissions Standard for Hazardous Air Pollutants (NESHAPS).

The New York State (NYS) Department of Health has recently revised the PLM Stratified Point Counting Method. The new method, Polarized Light Microscopy for Identifying and Quantitating Asbestos in Bulk Samples can be found as Item 198.1 in the Environmental Laboratory Accreditation Program (ELAP) Certification manual.

The State of New York ELAP has determined that analysis of NOB materials is not reliably performed by PLM. Therefore, if PLM yields negative results for a non-friable material, it must be confirmed by Transmission Electron Microscopy (TEM) analysis.

All NOB samples were initially analyzed by utilizing TEM methodology.

4.0 CONCLUSIONS AND RECOMMENDATIONS

This survey concluded that the materials listed in Section 2.0 Executive Summary tested ***positive or are assumed positive for asbestos and for lead based paint.***

Asbestos: These areas must be abated prior to building demolition or renovation if they are to be disturbed. Contaminated areas need to be vacated and isolated. See Appendix F

Lead: These areas must be either abated or Lead safe work practices must be implemented during the renovation or demolition activities if these areas are to be disturbed.

5.0 AREAS NOT ACCESSIBLE

Adelaide Environmental Health Associates inspected and sampled materials which were visible and/or accessible to the survey team. Adelaide does not inspect physically inaccessible areas, such as between walls, above fixed ceilings, under concrete slabs, etc. This report makes no representations as to the content of these areas or materials.

All materials present in those not accessible areas shall be assumed positive until tested.

6.0 REPORT CERTIFICATIONS

Adelaide Environmental Health Associates certifies that the information contained herein is based on the physical and visual inspections conducted by Adelaide and data collected during the inspection survey. This survey report does not constitute a NYS Asbestos Abatement Design and should not be used for bidding purposes. A NYS Abatement Design should be prepared by a NYS Asbestos Designer working for a NYS Asbestos Company (as required by NYS Code Rule 56).

7.0 TRANSMITTAL OF BUILDING/STRUCTURE ASBESTOS SURVEY

One (1) copy of the results of the building/structure asbestos survey shall be immediately transmitted by the building/structure owner as follows:

- (1) One (1) copy of the completed asbestos survey shall be sent by the owner or their agent to the local government entity charged with issuing a permit for such

demolition, renovation, remodeling or repair work under applicable State or local laws.


(2) The completed asbestos survey for controlled demolition (as per Subpart 56-11.5) or pre-demolition asbestos projects shall also be submitted to the appropriate Asbestos Control Bureau district office.

(3) The completed asbestos survey shall be kept on the construction site with the asbestos notification and variance, if required, throughout the duration of the asbestos project and any associated demolition, renovation, remodeling or repair project.

APPENDIX A

ASBESTOS ANALYTICAL RESULTS

AND CHAIN OF CUSTODY FORMS

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Attn: **Adelaide Associates, LLC**
1511 Route 22
Suite C-24
Brewster, NY 10509

Phone: (845) 278-7710
 Fax: (845) 278-7750
 Received: 03/28/16 9:27 AM
 Analysis Date: 4/3/2016
 Collected: 3/23/2016

Project: SUNY Purchase, 735 Anderson Hill Road, Purchase, NY 10577, Project #: PGS:15100.02-IN

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 1-1 061602991-0001		Description Homogeneity	Bsmt., Admin., Tar Paper behind Wood Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Black			<1% Anthophyllite <1% Total
Sample ID 1-2 061602991-0002		Description Homogeneity	Bsmt., Admin., Tar Paper behind Wood Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Black			<1% Anthophyllite <1% Total
Sample ID 2-3 061602991-0003		Description Homogeneity	Bsmt., Admin., Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 2-4 061602991-0004		Description Homogeneity	Bsmt., Admin., Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 2-5 061602991-0005		Description Homogeneity	Bsmt., Admin., Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	2-6	Description	Bsmt., Admin., Wall Plaster, Top Coat			
	061602991-0006	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	2-7	Description	Bsmt., Admin., Wall Plaster, Top Coat			
	061602991-0007	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	2-8	Description	Bsmt., Admin., Wall Plaster, Top Coat			
	061602991-0008	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	2-9	Description	Bsmt., Admin., Wall Plaster, Top Coat			
	061602991-0009	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	3-10	Description	Bsmt., Admin., Wall Plaster, Base Coat			
	061602991-0010	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Brown			98.52% Non-fibrous (other)	1.48% Chrysotile
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	3-11	Description	Bsmt., Admin., Wall Plaster, Base Coat			
	061602991-0011	Homogeneity				
PLM NYS 198.1 Friable	4/3/2016					Positive Stop
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
3-12 061602991-0012	Description Homogeneity	Bsmt., Admin., Wall Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
3-13 061602991-0013	Description Homogeneity	Bsmt., Admin., Wall Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
3-14 061602991-0014	Description Homogeneity	Bsmt., Admin., Wall Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
3-15 061602991-0015	Description Homogeneity	Bsmt., Admin., Wall Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
3-16 061602991-0016	Description Homogeneity	Bsmt., Admin., Wall Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
4-17 061602991-0017	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	White	100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	4-18	Description	Bsmt., Admin., Ceiling Plaster, Top Coat			
	061602991-0018	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	4-19	Description	Bsmt., Admin., Ceiling Plaster, Top Coat			
	061602991-0019	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	4-20	Description	Bsmt., Admin., Ceiling Plaster, Top Coat			
	061602991-0020	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	4-21	Description	Bsmt., Admin., Ceiling Plaster, Top Coat			
	061602991-0021	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	4-22	Description	Bsmt., Admin., Ceiling Plaster, Top Coat			
	061602991-0022	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	4-23	Description	Bsmt., Admin., Ceiling Plaster, Top Coat			
	061602991-0023	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White			100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
5-24 061602991-0024	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	Brown	98.46% Non-fibrous (other)	1.54% Chrysotile
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
5-25 061602991-0025	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
5-26 061602991-0026	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
5-27 061602991-0027	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
5-28 061602991-0028	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
5-29 061602991-0029	Description Homogeneity	Bsmt., Admin., Ceiling Plaster, Base Coat		
PLM NYS 198.1 Friable	4/3/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos			Asbestos
Sample ID		Description Homogeneity	Fibrous	Non-Fibrous		
5-30 061602991-0030			Bsmt., Admin., Ceiling Plaster, Base Coat			
PLM NYS 198.1 Friable	4/3/2016					Positive Stop
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
6-31 061602991-0031			Bsmt., Admin., 0012, Stair Covering Heterogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Black				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Gray/Black				None Detected
6-32 061602991-0032			Bsmt., Admin., 0012, Stair Covering Heterogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Black				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Gray/Black				None Detected
7-33 061602991-0033			Bsmt., Admin., 0008, Flue Sealant Homogeneous			
PLM NYS 198.1 Friable	4/2/2016	Gray/Rust	4.00% Wollastonite	96.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
7-34 061602991-0034			Bsmt., Admin., 0008, Flue Sealant Heterogeneous			
PLM NYS 198.1 Friable	4/2/2016	Gray/Rust	5.00% Glass 6.00% Wollastonite	89.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
8-35 061602991-0035			Bsmt., Admin., 0001, Stone Mortar Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Gray		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos			Asbestos
Sample ID		Description	Fibrous	Non-Fibrous		
8-36		Homogeneity	Bsmt., Admin., 0001, Stone Mortar			
061602991-0036			Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Gray		100.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	9-37	Description	Bsmt., Admin., 0007, Drywall			
061602991-0037		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White	8.00% Cellulose	92.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	9-38	Description	Bsmt., Admin., 0007, Drywall			
061602991-0038		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	White	6.00% Cellulose	94.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	10-39	Description	Bsmt., Admin., 0007, Joint Compound			
061602991-0039		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Tan		97.89% Non-fibrous (other)	2.11% Chrysotile	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	10-40	Description	Bsmt., Admin., 0007, Joint Compound			
061602991-0040		Homogeneity				
PLM NYS 198.1 Friable	4/3/2016				Positive Stop	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	11-41	Description	Bsmt., Admin., 0010, Red Fire-Stop			
061602991-0041		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable					Not Analyzed	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Red	1.3% Glass		Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/3/2016	Red			None Detected	

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	11-42	Description	Bsmt., Admin., 0010, Red Fire-Stop			
	061602991-0042	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Red	1.3% Glass			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Red				None Detected
Sample ID	12-43	Description	Bsmt., Admin., 0009, Ceramic Floor Grout			
	061602991-0043	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Gray	100.00% Non-fibrous (other)			None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	12-44	Description	Bsmt., Admin., 0009, Ceramic Floor Grout			
	061602991-0044	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Gray	100.00% Non-fibrous (other)			None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	13-45	Description	Bsmt., Admin., 0009, Concrete			
	061602991-0045	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Gray	100.00% Non-fibrous (other)			None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	13-46	Description	Bsmt., Admin., 0009, Concrete			
	061602991-0046	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/3/2016	Gray	100.00% Non-fibrous (other)			None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	14-47	Description	Bsmt., Admin., 0004, Black Wall Mastic			
	061602991-0047	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Black				None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test	Color	Non Asbestos		Asbestos
		Fibrous	Non-Fibrous	
Sample ID 14-48 061602991-0048	Description Homogeneity	Bsmt., Admin., 0004, Black Wall Mastic Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB 4/2/2016	Black			Inconclusive: None Detected
TEM NYS 198.4 NOB 4/3/2016	Black			None Detected
Sample ID 15-49 061602991-0049	Description Homogeneity	Bsmt., Admin., 0004, Material behind Heat Shield Homogeneous		
PLM NYS 198.1 Friable 4/3/2016	White		50.00% Non-fibrous (other)	50.00% Chrysotile
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 15-50 061602991-0050	Description Homogeneity	Bsmt., Admin., 0004, Material behind Heat Shield		
PLM NYS 198.1 Friable 4/3/2016				Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 15-51 061602991-0051	Description Homogeneity	Bsmt., Admin., 0004, Material behind Heat Shield		
PLM NYS 198.1 Friable 4/3/2016				Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 16-52 061602991-0052	Description Homogeneity	Bsmt., Admin., 0004, Pipe Insul. Debris Homogeneous		
PLM NYS 198.1 Friable 4/3/2016	Tan		80.90% Non-fibrous (other)	19.10% Chrysotile
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 16-53 061602991-0053	Description Homogeneity	Bsmt., Admin., 0004, Pipe Insul. Debris		
PLM NYS 198.1 Friable 4/3/2016				Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	16-54	Description	Bsmt., Admin., 0004, Pipe Insul. Debris		
	061602991-0054	Homogeneity			
PLM NYS 198.1 Friable	4/3/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	17-55	Description	Bsmt., Admin., 0004, Brick Mortar		
	061602991-0055	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	Gray		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	17-56	Description	Bsmt., Admin., 0004, Brick Mortar		
	061602991-0056	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/3/2016	Gray		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	18-57	Description	Bsmt., Admin., 0004, Fireplace Stone Mortar		
	061602991-0057	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	18-58	Description	Bsmt., Admin., 0004, Fireplace Stone Mortar		
	061602991-0058	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	19-59	Description	Bsmt., Admin., 0004, Fireplace Fire Brick Mortar		
	061602991-0059	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	19-60 061602991-0060	Description Homogeneity	Bsmt., Admin., 0004, Fireplace Fire Brick Mortar Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	20-61 061602991-0061	Description Homogeneity	Bsmt., Admin., 0004, Fireplace Fire Brick Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	20-62 061602991-0062	Description Homogeneity	Bsmt., Admin., 0004, Fireplace Fire Brick Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	21-63 061602991-0063	Description Homogeneity	1st Fl., Admin., 1005, Black Border Tile Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Black			None Detected
Sample ID	21-64 061602991-0064	Description Homogeneity	1st Fl., Admin., 1005, Black Border Tile Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Black			None Detected
Sample ID	22-65 061602991-0065	Description Homogeneity	1st Fl., Admin., 1005, Tan w./ Swirls F.T. Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Tan			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Tan			None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
22-66 061602991-0066	Description Homogeneity	1st Fl., Admin., 1005, Tan w./ Swirls F.T. Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Tan/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016 Tan/Black			None Detected
Sample ID 23-67 061602991-0067	Description Homogeneity	1st Fl., Admin., 1005, Black Mastic/Felt Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016 Black			None Detected
Sample ID 23-68 061602991-0068	Description Homogeneity	1st Fl., Admin., 1005, Black Mastic/Felt Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016 Black			None Detected
Sample ID 24-69 061602991-0069	Description Homogeneity	1st Fl., Admin., 1005C, Beige Flooring and Felt Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Tan			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016 Brown/Tan			None Detected
Sample ID 24-70 061602991-0070	Description Homogeneity	1st Fl., Admin., 1005C, Beige Flooring and Felt Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Tan			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016 Brown/Tan			None Detected
Sample ID 25-71 061602991-0071	Description Homogeneity	1st Fl., Admin., 1005C, Black Mastic/Felt Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016 Brown/Black			None Detected

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	25-72	Description		1st Fl., Admin., 1005C, Black Mastic/Felt		
	061602991-0072	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Black/ Green				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Brown/Black/ Green				None Detected
Sample ID	26-73	Description		1st Fl., Admin., 1005B, Small Black and Brown Flooring		
	061602991-0073	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Tan/G reen				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Brown/Tan/G reen				None Detected
Sample ID	26-74	Description		1st Fl., Admin., 1005B, Small Black and Brown Flooring		
	061602991-0074	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Tan/G reen				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/3/2016	Brown/Tan/G reen				None Detected
Sample ID	27-75	Description		1st Fl., Admin., 1005D, Black Flooring on Concrete		
	061602991-0075	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Black				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Brown/Black				None Detected
Sample ID	27-76	Description		1st Fl., Admin., 1005D, Black Flooring on Concrete		
	061602991-0076	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Black				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Brown/Black				None Detected
Sample ID	28-77	Description		1st Fl., Admin., 1005D, 12"x12" Beige F.T.		
	061602991-0077	Homogeneity		Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Tan				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/Tan				None Detected

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
		Color	Fibrous Non-Fibrous	
Sample ID	28-78 061602991-0078	Description Homogeneity	1st Fl., Admin., 1005D, 12"x12" Beige F.T. Homogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Tan		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/Tan		None Detected
Sample ID	29-79A 061602991-0079	Description Homogeneity	1st Fl., Admin., 1006C, Beige w./ Brown Streaks F.T. Homogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Tan/ White		Inconclusive : <1%Chrysotile Inconclusive - <1% Total
One of two sample bags marked 79. Labelled A for ID purposes.				
TEM NYS 198.4 NOB	4/4/2016	Brown/Tan/ White		<1% Chrysotile <1% Total
Sample ID	29-79B 061602991-0079A	Description Homogeneity	1st Fl., Admin., 1006C, Beige w./ Brown Streaks F.T. Homogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Gray/ Tan		Inconclusive : <1%Chrysotile Inconclusive - <1% Total
One of two sample bags marked 79. Labelled B for ID purposes.				
TEM NYS 198.4 NOB	4/4/2016	Brown/Gray/ Tan		<1% Chrysotile <1% Total
Sample ID	29-80A 061602991-0080	Description Homogeneity	1st Fl., Admin., 1006C, Beige w./ Brown Streaks F.T. Homogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Tan/ White		Inconclusive : <1%Chrysotile Inconclusive - <1% Total
One of two sample bags marked 80. Labelled A for ID purposes.				
TEM NYS 198.4 NOB	4/4/2016	Brown/Tan/ White		<1% Chrysotile <1% Total

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material**Non Asbestos**

Test	Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 29-80B 061602991-0080A	Description 1st Fl., Admin., 1006C, Beige w./ Brown Streaks F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Gray/ Tan			Inconclusive : <1%Chrysotile Inconclusive - <1% Total

One of two sample bags marked 80. Labelled B for ID purposes.

TEM NYS 198.4 NOB	4/4/2016 Brown/Gray/ Tan			<1% Chrysotile <1% Total
-------------------	-----------------------------	--	--	-----------------------------

Sample ID 30-81 061602991-0081	Description 1st Fl., Admin., 1006, 12"x12" Gray F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Gray			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Gray			None Detected

Sample ID 30-82 061602991-0082	Description 1st Fl., Admin., 1006, 12"x12" Gray F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Gray			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Gray			None Detected

Sample ID 31-83 061602991-0083	Description 1st Fl., Admin., 1006, 12"x12" White F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 White			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 White			None Detected

Sample ID 31-84 061602991-0084	Description 1st Fl., Admin., 1006, 12"x12" White F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 White			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 White			None Detected

Sample ID 32-85 061602991-0085	Description 1st Fl., Admin., 1006, 12"x12" White F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 White			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 White			None Detected

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 15

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
32-86 061602991-0086	Description Homogeneity	1st Fl., Admin., 1006, 12"x12" White F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 White			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 White			None Detected
33-87 061602991-0087	Description Homogeneity	1st Fl., Admin., 1004, 12"x12" Black F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Black			None Detected
33-88 061602991-0088	Description Homogeneity	1st Fl., Admin., 1004, 12"x12" Black F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Black			None Detected
34-89 061602991-0089	Description Homogeneity	1st Fl., Admin., 1004, 4" Vinyl Covebase and Mastic Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Black/Clear			Inconclusive: None Detected
Composite of cove base and inseparable clear adhesive.				
TEM NYS 198.4 NOB	4/4/2016 Black/Clear			None Detected
34-90 061602991-0090	Description Homogeneity	1st Fl., Admin., 1004, 4" Vinyl Covebase and Mastic Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Black/Clear			Inconclusive: None Detected
Composite of cove base and inseparable clear adhesive.				
TEM NYS 198.4 NOB	4/4/2016 Black/Clear			None Detected
35-91 061602991-0091	Description Homogeneity	1st Fl., Admin., 1004C, Textured Ceiling Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 16

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
35-92 061602991-0092	Description Homogeneity	1st Fl., Admin., 1004C, Textured Ceiling Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
35-93 061602991-0093	Description Homogeneity	1st Fl., Admin., 1004C, Textured Ceiling Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
35-94 061602991-0094	Description Homogeneity	1st Fl., Admin., 1004C, Textured Ceiling Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
35-95 061602991-0095	Description Homogeneity	1st Fl., Admin., 1004C, Textured Ceiling Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
36-96 061602991-0096	Description Homogeneity	1st Fl., Admin., 1006A, Ceramic Grout Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
36-97 061602991-0097	Description Homogeneity	1st Fl., Admin., 1006A, Ceramic Grout Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 17

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
37-98 061602991-0098	Description Homogeneity	2nd Fl., Admin., 2012F Closet, 12"x12" Beige F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Gray/ Tan			Inconclusive : <1%Chrysotile Inconclusive - <1% Total
TEM NYS 198.4 NOB	4/4/2016 Brown/Gray/ Tan			<1% Chrysotile <1% Total
37-99 061602991-0099	Description Homogeneity	2nd Fl., Admin., 2012F Closet, 12"x12" Beige F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Gray/ Tan			Inconclusive : <1%Chrysotile Inconclusive - <1% Total
TEM NYS 198.4 NOB	4/4/2016 Brown/Gray/ Tan			<1% Chrysotile <1% Total
38-100 061602991-0100	Description Homogeneity	2nd Fl., Admin., 2012F Closet, Brown Floor Mastic Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Brown/Black			None Detected
38-101 061602991-0101	Description Homogeneity	2nd Fl., Admin., 2012F Closet, Brown Floor Mastic Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Brown/Black			None Detected
39-102 061602991-0102	Description Homogeneity	2nd Fl., Admin., 2011A, 12"x12" Gray F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Gray			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Gray			None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report: Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
	Color	Fibrous	Non-Fibrous	
Sample ID 39-103 061602991-0103	Description 2nd Fl., Admin., 2011A, 12"x12" Gray F.T. Homogeneity Homogeneous			
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB 4/2/2016	Gray			Inconclusive: None Detected
Sample bag contains a small piece of black floor tile which wasn't analyzed.				
TEM NYS 198.4 NOB 4/4/2016	Gray			None Detected
Sample ID 40-104 061602991-0104	Description 1st Fl., Admin., 1001A, 9"x9" Ceramic Mortar Homogeneity Homogeneous			
PLM NYS 198.1 Friable 4/4/2016	Black		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 40-105 061602991-0105	Description 1st Fl., Admin., 1001A, 9"x9" Ceramic Mortar Homogeneity Homogeneous			
PLM NYS 198.1 Friable 4/4/2016	Black		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 41-106 061602991-0106	Description 3rd Fl., H.R., 3002, Wall Plaster, Top Coat Homogeneity Homogeneous			
PLM NYS 198.1 Friable 4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 41-107 061602991-0107	Description 3rd Fl., H.R., 3002, Wall Plaster, Top Coat Homogeneity Homogeneous			
PLM NYS 198.1 Friable 4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 41-108 061602991-0108	Description 3rd Fl., H.R., 3002, Wall Plaster, Top Coat Homogeneity Homogeneous			
PLM NYS 198.1 Friable 4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	41-109	Description	3rd Fl., H.R., 3002, Wall Plaster, Top Coat		
	061602991-0109	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	41-110	Description	3rd Fl., H.R., 3002, Wall Plaster, Top Coat		
	061602991-0110	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	41-111	Description	3rd Fl., H.R., 3002, Wall Plaster, Top Coat		
	061602991-0111	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	41-112	Description	3rd Fl., H.R., 3002, Wall Plaster, Top Coat		
	061602991-0112	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	42-113	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0113	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	42-114	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0114	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID	42-115	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0115	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.40% Non-fibrous (other)	0.60% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	42-116	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0116	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.33% Non-fibrous (other)	0.67% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	42-117	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0117	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.41% Non-fibrous (other)	0.59% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	42-118	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0118	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.72% Non-fibrous (other)	0.28% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	42-119	Description	3rd Fl., H.R., 3002, Wall Plaster, Base Coat		
	061602991-0119	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	43-120	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0120	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID	43-121	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0121	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	43-122	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0122	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	43-123	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0123	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	43-124	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0124	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	43-125	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0125	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	43-126	Description	3rd Fl., H.R., 3002, Ceiling Plaster, Top Coat		
	061602991-0126	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

		Non Asbestos			Asbestos
Test		Color	Fibrous	Non-Fibrous	
Sample ID 44-127 061602991-0127		Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 44-128 061602991-0128		Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 44-129 061602991-0129		Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.73% Non-fibrous (other)	0.27% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 44-130 061602991-0130		Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 44-131 061602991-0131		Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.40% Non-fibrous (other)	0.60% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 44-132 061602991-0132		Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Brown		99.36% Non-fibrous (other)	0.64% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

		Non Asbestos		Asbestos
Test	Color	Fibrous	Non-Fibrous	
Sample ID 44-133 061602991-0133	Description Homogeneity	3rd Fl., H.R., 3002, Ceiling Plaster, Base Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016 Brown	99.72% Non-fibrous (other)		0.28% Chrysotile
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 45-134 061602991-0134	Description Homogeneity	3rd Fl., H.R., 3003, Multi-Colored Linoleum Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Gray			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Brown/Gray			None Detected
Sample ID 45-135 061602991-0135	Description Homogeneity	3rd Fl., H.R., 3003, Multi-Colored Linoleum Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Brown/Gray			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Brown/Gray			None Detected
Sample ID 46-136 061602991-0136	Description Homogeneity	3rd Fl., H.R., 3003, 2nd Layer Flooring Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Tan/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Tan/Black			None Detected
Sample ID 46-137 061602991-0137	Description Homogeneity	3rd Fl., H.R., 3003, 2nd Layer Flooring Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Tan/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Tan/Black			None Detected
Sample ID 47-138 061602991-0138	Description Homogeneity	2nd Fl., H.R., 2005, 12"x12" Gray F.T. Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016 Gray			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016 Gray			None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	47-139 061602991-0139	Description Homogeneity	2nd Fl., H.R., 2005, 12"x12" Gray F.T. Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray	Inconclusive: None Detected		
TEM NYS 198.4 NOB	4/4/2016	Gray	None Detected		
Sample ID	48-140 061602991-0140	Description Homogeneity	2nd Fl., H.R., 2005, 12"x12" White F.T. Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Tan/White	Inconclusive: None Detected		
TEM NYS 198.4 NOB	4/4/2016	Tan/White	None Detected		
Sample ID	48-141 061602991-0141	Description Homogeneity	2nd Fl., H.R., 2005, 12"x12" White F.T. Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Tan/White	Inconclusive: None Detected		
TEM NYS 198.4 NOB	4/4/2016	Tan/White	None Detected		
Sample ID	49-142 061602991-0142	Description Homogeneity	2nd Fl., H.R., 2005, Black Mastic Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black	Inconclusive: None Detected		
TEM NYS 198.4 NOB	4/4/2016	Black	None Detected		
Sample ID	49-143 061602991-0143	Description Homogeneity	2nd Fl., H.R., 2005, Black Mastic Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black	Inconclusive: None Detected		
TEM NYS 198.4 NOB	4/4/2016	Black	None Detected		
Sample ID	50-144 061602991-0144	Description Homogeneity	2nd Fl., H.R., 2005, Sink Coating Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Tan	Inconclusive: None Detected		
TEM NYS 198.4 NOB	4/4/2016	Tan	None Detected		

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	50-145	Description	2nd Fl., H.R., 2005, Sink Coating			
	061602991-0145	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Tan				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Tan				None Detected
Sample ID	51-146	Description	1st Fl., H.R., 1001, Fireplace Stone Mortar			
	061602991-0146	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	51-147	Description	1st Fl., H.R., 1001, Fireplace Stone Mortar			
	061602991-0147	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	52-148	Description	Bsmt., H.R. CMU Mortar			
	061602991-0148	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray/Tan		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	52-149	Description	Bsmt., H.R. CMU Mortar			
	061602991-0149	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	53-150	Description	Bsmt., H.R. Drywall			
	061602991-0150	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White	6.00% Cellulose	94.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

		Non Asbestos			
Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 53-151 061602991-0151		Description Homogeneity	Bsmt., H.R. Drywall Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	5.00% Cellulose	95.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 54-152 061602991-0152		Description Homogeneity	Bsmt., H.R. Joint Compound Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 54-153 061602991-0153		Description Homogeneity	Bsmt., H.R. Joint Compound Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 55-154 061602991-0154		Description Homogeneity	Bsmt., H.R. Pipe Insulation Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		77.80% Non-fibrous (other)	22.20% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 55-155 061602991-0155		Description Homogeneity	Bsmt., H.R. Pipe Insulation		
PLM NYS 198.1 Friable	4/4/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 55-156 061602991-0156		Description Homogeneity	Bsmt., H.R. Pipe Insulation		
PLM NYS 198.1 Friable	4/4/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Non Asbestos					
Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	56-157 061602991-0157	Description Homogeneity	Bsmt., H.R. Debris on Metal Support Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	71.40% Non-fibrous (other)		28.60% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	57-158 061602991-0158	Description Homogeneity	Bsmt., H.R. Debris on Galv. Elbow Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Gray	30.00% Wollastonite	70.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	58-159 061602991-0159	Description Homogeneity	1st Fl., Business Annex, Skim Coat on Concrete Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	58-160 061602991-0160	Description Homogeneity	1st Fl., Business Annex, Skim Coat on Concrete Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	58-161 061602991-0161	Description Homogeneity	1st Fl., Business Annex, Skim Coat on Concrete Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	58-162 061602991-0162	Description Homogeneity	1st Fl., Business Annex, Skim Coat on Concrete Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	58-163	Description	1st Fl., Business Annex, Skim Coat on Concrete		
	061602991-0163	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	59-164	Description	1st Fl., Business Annex, Concrete		
	061602991-0164	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	59-165	Description	1st Fl., Business Annex, Concrete		
	061602991-0165	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	60-166	Description	1st Fl., Business Annex, Black Mastic under Carpet		
	061602991-0166	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Brown/Black			None Detected
Sample ID	60-167	Description	1st Fl., Business Annex, Black Mastic under Carpet		
	061602991-0167	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Brown/Black			None Detected
Sample ID	61-168	Description	Bsmt., Business Annex, Drywall		
	061602991-0168	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White	4.00% Cellulose	96.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	61-169	Description	Bsmt., Business Annex, Drywall			
	061602991-0169	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White	5.00% Cellulose	95.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	62-170	Description	Bsmt., Business Annex, Joint Compound			
	061602991-0170	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	62-171	Description	Bsmt., Business Annex, Joint Compound			
	061602991-0171	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	63-172	Description	Bsmt., Business Annex, Brick Mortar			
	061602991-0172	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	63-173	Description	Bsmt., Business Annex, Brick Mortar			
	061602991-0173	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	64-174	Description	1st Fl., Gate House, 12"x12" Ceiling Tile			
	061602991-0174	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Beige				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Beige				None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	64-175	Description	1st Fl., Gate House, 12"x12" Ceiling Tile			
	061602991-0175	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Beige				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Beige				None Detected
Sample ID	65-176	Description	1st Fl., Gate House, Glue Dabs			
	061602991-0176	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Brown				<1% Chrysotile <1% Total
Sample ID	65-177	Description	1st Fl., Gate House, Glue Dabs			
	061602991-0177	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Brown				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Brown				None Detected
Sample ID	66-178	Description	1st Fl., Gate House, Drywall			
	061602991-0178	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White	5.00% Cellulose	95.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	66-179	Description	1st Fl., Gate House, Drywall			
	061602991-0179	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White	6.00% Cellulose	94.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	67-180	Description	1st Fl., Gate House, Wall Plaster, Top Coat			
	061602991-0180	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White		22.00% Ca Carbonate 78.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	67-181 061602991-0181	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		30.00% Ca Carbonate 70.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	67-182 061602991-0182	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		28.00% Ca Carbonate 72.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	67-183 061602991-0183	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		25.00% Ca Carbonate 75.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	67-184 061602991-0184	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		29.00% Ca Carbonate 71.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	67-185 061602991-0185	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		27.00% Ca Carbonate 73.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	67-186 061602991-0186	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Top Coat Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/04/2016 11:50:43

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos			Asbestos
			Fibrous	Non-Fibrous		
Sample ID	68-187 061602991-0187	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Base Coat Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	2.00% Hair	30.00% Quartz 7.00% Mica 6.00% Ca Carbonate 55.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	68-188 061602991-0188	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Base Coat Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	2.00% Hair 5.00% Cellulose	33.00% Quartz 9.00% Mica 5.00% Ca Carbonate 46.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	68-189 061602991-0189	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Base Coat Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	3.00% Hair	32.00% Quartz 9.00% Mica 7.00% Ca Carbonate 49.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	68-190 061602991-0190	Description Homogeneity	1st Fl., Gate House, Wall Plaster, Base Coat Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	4.00% Hair	27.00% Quartz 10.00% Mica 9.00% Ca Carbonate 50.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	68-191	Description	1st Fl., Gate House, Wall Plaster, Base Coat			
	061602991-0191	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	3.00% Hair	25.00% Quartz		None Detected
				10.00% Mica		
				10.00% Ca Carbonate		
				52.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	68-192	Description	1st Fl., Gate House, Wall Plaster, Base Coat			
	061602991-0192	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	3.00% Hair	25.00% Quartz		None Detected
				10.00% Mica		
				9.00% Ca Carbonate		
				53.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	68-193	Description	1st Fl., Gate House, Wall Plaster, Base Coat			
	061602991-0193	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	2.00% Hair	30.00% Quartz		None Detected
				8.00% Mica		
				5.00% Ca Carbonate		
				55.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	69-194	Description	1st Fl., Gate House, Fireplace, Brick Mortar			
	061602991-0194	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray		20.00% Quartz		None Detected
				40.00% Ca Carbonate		
				40.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
		Color	Fibrous	
			Non-Fibrous	
Sample ID	69-195	Description	1st Fl., Gate House, Fireplace, Brick Mortar	
	061602991-0195	Homogeneity	Homogeneous	
PLM NYS 198.1 Friable	4/4/2016	Gray	16.00% Quartz 44.00% Ca Carbonate 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	70-196	Description	1st Fl., Gate House, West Room, Linoleum and Mastic	
	061602991-0196	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Tan/Black		11.4% Chrysotile 11.4% Total
Composite of linoleum and inseparable mastic / tar paper.				
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	70-197	Description	1st Fl., Gate House, West Room, Linoleum and Mastic	
	061602991-0197	Homogeneity		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016			Positive Stop (Not Analyzed)
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	71-198	Description	1st Fl., Gate House, West Room, Back Splash	
	061602991-0198	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Black/Gold		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White/Black/Gold		None Detected
Sample ID	71-199	Description	1st Fl., Gate House, West Room, Back Splash	
	061602991-0199	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Black/Gold		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White/Black/Gold		None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	72-200	Description	Bsmt., Gate House, Debris on Ground			
	061602991-0200	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Brown/Tan	1.00% Cellulose	5.00% Ca Carbonate		None Detected
				94.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	72-201	Description	Bsmt., Gate House, Debris on Ground			
	061602991-0201	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Brown/Tan	3.00% Cellulose	97.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	73-202	Description	Bsmt., Gate House, Pipe Insulation			
	061602991-0202	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray		20.00% Non-fibrous (other)		80.00% Chrysotile
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	73-203	Description	Bsmt., Gate House, Pipe Insulation			
	061602991-0203	Homogeneity				
PLM NYS 198.1 Friable	4/4/2016					Positive Stop
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	73-204	Description	Bsmt., Gate House, Pipe Insulation			
	061602991-0204	Homogeneity				
PLM NYS 198.1 Friable	4/4/2016					Positive Stop
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	74-205	Description	Bsmt., Gate House, Mudded Fitting			
	061602991-0205	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray		25.00% Ca Carbonate		40.00% Chrysotile
				35.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	74-206 061602991-0206	Description Homogeneity	Bsmt., Gate House, Mudded Fitting		
PLM NYS 198.1 Friable		4/4/2016	Positive Stop		
PLM NYS 198.6 VCM		Not Analyzed			
PLM NYS 198.6 NOB		Not Analyzed			
TEM NYS 198.4 NOB		Not Analyzed			
Sample ID	74-207 061602991-0207	Description Homogeneity	Bsmt., Gate House, Mudded Fitting		
PLM NYS 198.1 Friable		4/4/2016	Positive Stop		
PLM NYS 198.6 VCM		Not Analyzed			
PLM NYS 198.6 NOB		Not Analyzed			
TEM NYS 198.4 NOB		Not Analyzed			
Sample ID	75-208 061602991-0208	Description Homogeneity	Bsmt., Gate House, Concrete Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan	3.00% Cellulose	40.00% Quartz 22.00% Ca Carbonate 35.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM		Not Analyzed			
PLM NYS 198.6 NOB		Not Analyzed			
TEM NYS 198.4 NOB		Not Analyzed			
Sample ID	75-209 061602991-0209	Description Homogeneity	Bsmt., Gate House, Concrete Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Tan	3.00% Cellulose	40.00% Quartz 16.00% Ca Carbonate 41.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM		Not Analyzed			
PLM NYS 198.6 NOB		Not Analyzed			
TEM NYS 198.4 NOB		Not Analyzed			
Sample ID	76-210 061602991-0210	Description Homogeneity	Bsmt., Gate House, Flue Sealant Heterogeneous		
PLM NYS 198.1 Friable		Not Analyzed			
PLM NYS 198.6 VCM		Not Analyzed			
PLM NYS 198.6 NOB	4/2/2016	Gray/White	Inconclusive: None Detected		
TEM NYS 198.4 NOB		Not Analyzed			

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non-Asbestos	Non-Fibrous	Asbestos
Sample ID	76-211 061602991-0211	Description Homogeneity	Bsmt., Gate House, Flue Sealant Heterogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/White	1.4% Chrysotile 1.4% Total			
Mixture of paint and insulation material.						
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	77-212 061602991-0212	Description Homogeneity	2nd Fl., Gate House, Bathroom, 9"x9" F.T. and Mastic Heterogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Black	1.2% Chrysotile 1.2% Total			
Composite of floor tile and inseparable mastic.						
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	77-213 061602991-0213	Description Homogeneity	2nd Fl., Gate House, Bathroom, 9"x9" F.T. and Mastic			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Positive Stop (Not Analyzed)				
Composite of floor tile and inseparable mastic.						
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	78-214-Joint Compound 061602991-0214	Description Homogeneity	2nd Fl., Gate House, Joint Compound Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White	5.00% Mica 70.00% Ca Carbonate 25.00% Non-fibrous (other)		None Detected	
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	78-214-Tape 061602991-0214A	Description Homogeneity	2nd Fl., Gate House, Joint Compound Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	98.00% Cellulose	2.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	78-215-Joint Compound 061602991-0215	Description	2nd Fl., Gate House, Joint Compound			
		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White			5.00% Mica 45.00% Ca Carbonate 50.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	78-215-Tape 061602991-0215A	Description	2nd Fl., Gate House, Joint Compound			
		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	99.00% Cellulose		1.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	79-216 061602991-0216	Description	1st Fl., Facilities, 1009, Beige w./ Streaks F.T.			
		Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Black				1.4% Chrysotile 1.4% Total
Composite of floor tile and inseparable mastic.						
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	79-217 061602991-0217	Description	1st Fl., Facilities, 1009, Beige w./ Streaks F.T.			
		Homogeneity				
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016					Positive Stop (Not Analyzed)
Composite of floor tile and inseparable mastic.						
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	80-218 061602991-0218	Description	Attic, Admin, Blown-In Insulation			
		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray/Tan/Wh	45.00% Cellulose		55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos			Asbestos
Sample ID	80-219 061602991-0219	Description Homogeneity	Attic, Admin, Blown-In Insulation Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray/Tan/Wh	44.00% Cellulose <1% Glass	6.00% Ca Carbonate 50.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	80-220 061602991-0220	Description Homogeneity	Attic, Admin, Blown-In Insulation Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray/Tan/Wh	40.00% Cellulose	8.00% Ca Carbonate 52.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	81-221 061602991-0221	Description Homogeneity	Attic, Admin, Canvas over Horsehair Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	94.00% Cellulose <1% Hair	6.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	81-222 061602991-0222	Description Homogeneity	Attic, Admin, Canvas over Horsehair Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	96.00% Cellulose <1% Hair	4.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	81-223 061602991-0223	Description Homogeneity	Attic, Admin, Canvas over Horsehair Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Tan	96.00% Cellulose <1% Hair	4.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	82-224 061602991-0224	Description Homogeneity	1st Fl., Facilities, 1009, Felt/Mastic under F.T. Homogeneous			
PLM NYS 198.1 Friable					Not Analyzed	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Black	Inconclusive: None Detected			
TEM NYS 198.4 NOB	4/4/2016	Black	None Detected			

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 40

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos	
	Color	Fibrous	Non-Fibrous		
Sample ID 82-225 061602991-0225	Description Homogeneity	1st Fl., Facilities, 1009, Felt/Mastic under F.T. Homogeneous			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Black			None Detected
Sample ID 83-226 061602991-0226	Description Homogeneity	1st Fl., Facilities, 1005, Cement Board Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray	35.00% Ca Carbonate 28.60% Non-fibrous (other)		36.40% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 83-227 061602991-0227	Description Homogeneity	1st Fl., Facilities, 1005, Cement Board			
PLM NYS 198.1 Friable	4/4/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 84-228 061602991-0228	Description Homogeneity	1st Fl., Facilities, 1005, Flue Sealant Heterogeneous			
PLM NYS 198.1 Friable	4/2/2016	Brown/Gray/	53.00% Cellulose 8.00% Ca Carbonate 37.25% Non-fibrous (other)		1.75% Chrysotile
Composite of paper and textured paint.					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 84-229 061602991-0229	Description Homogeneity	1st Fl., Facilities, 1005, Flue Sealant			
PLM NYS 198.1 Friable	4/2/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 85-230 061602991-0230	Description Homogeneity	3rd Fl., Admin., 3009B, Ceramic Grout Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	White	12.00% Ca Carbonate 88.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 41

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	85-231	Description	3rd Fl., Admin., 3009B, Ceramic Grout		
	061602991-0231	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		15.00% Ca Carbonate 85.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	86-232	Description	1st Fl., Facilities, 12"x12" Spline Ceiling Tile		
	061602991-0232	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Beige			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White/Beige			None Detected
Sample ID	86-233	Description	1st Fl., Facilities, 12"x12" Spline Ceiling Tile		
	061602991-0233	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Beige			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White/Beige			None Detected
Sample ID	87-234	Description	1st Fl., Facilities, Joint Compound		
	061602991-0234	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		6.00% Mica 70.00% Ca Carbonate 24.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	87-235	Description	1st Fl., Facilities, Joint Compound		
	061602991-0235	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		7.00% Mica 68.00% Ca Carbonate 25.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	88-236	Description	1st Fl., Facilities, Drywall		
	061602991-0236	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Gray/Tan	17.00% Cellulose	83.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/04/2016 11:50:43

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			
		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	88-237	Description	1st Fl., Facilities, Drywall		
	061602991-0237	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Gray/Tan	20.00% Cellulose	80.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	89-238	Description	1st Fl., Facilities, Toilet, Ceramic Grout		
	061602991-0238	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		60.00% Ca Carbonate 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	89-239	Description	1st Fl., Facilities, Toilet, Ceramic Grout		
	061602991-0239	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	White		65.00% Ca Carbonate 35.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	90-240	Description	1st Fl., Facilities, Toilet, 4" Covebase and Mastic		
	061602991-0240	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Yellow			Inconclusive: None Detected
Composite of cove base and inseparable mastic.					
TEM NYS 198.4 NOB	4/4/2016	Gray/Yellow			None Detected
Sample ID	90-241	Description	1st Fl., Facilities, Toilet, 4" Covebase and Mastic		
	061602991-0241	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Yellow			Inconclusive: None Detected
Composite of cove base and inseparable mastic.					
TEM NYS 198.4 NOB	4/4/2016	Gray/Yellow			None Detected
Sample ID	91-242	Description	1st Fl., Facilities, Wood Flooring Laminate		
	061602991-0242	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Black			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/Black			None Detected

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Non Asbestos			Asbestos
Sample ID		Description	Fibrous	Non-Fibrous		
91-243						
061602991-0243		Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable					Not Analyzed	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Gray/Black	Inconclusive: None Detected			
TEM NYS 198.4 NOB	4/4/2016	Gray/Black	None Detected			
Sample ID	92-244	Description	1st Fl., Facilities, 1006, Fiberboard Walls			
061602991-0244		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Brown	90.00% Cellulose	10.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	92-245	Description	1st Fl., Facilities, 1006, Fiberboard Walls			
061602991-0245		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Brown	92.00% Cellulose	8.00% Non-fibrous (other)	None Detected	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	93-246	Description	1st Fl., Facilities, Ext., Cementitious Siding			
061602991-0246		Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/4/2016	Gray/White	37.00% Ca Carbonate		33.30% Chrysotile	
			29.70% Non-fibrous (other)			
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	93-247	Description	1st Fl., Facilities, Ext., Cementitious Siding			
061602991-0247		Homogeneity				
PLM NYS 198.1 Friable	4/4/2016		Positive Stop			
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB					Not Analyzed	
TEM NYS 198.4 NOB					Not Analyzed	
Sample ID	94-248	Description	1st Fl., Facilities, Ext., Window Caulk			
061602991-0248		Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable					Not Analyzed	
PLM NYS 198.6 VCM					Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Gray/White	Inconclusive: None Detected			
TEM NYS 198.4 NOB	4/4/2016	Gray/White	None Detected			

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
	Color	Fibrous	Non-Fibrous	
Sample ID 94-249 061602991-0249	Description Homogeneity	1st Fl., Facilities, Ext., Window Caulk Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/White		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/White		None Detected
Sample ID 95-250 061602991-0250	Description Homogeneity	Crawlspace, Facilities, Pipe Insul. Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Gray	50.00% Non-fibrous (other)	50.00% Chrysotile
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 95-251 061602991-0251	Description Homogeneity	Crawlspace, Facilities, Pipe Insul.		
PLM NYS 198.1 Friable	4/4/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 95-252 061602991-0252	Description Homogeneity	Crawlspace, Facilities, Pipe Insul.		
PLM NYS 198.1 Friable	4/4/2016			Positive Stop
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 96-253 061602991-0253	Description Homogeneity	Crawlspace, Facilities, Debris Homogeneous		
PLM NYS 198.1 Friable	4/4/2016	Gray	42.90% Non-fibrous (other)	57.10% Chrysotile
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID 97-254 061602991-0254	Description Homogeneity	Roof, Facilities, Shingles Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black	7.6% Glass	Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Black		None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos	
		Color	Fibrous	Non-Fibrous	
Sample ID	97-255	Description	Roof, Facilities, Shingles		
	061602991-0255	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB 4/2/2016					Not Submitted
Empty sample bag.					
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	98-256	Description	Roof, Facilities, Felt		
	061602991-0256	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB 4/2/2016 Black 1.2% Glass					Inconclusive: None Detected
TEM NYS 198.4 NOB 4/4/2016 Black					None Detected
Sample ID	98-257	Description	Roof, Facilities, Felt		
	061602991-0257	Homogeneity			
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB 4/2/2016					Not Submitted
Empty sample bag.					
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	99-258	Description	Roof, Annex, Roof Shingle		
	061602991-0258	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB 4/2/2016 Brown/Gray/Black 6.0% Glass					Inconclusive: None Detected
TEM NYS 198.4 NOB 4/4/2016 Brown/Gray/Black					None Detected
Sample ID	99-259	Description	Roof, Annex, Roof Shingle		
	061602991-0259	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB 4/2/2016 Brown/Gray/Black 1.8% Glass					Inconclusive: None Detected
TEM NYS 198.4 NOB 4/4/2016 Brown/Gray/Black					None Detected
Sample ID	100-260	Description	Roof, Annex, Felt		
	061602991-0260	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB 4/2/2016 Black 1.9% Glass					Inconclusive: None Detected
TEM NYS 198.4 NOB 4/4/2016 Black					None Detected

Initial Report From 04/04/2016 11:50:43

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos	
		Color	Fibrous	Non-Fibrous	
Sample ID	100-261	Description	Roof, Annex, Felt		
	061602991-0261	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed	
PLM NYS 198.6 VCM				Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Black	1.8% Glass	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/4/2016	Black		None Detected	
Sample ID	101-262	Description	1st Fl., Annex, Window Caulk		
	061602991-0262	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed	
PLM NYS 198.6 VCM				Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	White		Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/4/2016	White		None Detected	
Sample ID	101-263	Description	1st Fl., Annex, Window Caulk		
	061602991-0263	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed	
PLM NYS 198.6 VCM				Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	White		Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/4/2016	White		None Detected	
Sample ID	102-264	Description	Roof, Annex, Roof Shingle		
	061602991-0264	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed	
PLM NYS 198.6 VCM				Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Brown/Red/B lack	8.9% Glass	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/4/2016	Brown/Red/B lack		None Detected	
Sample ID	102-265	Description	Roof, Annex, Roof Shingle		
	061602991-0265	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable				Not Analyzed	
PLM NYS 198.6 VCM				Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Brown/Red/B lack	7.0% Glass	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/4/2016	Brown/Red/B lack		None Detected	
Sample ID	103-266	Description	Roof, Annex, Felt		
	061602991-0266	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable				Not Analyzed	
PLM NYS 198.6 VCM				Not Analyzed	
PLM NYS 198.6 NOB	4/2/2016	Black	3.1% Glass	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/4/2016	Black		None Detected	

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 47

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	103-267	Description		Roof, Annex, Felt		
	061602991-0267	Homogeneity		Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black		3.6% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Black				None Detected
Sample ID	104-268	Description		1st Fl., Annex, Window Caulk		
	061602991-0268	Homogeneity		Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White				None Detected
Sample ID	104-269	Description		1st Fl., Annex, Window Caulk		
	061602991-0269	Homogeneity		Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White				Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White				None Detected
Sample ID	105-270	Description		1st Fl., Gate House, Roof Shingle		
	061602991-0270	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Red/Black		5.3% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/Red/Black				None Detected
Sample ID	105-271	Description		1st Fl., Gate House, Roof Shingle		
	061602991-0271	Homogeneity		Heterogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/Red/Black		4.1% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/Red/Black				None Detected
Sample ID	106-272	Description		1st Fl., Gate House, Felt		
	061602991-0272	Homogeneity		Homogeneous		
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black		3.2% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Black				None Detected

Initial Report From 04/04/2016 11:50:43

Test Report 198VCM-7.30.0 Printed: 4/4/2016 11:50:43 AM

Page 48

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos	
		Color	Fibrous	Non-Fibrous	
Sample ID	106-273	Description	1st Fl., Gate House, Felt		
	061602991-0273	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Black	3.2% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Black			None Detected
Sample ID	107-274	Description	1st Fl., Gate House, Window Caulk		
	061602991-0274	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/White			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/White			None Detected
Sample ID	107-275	Description	1st Fl., Gate House, Window Caulk		
	061602991-0275	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	Gray/White			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	Gray/White			None Detected
Sample ID	108-276	Description	1st Fl., H.R., Window Caulk		
	061602991-0276	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Blue			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White/Blue			None Detected
Sample ID	108-277	Description	1st Fl., H.R., Window Caulk		
	061602991-0277	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/2/2016	White/Blue			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/4/2016	White/Blue			None Detected



EMSL Analytical, Inc.

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>

carleplacelab@emsl.com


EMSL Order: 061602991

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report: Asbestos Analysis of Bulk Material

		Non Asbestos		
Test	Color	Fibrous	Non-Fibrous	Asbestos
Analyst(s)				
Ashley Hastings	Ellen Russell			 Michelle McGowan, Laboratory Manager or other approved signatory
Andrei Zanko	Matthew Greco			
Daniel Clarke	Steve Juscuk			

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non-asbestos containing.

All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. Carle Place, NY NYS ELAP 11469

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable Non-Friable	Condition g, d, sd
1	1	B	Admin - Top Paper Behind Wood	100 SF	NF	D
2	1	B		↓	↓	D
3	2	B	- Wall Plaster - Top Coat	20,000 SF	F	SD
4	2	B				
5	2	B				
6	2	B				
7	2	B				
8	2	B				
9	2	B				
10	3	B	Base Coat			
11	3	B				
12	3	↓				
13	3	↓				

RECEIVED
 EHS/ANALYTICAL
 3/28/16 11:51

Special Instructions/ Turnaround Time: **Stop at 1st Positive per Homogenous Area** **5 day TAT**
 E-Mail Results to AdelaideLabResults@adelaidellc.com

Relinquished by: _____
 Received by: *Jason Fullum*
 Relinquished by: _____
 Received by: _____

4/1/16

AC *Pham* 4/1/16

4/1/16

4/1/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

2

Order ID: 061602991

Site Address: SUNY Purchase	Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum
735 Anderson Hill Road		
Purchase, NY 10577	Project #: PGS:15100.02-IN	

Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition B, d, sd
14	3	B	Admin. - Wall Plaster - Base Coat	20,000 SF	F	SD
15	3	B	↓	↓	↓	↓
16	3	B	↓	↓	↓	↓
17	4	B	- Ceiling Plaster - Top Coat	10,000 SF	F	SD
18	4		↓	↓	↓	↓
19	4		↓	↓	↓	↓
20	4		↓	↓	↓	↓
21	4		↓	↓	↓	↓
22	4		↓	↓	↓	↓
23	4		↓	↓	↓	↓
24	5		↓	↓	↓	↓
25	5		- Base Coat	↓	↓	↓
26	5	↓	↓	↓	↓	↓

Special Instructions/ Turnaround Time:

Stop at 1st Positive per Homogenous Area
E-Mail Results to AdelaideLabResults@adelaidellc.com
5 day TAT

Relinquished by:	<i>[Signature]</i> 3/28/16
Received by:	
Relinquished by:	
Received by:	

dt 4/13/16
AC
4/14/16

Matthew 4/12/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24

Brewster, NY 10509

845-278-7710

845-278-7750 - fax

061602991

3

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
27	5	B	Admin. - Ceiling Plaster - Base Coat	10,000 SF	F	SD
28	5		↓	↓	↓	↓
29	5		↓	↓	↓	↓
30	5		↓	↓	↓	↓
31	6	B	- 0012 - Skiv Counting	36 SF	NF	D
32	6	B	↓	↓	↓	↓
33	7	B	- 0008 - Flue Socklet	4 SF	NF	SD
34	7	B	↓	↓	↓	↓
35	8	B	- 0001 - Stone Mortar	10,000 SF	NF	G
36	8	D	↓	↓	↓	G
37	9	B	- 0007 - Drywall	250 SF	F	D
38	9	B	↓	↓	↓	↓
39	10	B	↓ - Joint Compound	↓	↓	↓
Special Instructions/ Turnaround Time:			Relinquished by:			
Stop at 1st Positive per Homogenous Area			Received by:			
5 day TAT			Relinquished by:			
E-Mail Results to AdelaideLabResults@adelaidelc.com			Received by:			

4/4/16

AZ *[Signature]* 4/4/16

[Signature] 4/4/16

1/4/16 v100

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24

Brewster, NY 10509

845-278-7710

845-278-7750 - fax

061602991

OrderID: 061602991

Site Address: SUNY Purchase		Date: 3/23 - 3/25/16		Inspector(s) Jason Fullum	
735 Anderson Hill Road					
Purchase, NY 10577		Project #: PGS:15100.02-IN			


Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable (Not Friable)	RECEIVED ANALYSIS DATE PLACE
40	10	B	Admin - 0007 - Joint Compound	250 SF	F	D
41	11	B	↓ - 0010 - Red Fire Stop	10 SF	NF	G
42	11	B	↓	↓	↓	G
43	12	B	↓ - 0009 - Ceramic Floor Grout	100 SF	NF	D
44	12	B	↓	↓	↓	D
45	13	B	↓ - Concrete	5,000 SF	↓	D
46	13	B	↓	↓	↓	D
47	14	B	0004 - Black Wall Mesh	5,000 SF	NF	D
48	14	B	↓	↓	↓	D
49	15	B	↓ - Material Behind Heat Shield	60 SF	F	D
50	15	B	↓	↓	↓	D
51	15	B	↓	↓	↓	D


Special Instructions/ Turnaround Time:


Stop at 1st Positive per Homogenous Area


E-Mail Results to AdelaideLabResults@adelaideinc.com

5 day TAT

Relinquished by: 

Received by: 

Relinquished by: 

Received by: 

3/28/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24

Brewster, NY 10509

845-278-7710

845-278-7750 - fax

061602991

S

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	8.5 Enflable NonFriable	ANALYTICAL
52	16	B	Admin. - 0004 - Pipe Ins Debris	2 SF	MF	D
53	16	B	↓	↓	MF	↓
54	16	B	↓	↓	MF	↓
55	17	B	↓ - Brick Mark	50 SF	MF	D
56	17	B	↓	↓	MF	↓
57	18	B	↓ - fireplace Stone Mark	50 SF	MF	6
58	18	B	↓	↓	MF	6
59	19	B	↓ - Fire place Firebrick Mark	25 SF	MF	D
60	19	B	↓	↓	MF	↓
61	20	B	↓ - Fire place Firebrick	↓	MF	↓
62	20	B	↓	↓	MF	↓
63	21	1	↓ - 1005 - Black Border Tile	20 SF	MF	D
64	21	1	↓	↓	MF	↓
Special Instructions/ Turnaround Time:			Relinquished by:			
Stop at 1st Positive per Homogenous Area			Received by:			
E-Mail Results to AdelaideLabResults@adelaidehc.com			Relinquished by:			
5 day TAT			Received by:			

AT 4/16

AC [Signature] 4/16

Matthew 4/16

4/16/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

6

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23-3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Frangible Non-Frangible	Frangible Non-Frangible
65	22	1	Admin - 1005 - Tan w/ Swirls F.T.	200 SF	NF	G
66	22	1	↓	↓	↓	↓
67	23	1	↓ - Black Marble/Felt	↓	↓	↓
68	23	1	↓	↓	↓	↓
69	24	1	↓ - 1005C - Beige Florig + Felt	120 SF	↓	D
70	24	1	↓	↓	↓	↓
71	25	1	↓ - Black Marble/Felt	↓	NF	↓
72	25	1	↓	↓	↓	↓
73	26	1	1005B - Small Black Florig + Felt	120 SF	NF	G
74	26	1	↓	↓	↓	↓
75	27	1	Small Beige Floor Tile	↓	↓	↓
76	27	1	↓	↓	↓	↓
Special Instructions/ Turnaround Time:			Relinquished by: <i>[Signature]</i>			
Stop at 1st Positive per Homogenous Area			Received by: <i>[Signature]</i> 3/28/16			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by:			
			Received by:			

4/1/16

[Signature] 4/1/16

[Signature] 4/1/16

4/2/16 4:15 PM

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

7

Order ID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Frangible Non-Frangible	ps - per Condition
75	27	1	Admin. - 1005 D - Black Flooring & Concrete	200 SF	MF	D
76	27	1	↓	↓	↓	↓
77	28	1	↓ - 12x12 Beige F.T.	30 SF	MF	D
78	28	1	↓	↓	↓	↓
79	29	1	↓ - 1006 C - Beige w/ Brown Streaks F.T.	20 SF	NF	D
80	29	1	↓	↓	↓	↓
81	30	1	↓ - 1006 - 12x12 Gray F.T.	60 SF	NF	G
82	30	1	↓	↓	↓	↓
83	31	1	↓ - 12x12 White F.T.	60 SF	↓	↓
84	31	1	↓	↓	↓	↓
85	32	1	↓ - 1004 - 12x12 White F.T.	25 SF	NF	↓
86	32	1	↓	↓	↓	↓
Special Instructions/ Turnaround Time:			Relinquished by: <i>[Signature]</i>			
Stop at 1st Positive per Homogenous Area			Received by: <i>[Signature]</i> 3/28/16			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by:			
5 day TAT			Received by:			

AS 4/1/16

AC *[Signature]* 4/1/16

AM 4/1/16

4/2/16 4:00

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

8

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
87	33	1	Admin - 1004 - 12x12 Black FT.	25SF	NF	G
88	33	1	↓	↓	↓	G
89	34	1	↓ - 4" Vinyl Covebase + Mosaic	100SF	NF	G
90	34	1	↓	↓	↓	G
91	35	1	1004L - Textured Ceiling	1,000SF	F	D
92	35	1	↓	↓	↓	
93	35	1	↓	↓	↓	
94	35	1	↓	↓	↓	
95	35	1	↓	↓	↓	
96	36	1	1006A - Ceramic Grout	55SF	NF	D
97	36	1	↓	↓	↓	D
98	37	2	- 2012F Closet - 12 x 12 Beige FT.	20SF	NF	D
99	37	2	↓	↓	↓	D

Special Instructions/ Turnaround Time:

Stop at 1st Positive per Homogenous Area

5 day TAT

E-Mail Results to AdelaideLabResults@adelaidellc.com

Relinquished by: *[Signature]*

Received by: *[Signature]* 3/28/16

Relinquished by:

Received by:

4/13/16

AC *[Signature]* 4/6/16

4/14/16

4/21/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

9

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Frangible NonFrangible	Condition g, d, sd
100	38	2	Admin. - 2012F Closet - Brown Floor Mastic	20SF	NF	D
101	38	2	↓	↓	NF	D
102	39	2	↓ - 2011A - 12x12 Gray F.T.	40SF	NF	D
103	39	2	↓	↓	NF	D
104	40	1	↓ - 1001A - 9x9 Ceramic-Mortar	300SF	NF	D
105	40	1	↓	↓	NF	D
106	41	3	H. R. - 3002 - Wall Plaster - Top Coat	5,000SF	F	D
107	41	3	↓	↓	↓	↓
108	41	3	↓	↓	↓	↓
109	41	3	↓	↓	↓	↓
110	41	3	↓	↓	↓	↓
111	41	3	↓	↓	↓	↓
112	41	3	↓	↓	↓	↓
Special Instructions/ Turnaround Time:			Relinquished by: <i>[Signature]</i>			
Stop at 1st Positive per Homogenous Area			Received by: <i>[Signature]</i> 3/28/16			
5 day TAT			Relinquished by:			
E-Mail Results to AdelaideLabResults@adelaideinc.com			Received by:			

061602991

AC

Brewster 4/4/16

061602991

4/2/16 4102

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

10

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25		Inspector(s) Jason Fullum		
735 Anderson Hill Road							
Purchase, NY 10577			Project #: PGS:15100.02-IN				
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd	
113	42	3	H.R. - 3002 - Wall Plaster - Base Coat	5,000 SF	F	D	
114	42	3	↓ ↓ ↓ ↓ ↓ ↓ ↓	↓	↓	↓	
115	42	3					
116	42	3					
117	42	3					
118	42	3					
119	42	3					
120	43	3					- Ceiling Plaster - Top Coat
121	43	3	↓ ↓ ↓ ↓ ↓	↓	↓	↓	
122	43	3					
123	43	3					
124	43	3					
125	43	3					

Special Instructions/ Turnaround Time:

Stop at 1st Positive per Homogenous Area

5 day TAT

E-Mail Results to AdelaideLabResults@adelaidellc.com

Relinquished by: *[Signature]*

Received by: *[Signature]* **3/28/16**

Relinquished by:

Received by:

845 41316

[Signature] 4/6/16

[Signature] 4/1/16


4/12/16 41316

Adelaide Environmental Health Associates, Inc


1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
126	43	3	H.R. - 3002 - Ceiling Water - Top Coat	2,000SF	F	D
127	44	3	- Base Coat			
128	44	3				
129	44	3				
130	44	2				
131	44	3				
132	44	3				
133	44	3				
134	45	3	- 3003 - Multi Colored Linoleum	50SF	NF	D
135	45	3				
136	46	3	- 2nd Layer Flooring			
137	46	3				
Special Instructions/ Turnaround Time:			Relinquished by:  3/28/16			
Stop at 1st Positive per Homogenous Area			Received by:			
5 day TAT			Relinquished by:			
E-Mail Results to AdelaideLabResults@adelaideinc.com			Received by:			

4/13/16

AC  4/14/16

Matt 4/14/16

1/4/16 4/12

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24

Brewster, NY 10509



845-278-7710

845-278-7750 - fax


061602991

12


OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25		Inspector(s) Jason Fullum			
735 Anderson Hill Road								
Purchase, NY 10577			Project #: PGS:15100.02-IN					
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description			Quantity (In Feet)	Frangible NonFrangible	Condition g, d, sd
138	47	2	H.R. - 2055 - 12x12 Gray F.T.			25 SF	NF	D
139	47	2	↓			↓		↓
140	48	2	↓ - 12x12 White F.T.			25 SF		↓
141	48	2	↓			↓		↓
142	49	2	↓ - Black mesh			50 SF		G
143	49	2	↓			↓		↓
144	50	2	↓ - Sink Coating			4 SF		↓
145	50	2	↓			↓		↓
146	51	1	↓ - 1001 - Fireplace Stone Mortar			58 SF	NF	D
147	51	1	↓			↓		D
148	52	B	↓ - Dmt. - Cmu Mortar			300 SF	NF	D
149	52	B	↓			↓		D
Special Instructions/ Turnaround Time:			Relinquished by:  Received by:  3/28/16 Relinquished by: Received by:					
Stop at 1st Positive per Homogenous Area			5 day TAT					
E-Mail Results to AdelaideLabResults@adelaidellc.com								

4/1/16

AC  4/1/16

AM  4/1/16

J  4/1/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

13

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23/16 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Removable NonFriable	RECEIVED BY ANALYTICAL LAB
150	53	B	H.R. - Bsmth - Drywall	40 SF	F	D
151	53	B	↓	↓	↓	↓
152	54	B	Joint Compound	↓	↓	↓
153	54	B	↓	↓	↓	↓
154	55	B	- Pipe Insulation	25 LF	F	D
155	55	B	↓	↓	↓	↓
156	55	B	↓	↓	↓	↓
157	56	B	- Debris on Metal Support	1 SF	F	SD
158	57	B	- Debris on Geli Elbow	1 LF	F	SD
159	58	I	Business Annex - Skin Coat on Concrete	150 SF	F	B
160	58	I	↓	↓	↓	↓
161	58	I	↓	↓	↓	↓
162	58	I	↓	↓	↓	↓
Special Instructions/ Turnaround Time:				Relinquished by: <i>[Signature]</i>		
Stop at 1st Positive per Homogenous Area				Received by: <i>[Signature]</i> 3/28/16		
E-Mail Results to AdelaideLabResults@adelaideinc.com				Relinquished by:		
				Received by:		

5 day TAT

3/24/16

[Signature] 4/1/16

[Signature] 4/1/16

[Signature] 4/2/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23/16 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Fracture NonFracture	Condition ps p. g.
163	58	1	Business Annex - Skin Coat on Concrete	1,000 SF	F	D
164	59	1	↓ - Concrete	1,500 SF	F	D
165	59	1	↓	↓	28	D
166	60	1	↓ - Black Mastic Under Carpet	600 SF	NF	D
167	60	1	↓	↓	↓	D
168	61	B	↓ - Drywell	200 SF	F	SD
169	61	B	↓	↓	↓	↓
170	62	B	↓ - Joint Compound	↓	↓	↓
171	62	B	↓	↓	↓	↓
172	63	B	↓ - Brick Mortar	200 SF	NF	D
173	63	B	↓	↓	↓	D
174	64	1	Gate House - 12x12 Geyling Tile	2,000 SF	F	D
175	64	1	↓	↓	F	D
Special Instructions/ Turnaround Time:				Relinquished by:		
Stop at 1st Positive per Homogenous Area				Received by:		
E-Mail Results to AdelaideLabResults@adelaidellc.com				Relinquished by:		
5 day TAT				Received by:		

4/4/16

AC [Signature] 4/4/16

Matthew 4/14/16

4/2/16 ylon

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24

Brewster, NY 10509

845-278-7710

845-278-7750 - fax

061602991

15

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Frable NonFrable	Condition g, d, sd
176	65	1	Gate House - Glue Dabs	2, 0.01F	NF	D
177	65	1	↓	↓	↓	↓
178	66	1	- Dry well	3, 0.01F	F	↓
179	66	1	↓	↓	↓	↓
180	67	1	- Plaster Wall - Top Coat	5, 0.01F	F	D
181	67	1	↓	↓	↓	↓
182	67	1	↓	↓	↓	↓
183	67	1	↓	↓	↓	↓
184	67	1	↓	↓	↓	↓
185	67	1	↓	↓	↓	↓
186	67	1	↓	↓	↓	↓
187	68	1	- Base Coat	5, 0.01F	↓	↓
188	68	1	↓	↓	↓	↓

Special Instructions/ Turnaround Time:

Stop at 1st Positive per Homogenous Area

E-Mail Results to AdelaideLabResults@adelaidellc.com

5 day TAT

Relinquished by: *Jason Fullum*

Received by: *3/28/16*

Relinquished by:

Received by:

4/1/16

Adelaide
4/14/16

4/14/16

4/14/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

16

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25		Inspector(s) Jason Fullum		
735 Anderson Hill Road							
Purchase, NY 10577			Project #: PGS:15100.02-IN				
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd	
189	68	1	Gate House - Plaster Wall - Base Coat	500 SF	F	D	
190	68	1	↓	↓	↓	↓	
191	68	1	↓	↓	↓	↓	
192	68	1	↓	↓	↓	↓	
193	68	1	↓	↓	↓	↓	
194	69	1	↓ - Fireplace - Back Mante	30 SF	NF	G	
195	69	1	↓	↓	↓	G	
196	70	1	↓ - West Room - Linoleum + Mastic	250 SF	NF	D	
197	70	1	↓	↓	↓	D	
198	71	1	↓ - Back Flush	100 SF	NF	D	
199	71	1	↓	↓	↓	D	
200	72	B	↓ - Debris on Ground	200 SF	F	SD	
201	72	B	↓	↓	↓	↓	

Special Instructions/ Turnaround Time:

Stop at 1st Positive per Homogenous Area

E-Mail Results to AdelaideLabResults@adelaideinc.com

5 day TAT

Relinquished by: *[Signature]*

Received by: *[Signature]*

Relinquished by: *[Signature]*

Received by: *[Signature]*

3/28/16

4/13/16

[Signature] 4/14/16

[Signature] 4/14/16

[Signature] 4/14/16



Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

17

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23/16 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
202	73	B	Gsta House - Pipe Insulation	50 LF	F	SD
203	73	B	↓	↓	↓	↓
204	73	B	↓	↓	↓	↓
205	74	B	- Mudded Fittings	1 LF	F	D
206	74	B	↓	↓	↓	↓
207	74	B	↓	↓	↓	↓
208	75	B	- Concrete	200 SF	NF	G
209	75	B	↓	↓	↓	G
210	76	B	- Flue Sealant	40 SF	NF	D
211	76	B	↓	↓	↓	D
212	77	#2	- Bathroom + 9x9 F.T. + Modic	40 SF	NF	D
213	77	2	↓	↓	↓	D
Special Instructions/ Turnaround Time:			Relinquished by: 			
Stop at 1st Positive per Homogenous Area			Received by:  3/28/16			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by:			
			Received by:			

4/13/16

AR  4/14/16



Matt 4/19/16

4/16/16 8:00

061602991


18

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23/16 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
214	78	2	Gate House - Joint Compound	200 SF	F	D
215	78	2	↓	↓	↓	↓
216	79	1	Facilities - Beige w/ Stracks F.T. - 1009	205 SF	NF	G
217	79	1	↓	↓	↓	G
218	80	Attic	Admin. - Blown In Insulation	300 SF	F	D
219	80	↓	↓	↓	F	D
220	80	↓	↓	↓	F	D
221	81	↓	- Canvas Over Horsehair	38 LF	NF	D
222	81	↓	↓	↓	↓	↓
223	81	↓	↓	↓	↓	↓
224	82	1	Facilities - Felt/Mat Under F.T. - 1009	205 SF	NF	G
225	82	1	↓	↓	↓	G
Special Instructions/ Turnaround Time:			Relinquished by: 			
Stop at 1st Positive per Homogenous Area			Received by: 			
E-Mail Results to AdelaideLabResults@adelaideehc.com			Relinquished by:			
			Received by:			

5 day TAT

4/3/16

 4/4/16

Matthew 4/11/16

4/6/16 4:00


Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax


061602991

19


OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
226	83	1	Facilities - 1005 - Cement Board	300 SF	NF	D
227	83	1	↓	↓	↓	D
228	84	1	↓ - Flue Sealant	4 SF	F	D
229	84	1	↓	↓	↓	D
230	85	3	Admin. - 3009 B - Ceramic Grout	75 SF	NF	D
231	85	3	↓	↓	↓	D
232	86	1	Facilities - 12x12 Spring Ceiling Tile	70 SF	F	G
233	86	1	↓	↓	↓	G
234	87	1	↓ - Joint Compound	200 SF	F	G
235	87	1	↓	↓	↓	G
236	88	1	↓ - Drywall	↓	↓	G
237	88	1	↓	↓	↓	G
Special Instructions/ Turnaround Time:			Relinquished by:  3/28/16			
Stop at 1st Positive per Homogenous Area			Received by:			
E-Mail Results to AdelaideLabResults@adelaidehc.com			Relinquished by:			
			Received by:			

061602991

AC  4/6/16

Matthew 4/4/16

4/4/16 

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

20

Order ID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable Non-Friable	Condition g, d, sd
238	89	1	Facilities - Toilet - Ceramic Grout	50 SF	NF	D
239	89	1	↓ ↓ ↓	↓	↓	D
240	90	1	↓ - 4" Covegrout Mastic	200 SF	NF	D
241	90	1	↓ ↓	↓	↓	D
242	91	1	↓ - Wood Flooring Laminates	70 SF	↓	D
243	91	1	↓ ↓	↓	↓	D
244	92	1	↓ - 1006 - Fiberboard Walls	800 SF	NF	D
245	92	1	↓ ↓	↓	↓	D
246	93	1	↓ - Ext. - Cementitious Siding	1500 SF	NF	D
247	93	1	↓ ↓	↓	↓	D
248	94	1	↓ - Window Caulk	600 SF	NF	D
249	94	1	↓ ↓	↓	↓	D
Special Instructions/ Turnaround Time:			Relinquished by:			
Stop at 1st Positive per Homogenous Area			Received by:			
E-Mail Results to AdelaideLabResults@adelaideinc.com			Relinquished by:			
			Received by:			

5 day TAT

4/13/16

AZ [Signature] 4/14/16

AM [Signature] 4/14/16

4/12/16 4/10/16


Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061602991

21

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23 - 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
250	75	BCS	Facilities - Crawlspace - Pipe Ins.	150LF	F	SD
251	95	CS	↓	↓	↓	↓
252	95	CS	↓	↓	↓	↓
253	96	CS	↓ - Debris	100SF	F	SD
254	97	R	↓ - Shingles	200SF	NF	G
255	97	R	↓	↓	↓	↓
256	98	R	↓ - Felt	↓	↓	↓
257	98	R	↓	↓	↓	↓
258	99	R	Annex - Shingles	80 SF	NF	G
259	99	R	↓	↓	↓	↓
260	100	R	↓ - Felt	↓	↓	↓
261	100	R	↓	↓	↓	↓
Special Instructions/ Turnaround Time:			Relinquished by:  3/28/16			
Stop at 1st Positive per Homogenous Area			Received by:			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by:			
			Received by:			

4/13/16

 4/14/16

4/14/16

4/26/16

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24


Brewster, NY 10509

845-278-7710

845-278-7750 - fax

061602991 22

OrderID: 061602991

Site Address: SUNY Purchase			Date: 3/23- 3/25/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
262	101	R	Amex - Window Caulk	200 LF	NF	D
263	101	I	↓	↓	↓	D
264	102	R	Admin - Roof Shingle	10,000 SF	NF	D
265	102	R	↓	↓	↓	
266	103	R	- Felt	↓	↓	
267	103	R	↓	↓	↓	
268	104	I	- Window Caulk	1,000 LF	↓	↓
269	104	I	↓	↓	↓	
270	105	I	Gate House - Roof Shingle	1000 SF	NF	D
271	105	I	↓	↓	↓	
272	106	I	- Felt	↓	↓	
273	106	I	↓	↓	↓	
Special Instructions/ Turnaround Time:				Relinquished by:  3/28/16		
Stop at 1st Positive per Homogenous Area				Received by:		
E-Mail Results to AdelaideLabResults@adelaidellc.com				Relinquished by:		
				Received by:		

5 day TAT

5 day TAT

E-Mail Results to AdelaideLabResults@adelaidellc.com

4/13/16

4/14/16

4/14/16

4/14/16

ates, Inc

061602991 23

Page 23 Of 23

of 4/2/16 4:00

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061603688

CustomerID: ADEL50

CustomerPO:

ProjectID:

Attn: **Adelaide Associates, LLC**
1511 Route 22
Suite C-24
Brewster, NY 10509

Phone: (845) 278-7710
Fax: (845) 278-7750
Received: 04/14/16 10:03 AM
Analysis Date: 4/15/2016
Collected: 4/13/2016

Project: SUNY Purchase, 735 Anderson Hill Road, Purchase, NY 10577, Project #: PGS: 15100.02-IN

Test Report: Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 97-255 061603688-0001		Description Homogeneity	Roof, Facilities - Shingles Heterogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Brown/Red/B lack	5.1% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/15/2016	Brown/Red/B lack			None Detected
Sample ID 98-257 061603688-0002		Description Homogeneity	Roof, Facilities - Felt Homogeneous		
PLM NYS 198.1 Friable					Not Analyzed
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Black	3.7% Glass		Inconclusive: None Detected
TEM NYS 198.4 NOB	4/15/2016	Black			None Detected
Sample ID 109-278 061603688-0003		Description Homogeneity	1st Fl., Admin. - Wall Plaster, Top Coat Heterogeneous		
PLM NYS 198.1 Friable	4/15/2016	Tan/White		60.00% Gypsum 35.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 109-279 061603688-0004		Description Homogeneity	1st Fl., Admin. - Wall Plaster, Top Coat Heterogeneous		
PLM NYS 198.1 Friable	4/15/2016	Tan/White		55.00% Gypsum 40.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/15/2016 02:28:17

Test Report 198VCM-7.30.0 Printed: 4/15/2016 2:28:17 AM

Page 1

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061603688

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

		Non Asbestos			Asbestos
Test		Color	Fibrous	Non-Fibrous	
Sample ID 109-280 061603688-0005	Description 1st Fl., Admin. - Wall Plaster, Top Coat Homogeneity Heterogeneous				
PLM NYS 198.1 Friable	4/15/2016 Tan/White		60.00% Gypsum 35.00% Ca Carbonate 5.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 110-281 061603688-0006	Description 1st Fl., Admin. - Wall Plaster, Base Coat Homogeneity Homogeneous				
PLM NYS 198.1 Friable	4/15/2016 Gray/Tan		59.00% Quartz 27.00% Gypsum 5.00% Ca Carbonate 7.75% Non-fibrous (other)		1.25% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 110-282 061603688-0007	Description 1st Fl., Admin. - Wall Plaster, Base Coat Homogeneity				
PLM NYS 198.1 Friable	4/15/2016				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 110-283 061603688-0008	Description 1st Fl., Admin. - Wall Plaster, Base Coat Homogeneity				
PLM NYS 198.1 Friable	4/15/2016				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 111-284 061603688-0009	Description 2nd Fl., Admin. - Wall Plaster, Top Coat Homogeneity Heterogeneous				
PLM NYS 198.1 Friable	4/15/2016 White		6.00% Mica 79.00% Ca Carbonate 15.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/15/2016 02:28:17

Test Report 198VCM-7.30.0 Printed: 4/15/2016 2:28:17 AM

Page 2

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061603688

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report: Asbestos Analysis of Bulk Material

		Non Asbestos			Asbestos
Test		Color	Fibrous	Non-Fibrous	
Sample ID 111-285 061603688-0010	Description 2nd Fl., Admin. - Wall Plaster, Top Coat Homogeneity Heterogeneous				
PLM NYS 198.1 Friable	4/15/2016	White		8.00% Mica 67.00% Ca Carbonate 25.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 111-286 061603688-0011	Description 2nd Fl., Admin. - Wall Plaster, Top Coat Homogeneity Heterogeneous				
PLM NYS 198.1 Friable	4/15/2016	Tan/White		5.00% Mica 35.00% Gypsum 40.00% Ca Carbonate 20.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 112-287 061603688-0012	Description 2nd Fl., Admin. - Wall Plaster, Base Coat Homogeneity Homogeneous				
PLM NYS 198.1 Friable	4/15/2016	Gray		45.00% Quartz 30.00% Ca Carbonate 25.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 112-288 061603688-0013	Description 2nd Fl., Admin. - Wall Plaster, Base Coat Homogeneity Homogeneous				
PLM NYS 198.1 Friable	4/15/2016	Gray		55.00% Quartz 25.00% Ca Carbonate 20.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 112-289 061603688-0014	Description 2nd Fl., Admin. - Wall Plaster, Base Coat Homogeneity Homogeneous				
PLM NYS 198.1 Friable	4/15/2016	Gray		45.00% Quartz 30.00% Ca Carbonate 25.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 04/15/2016 02:28:17

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061603688

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	113-290	Description	3rd Fl., Admin. - Wall Plaster, Top Coat		
	061603688-0015	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/15/2016	White		70.00% Gypsum 25.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	113-291	Description	3rd Fl., Admin. - Wall Plaster, Top Coat		
	061603688-0016	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	4/15/2016	Tan/White		70.00% Gypsum 15.00% Ca Carbonate 15.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	113-292	Description	3rd Fl., Admin. - Wall Plaster, Top Coat		
	061603688-0017	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	4/15/2016	Tan/White		70.00% Gypsum 15.00% Ca Carbonate 15.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	114-293	Description	3rd Fl., Admin. - Wall Plaster, Base Coat		
	061603688-0018	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	4/15/2016	Gray	<1% Cellulose	55.00% Quartz 32.00% Gypsum 5.00% Ca Carbonate 7.50% Non-fibrous (other)	0.50% Chrysotile
TEM recommended.					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061603688

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	114-294	Description	3rd Fl., Admin. - Wall Plaster, Base Coat			
	061603688-0019	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/15/2016	Gray	2.00% Cellulose	48.00% Quartz		None Detected
				37.00% Gypsum		
				5.00% Ca Carbonate		
				8.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	114-295	Description	3rd Fl., Admin. - Wall Plaster, Base Coat			
	061603688-0020	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	4/15/2016	Gray	1.00% Cellulose	49.00% Quartz		None Detected
				37.00% Gypsum		
				5.00% Ca Carbonate		
				8.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	115-296	Description	1st Fl., Annex - Wire Insulation			
	061603688-0021	Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Brown/Gray/ White	<1% Glass			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/15/2016	Brown/Gray/ White				None Detected
Sample ID	115-297	Description	1st Fl., Annex - Wire Insulation			
	061603688-0022	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Black	<1% Glass			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/15/2016	Black				None Detected
Sample ID	116-298	Description	Bsmt., Gate House - Wire Insulation			
	061603688-0023	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable						Not Analyzed
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Black	<1% Glass			Inconclusive: None Detected
TEM NYS 198.4 NOB	4/15/2016	Black				None Detected

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061603688

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report: Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
		Color	Fibrous	Non-Fibrous
Sample ID	116-299	Description	Bsmt., Gate House - Wire Insulation	
	061603688-0024	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Brown/Gray	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/15/2016	Brown/Gray	None Detected	
Sample ID	117-300	Description	Bsmt., Admin. - Wire Insulation	
	061603688-0025	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Tan/Black	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/15/2016	Tan/Black	None Detected	
Sample ID	117-301	Description	Bsmt., Admin. - Wire Insulation	
	061603688-0026	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable				Not Analyzed
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB	4/15/2016	Tan/Black	Inconclusive: None Detected	
TEM NYS 198.4 NOB	4/15/2016	Tan/Black	None Detected	

Analyst(s)

Keith McWilliams

Steve Juszczuk

Michelle McGowan, Laboratory Manager
or other approved signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non-asbestos containing.

All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL.

EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. Carle Place, NY NYS ELAP 11469

Initial Report From 04/15/2016 02:28:17

Test Report 198VCM-7.30.0 Printed: 4/15/2016 2:28:17 AM

THIS IS THE LAST PAGE OF THE REPORT.

Page 6

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061603688

OrderID: 061603688

Site Address: SUNY Purchase			Date: 4/13/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Frangible Non-Frangible	Condition g, d, sd
255	97	R	Facilities - Shingles	200 SF	NF	G
257	98	R	↓ - Felt	↓	NF	G
278	109	1	Admin. - Wall Plaster - Top Coat	20,000 SF	F	D
279	109	1	↓	↓	↓	↓
280	109	1	↓	↓	↓	↓
281	110	1	↓ - Base Coat	↓	↓	↓
282	110	1	↓	↓	↓	↓
283	110	1	↓	↓	↓	↓
284	111	2	↓ - Top Coat	↓	↓	↓
285	111	2	↓	↓	↓	↓
286	111	2	↓	↓	↓	↓
287	112	2	↓ - Base Coat	↓	↓	↓
288	112	2	↓	↓	↓	↓
Special Instructions/ Turnaround Time:			Relinquished by: [Signature] 4/13/16			
Stop at 1st Positive per Homogenous Area			Received by: [Signature] 4/14/16			
E-Mail Results to AdelaideLabResults@adelaidelhc.com			Relinquished by:			
			Received by:			

4-15-16

4/14/16 12:00 PM

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061603688

OrderID: 061603688

Site Address: SUNY Purchase			Date: 4/13/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGS:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
289	112	2	Admin. - Wall Plaster - Base Coat	20, awl SF	F	D
290	113	3	- Top Coat			
291	113	3				
292	113	3				
293	114	3	- Base Coat			
294	114	3				
295	114	3				
296	115	1	Annex - Wire Insulation	500 LF	NF	D
297	115	1				
298	116	B	Gate House - Wire Insulation	500 LF	NF	D
299	116	B				
300	117	B	Admin - Wire Insulation	10, awl SF	NF	D
301	117	B				
Special Instructions/ Turnaround Time:				Relinquished by: <i>[Signature]</i> 4/13/16		
Stop at 1st Positive per Homogenous Area				Received by: <i>[Signature]</i> 4-14-16		
E-Mail Results to AdelaideLabResults@adelaidelhc.com				Relinquished by:		
				Received by:		

Kurt Alva 4/13/16

4/15/16 1200 PM

**EMSL Analytical, Inc.**

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031613409

Customer ID: ADEL50

Customer PO:

Project ID:

Attention: Adelaide Associates, LLC

1511 Route 22

Suite C-24

Brewster, NY 10509

Phone: (845) 278-7710**Fax:** (845) 278-7750**Received Date:** 5/14/2016 11:26 AM**Analysis Date:** 5/16/2016**Collected Date:** 5/13/2016**Project:** PGA:15100.02-IH/ SUNY PURCHASE/ 735 ANDERSON HILL ROAD, PURCHASE, NY 10577**Test Report:Asbestos Analysis of Bulk Material**

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 1 031613409-0001		Description	BASEMENT/ SPACE 0004 - WALL PLASTER BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Tan		35.00% Ca Carbonate 35.00% Non-fibrous (other) 30.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 2 031613409-0002		Description	BASEMENT/ SPACE 0004 - WALL PLASTER BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Tan/White		35.00% Ca Carbonate 20.00% Gypsum 20.00% Non-fibrous (other) 25.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 3 031613409-0003		Description	BASEMENT/ SPACE 0004 - WALL PLASTER BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown		5.00% Ca Carbonate 35.00% Non-fibrous (other) 60.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 4 031613409-0004		Description	BASEMENT/ SPACE 0004 - WALL PLASTER TOP COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown	3.00% Hair	20.00% Gypsum 40.00% Non-fibrous (other) 37.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 05/16/2016 15:53:13

**EMSL Analytical, Inc.**

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com / manhattanlab@emsl.com>

EMSL Order: 031613409

Customer ID: ADEL50

Customer PO:

Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 5 031613409-0005		Description	BASEMENT/ SPACE 0004 - WALL PLASTER TOP COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown	3.00% Hair	50.00% Non-fibrous (other) 47.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 6 031613409-0006		Description	BASEMENT/ SPACE 0004 - WALL PLASTER TOP COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	White		45.00% Ca Carbonate 15.00% Non-fibrous (other) 40.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 7 031613409-0007		Description	BASEMENT/ SPACE 0004 - CEILING PLASTER BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Tan		35.00% Ca Carbonate 35.00% Non-fibrous (other) 30.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 8 031613409-0008		Description	BASEMENT/ SPACE 0004 - CEILING PLASTER BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Tan		25.00% Ca Carbonate 20.00% Gypsum 25.00% Non-fibrous (other) 30.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 9 031613409-0009		Description	BASEMENT/ SPACE 0004 - CEILING PLASTER BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown	2.00% Hair	10.00% Ca Carbonate 23.00% Non-fibrous (other) 65.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 05/16/2016 15:53:13



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com / manhattanlab@emsl.com>

EMSL Order: 031613409

Customer ID: ADEL50

Customer PO:

Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 10 031613409-0010		Description Homogeneity	BASEMENT/ SPACE 0004 - CEILING PLASTER BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown		2.00% Mica 48.00% Non-fibrous (other) 50.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 11 031613409-0011		Description Homogeneity	BASEMENT/ SPACE 0004 - CEILING PLASTER BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown	2.00% Hair	50.00% Non-fibrous (other) 48.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 12 031613409-0012		Description Homogeneity	BASEMENT/ SPACE 0004 - CEILING PLASTER BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown		10.00% Ca Carbonate 30.00% Non-fibrous (other) 60.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 13 031613409-0013		Description Homogeneity	BASEMENT/ SPACE 0008 HALL - PLASTER WALL BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown/Gray		25.00% Ca Carbonate 5.00% Mica 25.00% Non-fibrous (other) 45.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 14 031613409-0014		Description Homogeneity	BASEMENT/ SPACE 0007 - PLASTER WALL BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	White		45.00% Ca Carbonate 55.00% Non-fibrous (other)	None Detected
Inseparable paint / coating layer included in analysis					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 05/16/2016 15:53:13



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com / manhattanlab@emsl.com>

EMSL Order: 031613409

Customer ID: ADEL50

Customer PO:

Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 15 031613409-0015		Description Homogeneity	BASEMENT/ SPACE 0007 - PLASTER WALL BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	White		45.00% Ca Carbonate 55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 16 031613409-0016		Description Homogeneity	BASEMENT/ SPACE 0008 HALL - PLASTER WALL TOP COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Tan/White		25.00% Ca Carbonate 72.53% Non-fibrous (other)	2.47% Chrysotile
Inseparable paint / coating layer included in analysis					
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 17 031613409-0017		Description Homogeneity	BASEMENT/ SPACE 0007 - PLASTER WALL TOP COAT		
PLM NYS 198.1 Friable	5/16/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 18 031613409-0018		Description Homogeneity	BASEMENT/ SPACE 0007 - PLASTER WALL TOP COAT		
PLM NYS 198.1 Friable	5/16/2016				Positive Stop
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 19 031613409-0019		Description Homogeneity	BASEMENT/ SPACE 0007 - PLASTER CEILING BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown	3.00% Cellulose	35.00% Gypsum 37.00% Non-fibrous (other) 25.00% Quartz	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 20 031613409-0020		Description Homogeneity	BASEMENT/ HALL NEAR SPACE 0008 - PLASTER CEILING BASE COAT Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown	2.00% Cellulose	52.25% Non-fibrous (other) 45.00% Quartz	0.75% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 05/16/2016 15:53:13

**EMSL Analytical, Inc.**

307 West 38th Street New York, NY 10018
 Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com / manhattanlab@emsl.com>

EMSL Order: 031613409

Customer ID: ADEL50

Customer PO:

Project ID:

Test Report:Asbestos Analysis of Bulk Material

Test	Analyzed Date	Color	Non-Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 21 031613409-0021		Description	BASEMENT/ HALL NEAR SPACE 0008 - PLASTER CEILING BASE COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown		12.00% Ca Carbonate 17.25% Non-fibrous (other) 70.00% Quartz	0.75% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 22 031613409-0022		Description	BASEMENT/ SPACE 0007 - PLASTER CEILING TOP COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	White		50.00% Ca Carbonate 50.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 23 031613409-0023		Description	BASEMENT/ HALL NEAR SPACE 0008 - PLASTER CEILING TOP COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	White		45.00% Ca Carbonate 55.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 24 031613409-0024		Description	BASEMENT/ HALL NEAR SPACE 0008 - PLASTER CEILING TOP COAT		
		Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/16/2016	Brown		12.00% Ca Carbonate 26.50% Non-fibrous (other) 60.00% Quartz	1.50% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial report from: 05/16/2016 15:53:13



EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018
Tel/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order: 031613409

Customer ID: ADEL50

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Material

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via NYS ELAP Approved Methods. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 5/14/2016

Analysis Completed Date: 5/16/2016

Sample Receipt Time: 11:26 AM

Analysis Completed Time: 2:44 AM

Analyst(s):

Daena Charles PLM NYS 198.1 Friable (7)

Tiquasha Thompson PLM NYS 198.1 Friable (15)

Samples reviewed and approved by:

James Hall, Laboratory Manager
or Other Approved Signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non-asbestos containing.

All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. New York, NY NYS ELAP 11506

Initial report from: 05/16/2016 15:53:13

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

OrderID: 031613409

031613409

Site Address: SUNY Purchase			Date: 05/13/16		Inspector(s) Robert See			
735 Anderson Hill Road								
Purchase, NY 10577			Project #: SP460101VA PGA: 15100.02-IA					
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description			Quantity (In Feet)	Frable NonFrable	Condition g, d, sd
1	1	B	space 0004	Wall	Plaster	Base Coat	through 4x4	
2	1							
3	1							
4	2		space 0004			Top Coat		
5	2							
6	2							
7	3		space 0004	ceiling	Plaster	Base Coat		
8	3							
9	3							
10	4							
11	4							
12	4							
Special Instructions/ Turnaround Time:			Relinquished by: <i>[Signature]</i> Received by: <i>[Signature]</i> 5/14/16 11:26am Relinquished by: Received by: <i>[Signature]</i> 5/16/16 1:50pm					
Stop at 1st Positive per Homogenous Area			24 hr TAT					
E-Mail Results to AdelaideLabResults@adelaidelhc.com								

[Signature] 5/16/16 6:00AM

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24

Brewster, NY 10509

845-278-7710

845-278-7750 - fax

031613409

Site Address: SUNY Purchase			Date: 05/13/16		Inspector(s) Robert See			
735 Anderson Hill Road								
Purchase, NY 10577			Project #: SP-1500-02-15 PGA: 15100-02-15					
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description			Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
13	5	B	space 0008 Hall	Plaster wall	Base coat			
14	5		space 0007					
15	5		V 0007		V			
16	6		Space 0008 Hall		Top coat			
17	6		space 0007					
18	6		V V	V	V			
19	7		space 0007	Plaster ceiling	Base coat			
20	7		Hall near space 0008					
21	7		V V		V V			
22	8		space 0007		Top coat			
23	8		Hall near space 0008					
24	8	V	V V V	V	V			
Special Instructions/ Turnaround Time:			Relinquished by: <i>Robert See</i> Received by: <i>Samuel A. Lytle</i> 5/14/16 11:26am Relinquished by: Received by: <i>all</i> 5/16/16 1:50pm <i>Liquas Thompson</i> 5/16/16 6:00 AM					
Stop at 1st Positive per Homogenous Area			24 hr TAT					
E-Mail Results to AdelaideLabResults@adelaidellc.com								

OrderID: 031613409

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Attn: **Adelaide Associates, LLC****1511 Route 22****Suite C-24****Brewster, NY 10509**

Phone: (845) 278-7710

Fax: (845) 278-7750

Received: 05/28/16 10:13 AM

Analysis Date: 5/28/2016

Collected: 5/27/2016

Project: **SUNY Purchase, 735 Anderson Hill Road, Purchase, NY 10577, PGA: 15100.02-IN****Test Report:Asbestos Analysis of Bulk Material**

Test	Analyzed Date	Color	Non Asbestos		Asbestos
			Fibrous	Non-Fibrous	
Sample ID 9-25 061605584-0001		Description Homogeneity	1st Floor, Presidents Apartment - Wall Plaster - Top Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	White		5.00% Mica 20.00% Gypsum 70.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 9-26 061605584-0002		Description Homogeneity	1st Floor, Presidents Apartment - Wall Plaster - Top Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	White		3.00% Mica 80.00% Ca Carbonate 17.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 9-27 061605584-0003		Description Homogeneity	1st Floor, Presidents Apartment - Wall Plaster - Top Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 10-28 061605584-0004		Description Homogeneity	1st Floor, Presidents Apartment - Wall Plaster - Base Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	64.00% Quartz 22.00% Gypsum 5.00% Ca Carbonate 7.75% Non-fibrous (other)	1.25% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 05/31/2016 08:59:47

Test Report 198VCM-7.30.0 Printed: 5/31/2016 8:59:47 AM

Page 1

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com> carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non Asbestos	Non-Fibrous	Asbestos
Sample ID	10-29 061605584-0005	Description Homogeneity	1st Floor, Presidents Apartment - Wall Plaster - Base			
PLM NYS 198.1 Friable	5/28/2016					Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	10-30 061605584-0006	Description Homogeneity	1st Floor, Presidents Apartment - Wall Plaster - Base			
PLM NYS 198.1 Friable	5/28/2016					Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	11-31 061605584-0007	Description Homogeneity	1st Floor, Presidents Apartment - Ceiling Plaster - Top Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	White		55.00% Gypsum 35.00% Ca Carbonate 10.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	11-32 061605584-0008	Description Homogeneity	1st Floor, Presidents Apartment - Ceiling Plaster - Top Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	White		70.00% Gypsum 25.00% Ca Carbonate 5.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	11-33 061605584-0009	Description Homogeneity	1st Floor, Presidents Apartment - Ceiling Plaster - Top Homogeneous			
PLM NYS 198.1 Friable	5/31/2016	White		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Non Asbestos					
Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	12-34 061605584-0010	Description Homogeneity	1st Floor, Presidents Apartment - Ceiling Plaster - Base Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray	<1% Hair	75.00% Quartz 15.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	12-35 061605584-0011	Description Homogeneity	1st Floor, Presidents Apartment - Ceiling Plaster - Base Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray	<1% Hair	65.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	12-36 061605584-0012	Description Homogeneity	1st Floor, Presidents Apartment - Ceiling Plaster - Base Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	13-37 061605584-0013	Description Homogeneity	1st Floor, Room 1005A - Wall Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		60.00% Gypsum 5.00% Ca Carbonate 35.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	13-38 061605584-0014	Description Homogeneity	1st Floor, Room 1005A - Wall Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		55.00% Gypsum 5.00% Ca Carbonate 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 05/31/2016 08:59:47

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

		Non Asbestos			
Test		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID 13-39 061605584-0015		Description Homogeneity	1st Floor, Room 1005A - Wall Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		70.00% Gypsum 10.00% Ca Carbonate 20.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 14-40 061605584-0016		Description Homogeneity	1st Floor, Room 1005A - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Hair	65.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 14-41 061605584-0017		Description Homogeneity	1st Floor, Room 1005A - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose <1% Hair	60.00% Quartz 30.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 14-42 061605584-0018		Description Homogeneity	1st Floor, Room 1005A - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID 15-43 061605584-0019		Description Homogeneity	2nd Floor, Room 2016 - Ceiling Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		65.00% Gypsum 5.00% Ca Carbonate 30.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 05/31/2016 08:59:47

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	15-44	Description	2nd Floor, Room 2016 - Ceiling Plaster - Top Coat		
	061605584-0020	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		70.00% Gypsum 5.00% Ca Carbonate 25.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	15-45	Description	2nd Floor, Room 2016 - Ceiling Plaster - Top Coat		
	061605584-0021	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	16-46	Description	2nd Floor, Room 2016 - Ceiling Plaster - Base Coat		
	061605584-0022	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White	<1% Cellulose <1% Hair	55.00% Quartz 35.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	16-47	Description	2nd Floor, Room 2016 - Ceiling Plaster - Base Coat		
	061605584-0023	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		60.00% Quartz 30.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	16-48	Description	2nd Floor, Room 2016 - Ceiling Plaster - Base Coat		
	061605584-0024	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White	1.00% Cellulose <1% Hair	60.00% Quartz 28.00% Gypsum 5.00% Ca Carbonate 5.75% Non-fibrous (other)	0.25% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Initial Report From 05/31/2016 08:59:47

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com> carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	17-49	Description	2nd Floor, Hallway - 2012F - Wall Plaster - Top Coat			
	061605584-0025	Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White		70.00% Gypsum		None Detected
				5.00% Ca Carbonate		
				25.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	17-50	Description	2nd Floor, Hallway - 2012F - Wall Plaster - Top Coat			
	061605584-0026	Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White		40.00% Gypsum		None Detected
				45.00% Ca Carbonate		
				15.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	17-51	Description	2nd Floor, Hallway - 2012F - Wall Plaster - Top Coat			
	061605584-0027	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	5/31/2016	White		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	18-52	Description	2nd Floor, Hallway - 2012F - Wall Plaster - Base Coat			
	061605584-0028	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	65.00% Quartz		None Detected
				25.00% Gypsum		
				5.00% Ca Carbonate		
				5.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	18-53	Description	2nd Floor, Hallway - 2012F - Wall Plaster - Base Coat			
	061605584-0029	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	60.00% Quartz		None Detected
				30.00% Gypsum		
				5.00% Ca Carbonate		
				5.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

Initial Report From 05/31/2016 08:59:47

Test Report 198VCM-7.30.0 Printed: 5/31/2016 8:59:47 AM

Page 6

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color	Fibrous	Non Asbestos		Asbestos
Sample ID	18-54 061605584-0030	Description Homogeneity	2nd Floor, Hallway - 2012F - Wall Plaster - Base Coat Homogeneous			
PLM NYS 198.1 Friable	5/31/2016	Brown		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	19-55 061605584-0031	Description Homogeneity	2nd Floor, Room 2003 - Wall Plaster - Top Coat Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White/P		60.00% Gypsum 10.00% Ca Carbonate 30.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	19-56 061605584-0032	Description Homogeneity	2nd Floor, Room 2003 - Wall Plaster - Top Coat Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White/Y	6.00% Cellulose	50.00% Gypsum 14.00% Ca Carbonate 30.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	19-57 061605584-0033	Description Homogeneity	2nd Floor, Room 2003 - Wall Plaster - Top Coat Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White/P		60.00% Gypsum 5.00% Ca Carbonate 35.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	20-58 061605584-0034	Description Homogeneity	2nd Floor, Room 2003 - Wall Plaster - Base Coat Homogeneous			
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	65.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			Asbestos
		Color	Fibrous	Non-Fibrous	
Sample ID	20-59	Description	2nd Floor, Room 2003 - Wall Plaster - Base Coat		
	061605584-0035	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	60.00% Quartz 30.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	20-60	Description	2nd Floor, Room 2003 - Wall Plaster - Base Coat		
	061605584-0036	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	Brown		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	21-61	Description	2nd Floor, Room 2003 - Ceiling Plaster - Top Coat		
	061605584-0037	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		3.00% Mica 62.00% Ca Carbonate 35.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	21-62	Description	2nd Floor, Room 2003 - Ceiling Plaster - Top Coat		
	061605584-0038	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	Tan/White		5.00% Mica 70.00% Ca Carbonate 25.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	21-63	Description	2nd Floor, Room 2003 - Ceiling Plaster - Top Coat		
	061605584-0039	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	White		100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			
		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	22-64	Description	2nd Floor, Room 2003 - Ceiling Plaster - Base Coat		
	061605584-0040	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan		60.00% Quartz 29.00% Gypsum 5.00% Ca Carbonate 5.75% Non-fibrous (other)	0.25% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	22-65	Description	2nd Floor, Room 2003 - Ceiling Plaster - Base Coat		
	061605584-0041	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan		65.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	22-66	Description	2nd Floor, Room 2003 - Ceiling Plaster - Base Coat		
	061605584-0042	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	60.00% Quartz 27.00% Gypsum 5.00% Ca Carbonate 8.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	23-67	Description	2nd Floor, Room 2005A - Ceiling Plaster - Top Coat		
	061605584-0043	Homogeneity	Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016	White/Yellow		25.00% Gypsum 55.00% Ca Carbonate 20.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
		Color	Fibrous	
Sample ID	23-68	Description	2nd Floor, Room 2005A - Ceiling Plaster - Top Coat	
	061605584-0044	Homogeneity	Heterogeneous	
PLM NYS 198.1 Friable	5/28/2016	White/Yellow	60.00% Gypsum 25.00% Ca Carbonate 15.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	23-69	Description	2nd Floor, Room 2005A - Ceiling Plaster - Top Coat	
	061605584-0045	Homogeneity	Homogeneous	
PLM NYS 198.1 Friable	5/31/2016	White	100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	24-70	Description	2nd Floor, Room 2005A - Ceiling Plaster - Base Coat	
	061605584-0046	Homogeneity	Homogeneous	
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	65.00% Quartz 22.00% Gypsum 5.00% Ca Carbonate 8.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	24-71	Description	2nd Floor, Room 2005A - Ceiling Plaster - Base Coat	
	061605584-0047	Homogeneity	Homogeneous	
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	60.00% Quartz 27.00% Gypsum 5.00% Ca Carbonate 8.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
Sample ID	24-72	Description	2nd Floor, Room 2005A - Ceiling Plaster - Base Coat	
	061605584-0048	Homogeneity	Homogeneous	
PLM NYS 198.1 Friable	5/31/2016	Brown	100.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

Initial Report From 05/31/2016 08:59:47

Test Report 198VCM-7.30.0 Printed: 5/31/2016 8:59:47 AM

Page 10

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos
Sample ID	Color	Fibrous	Non-Fibrous	
25-73 061605584-0049	Description Homogeneity	2nd Floor, Room 2005A - Wall Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016 Tan/White		55.00% Gypsum 5.00% Ca Carbonate 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
25-74 061605584-0050	Description Homogeneity	2nd Floor, Room 2005A - Wall Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016 Tan/White		65.00% Gypsum 5.00% Ca Carbonate 30.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
25-75 061605584-0051	Description Homogeneity	2nd Floor, Room 2005A - Wall Plaster - Top Coat Heterogeneous		
PLM NYS 198.1 Friable	5/28/2016 Tan/White		55.00% Gypsum 5.00% Ca Carbonate 40.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
26-76 061605584-0052	Description Homogeneity	2nd Floor, Room 2005A - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016 Gray/Tan		65.00% Quartz 20.00% Gypsum 5.00% Ca Carbonate 10.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed
26-77 061605584-0053	Description Homogeneity	2nd Floor, Room 2005A - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016 Gray/Tan		60.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 10.00% Non-fibrous (other)	None Detected
PLM NYS 198.6 VCM				Not Analyzed
PLM NYS 198.6 NOB				Not Analyzed
TEM NYS 198.4 NOB				Not Analyzed

Initial Report From 05/31/2016 08:59:47

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos			
		Color	Fibrous	Non-Fibrous	Asbestos
Sample ID	26-78 061605584-0054	Description Homogeneity	2nd Floor, Room 2005A - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	Brown	100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	27-79 061605584-0055	Description Homogeneity	3rd Floor, Room 3011C - Wall Plaster - Top Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	White	80.00% Gypsum 15.00% Ca Carbonate 5.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	27-80 061605584-0056	Description Homogeneity	3rd Floor, Room 3011C - Wall Plaster - Top Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	White	70.00% Gypsum 25.00% Ca Carbonate 5.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	27-81 061605584-0057	Description Homogeneity	3rd Floor, Room 3011C - Wall Plaster - Top Coat Homogeneous		
PLM NYS 198.1 Friable	5/31/2016	White	100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	28-82 061605584-0058	Description Homogeneity	3rd Floor, Room 3011C - Wall Plaster - Base Coat Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	65.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 5.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Color		Non Asbestos		Asbestos
				Fibrous	Non-Fibrous	
Sample ID	28-83	Description	3rd Floor, Room 3011C - Wall Plaster - Base Coat			
	061605584-0059	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	<1% Cellulose	60.00% Quartz		None Detected
				25.00% Gypsum		
				5.00% Ca Carbonate		
				10.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	28-84	Description	3rd Floor, Room 3011C - Wall Plaster - Base Coat			
	061605584-0060	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan		60.00% Quartz		None Detected
				25.00% Gypsum		
				5.00% Ca Carbonate		
				10.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	29-85	Description	3rd Floor, Room 3011C - Ceiling Plaster - Top Coat			
	061605584-0061	Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White		52.00% Gypsum		None Detected
				8.00% Ca Carbonate		
				40.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	29-86	Description	3rd Floor, Room 3011C - Ceiling Plaster - Top Coat			
	061605584-0062	Homogeneity	Heterogeneous			
PLM NYS 198.1 Friable	5/28/2016	Tan/White		64.00% Gypsum		None Detected
				16.00% Ca Carbonate		
				20.00% Non-fibrous (other)		
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed
Sample ID	29-87	Description	3rd Floor, Room 3011C - Ceiling Plaster - Top Coat			
	061605584-0063	Homogeneity	Homogeneous			
PLM NYS 198.1 Friable	5/31/2016	White		100.00% Non-fibrous (other)		None Detected
PLM NYS 198.6 VCM						Not Analyzed
PLM NYS 198.6 NOB						Not Analyzed
TEM NYS 198.4 NOB						Not Analyzed

Initial Report From 05/31/2016 08:59:47

Test Report 198VCM-7.30.0 Printed: 5/31/2016 8:59:47 AM

Page 13

**EMSL Analytical, Inc.**

528 Mineola Avenue, Carle Place, NY 11514

Phone/Fax: (516) 997-7251 / (516) 997-7528

<http://www.EMSL.com>carleplacelab@emsl.com

EMSL Order: 061605584

CustomerID: ADEL50

CustomerPO:

ProjectID:

Test Report:Asbestos Analysis of Bulk Material

Test		Non Asbestos		Asbestos	
		Color	Fibrous	Non-Fibrous	
Sample ID	30-88	Description	3rd Floor, Room 3011C - Ceiling Plaster - Base Coat		
	061605584-0064	Homogeneity	Homogeneous		
PLM NYS 198.1 Friable	5/28/2016	Gray/Tan	3.00% Cellulose	56.00% Quartz 25.00% Gypsum 5.00% Ca Carbonate 9.75% Non-fibrous (other)	1.25% Chrysotile
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	30-89	Description	3rd Floor, Room 3011C - Ceiling Plaster - Base Coat		
	061605584-0065	Homogeneity			
PLM NYS 198.1 Friable	5/28/2016				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed
Sample ID	30-90	Description	3rd Floor, Room 3011C - Ceiling Plaster - Base Coat		
	061605584-0066	Homogeneity			
PLM NYS 198.1 Friable	5/28/2016				Positive Stop (Not Analyzed)
PLM NYS 198.6 VCM					Not Analyzed
PLM NYS 198.6 NOB					Not Analyzed
TEM NYS 198.4 NOB					Not Analyzed

Analyst(s)

Matthew Greco

Steve Juszczuk

Michelle McGowan, Laboratory Manager
or other approved signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non-asbestos containing.

All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL.

EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. Carle Place, NY NYS ELAP 11469

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061605584

OrderID: 061605584

Site Address: SUNY Purchase			Date: 05/27/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGA:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
25	9	1	<p>President's Apartment - Wall Plaster - Top</p> <p>↓</p> <p>- Base</p> <p>↓</p> <p>- Ceiling Plaster - Top</p> <p>↓</p> <p>- Base</p> <p>↓</p>		F	D
26	9	1			F	D
27	9	1			F	D
28	9	1			F	D
29	10	1			F	D
30	10	1			F	D
31	11	1			F	D
32	11	1			F	D
33	11	1			F	D
34	12	1			F	D
35	12	1			F	D
36	12	1			F	D
Special Instructions/ Turnaround Time:			Relinquished by: <i>[Signature]</i> Received by: <i>Sherry DeSouza</i> 05/28/16 Relinquished by: <i>[Signature]</i> ID: BAM Received by:			
Stop at 1st Positive per Homogenous Area E-Mail Results to AdelaideLabResults@adelaidellc.com			24 hr TAT RECEIVED ANALYTICAL 05/28 AM 10:13			

5/28/16 2317

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061605584

OrderID: 061605584

Site Address: SUNY Purchase			Date: 05/27/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGA:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
37	13	1	Room 1005A - Wall Plaster - Top Coat		F	D
38	13	1				
39	13	1				
40	14	1				
41	14	1				
42	14	1				
43	15	2	Room 2016 - Ceiling Plaster - Top Coat		F	D
44	15	2				
45	15	2				
46	16	2				
47	16	2				
48	16	2				
Special Instructions/ Turnaround Time:			Relinquished by:			
Stop at 1st Positive per Homogenous Area			Relinquished by: <i>Sherry Desoria</i> 05/28/16 10:13 AM			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by:			
			Received by:			


24 hr TAT

15728/16 237M

Adelaide Environmental Health Associates, Inc
 1511 Route 22, Suite C24
 Brewster, NY 10509
 845-278-7710
 845-278-7750 - fax

061605584

Order ID: 061605584

Site Address: SUNY Purchase			Date: 05/27/16		Inspector(s) Jason Fullum		
735 Anderson Hill Road							
Purchase, NY 10577			Project #: PGA:15100.02-IN		Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description				
49	17	2	Hallway - 20/2F - Wall Plaster - Top Coat				D
50	17	2					
51	17	2					
52	18	2					
53	18	2					
54	18	2					
55	19	2	Room 2003 - Wall Plaster - Top Coat				D
56	19	2					
57	19	2					
58	20	2					
59	20	2					
60	20	2					
Special Instructions/ Turnaround Time:			Relinquished by:  Received by: Sherry Desoria 05/28/16 10:13AM Relinquished by: Received by:				
Stop at 1st Positive per Homogenous Area			24 hr TAT				
E-Mail Results to AdelaideLabResults@adelaidellc.com							

RECEIVED

ANALYTICAL
 CHIEF
 05/28/16 10:13

05/28/16 2:37 PM

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061605584

OrderID: 061605584

Site Address: SUNY Purchase			Date: 05/27/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGA:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
61	21	2	Room 2003 - Ceiling Plaster - Top Coat		F	D
62	21	2	↓		F	D
63	21	2	↓		F	D
64	22	2	↓ - Base Coat		F	D
65	22	2	↓		F	D
66	22	2	↓		F	D
67	23	2	Room 2005A - Ceiling Plaster - Top Coat		F	D
68	23	2	↓		F	D
69	23	2	↓		F	D
70	24	2	↓ - Base Coat		F	D
71	24	2	↓		F	D
72	24	2	↓		F	D
Special Instructions/ Turnaround Time:			Relinquished by: <i>[Signature]</i>			
Stop at 1st Positive per Homogenous Area			Received by: <i>[Signature]</i> 05/28/16 10:13AM			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by: <i>[Signature]</i>			
			Received by:			

24 hr TAT

RECEIVED
ANALYTICAL
16 JUN 28 AM 10:13



Adelaide 732m

Adelaide Environmental Health Associates, Inc

1511 Route 22, Suite C24
Brewster, NY 10509
845-278-7710
845-278-7750 - fax

061605584

OrderID: 061605584

Site Address: SUNY Purchase			Date: 05/27/16	Inspector(s) Jason Fullum		
735 Anderson Hill Road						
Purchase, NY 10577			Project #: PGA:15100.02-IN			
Sample ID #	Homogeneous Area	Floor Level	Sample Location/Description	Quantity (In Feet)	Friable NonFriable	Condition g, d, sd
73	25	2	Room 2005A - Wall Plaster - Top Coat		↓	↓
74	25	2	↓		↓	↓
75	25	2	↓		↓	↓
76	26	2	- Base Coat		↓	↓
77	26	2	↓		↓	↓
78	26	2	↓		↓	↓
79	27	3	301A Room 301C - Wall Plaster - Top Coat		↓	↓
80	27	3	↓		↓	↓
81	27	3	↓		↓	↓
82	28	3	- Base Coat		↓	↓
83	28	3	↓		↓	↓
84	28	3	↓		↓	↓
Special Instructions/ Turnaround Time:			Relinquished by: 			
Stop at 1st Positive per Homogenous Area			Received by:  05/28/16 10:13 AM			
E-Mail Results to AdelaideLabResults@adelaidellc.com			Relinquished by:			
			Received by:			

RECEIVED

Adelaide 2377

061605584

Page 6 Of 6

[illegible]

Matt 5/31/16

10/20/16 272

APPENDIX B

XRF READINGS

SUNY Purchase

Index	Time	Site	Space Type	Floor	Room	Component	Color	Substrate	PbC	PbL	PbK	Units	Results	Inspector
1	2016-03-23 10:56	SUNY PURCHASE	School	Basement	Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.00 ± 0.40	mg / cm ^2	Null	Jason Fullum
2	2016-03-23 10:57	SUNY PURCHASE	School	Basement	Calibrate				0.90 ± 0.10	0.90 ± 0.10	< LOD : 0.90	mg / cm ^2	Negative	Jason Fullum
3	2016-03-23 10:57	SUNY PURCHASE	School	Basement	Calibrate				0.90 ± 0.10	0.90 ± 0.10	< LOD : 1.05	mg / cm ^2	Negative	Jason Fullum
4	2016-03-23 10:57	SUNY PURCHASE	School	Basement	Calibrate				0.90 ± 0.20	0.90 ± 0.20	< LOD : 2.55	mg / cm ^2	Null	Jason Fullum
5	2016-03-23 10:58	SUNY PURCHASE	School	Basement	Calibrate				1.10 ± 0.40	1.10 ± 0.40	< LOD : 3.00	mg / cm ^2	Null	Jason Fullum
6	2016-03-23 10:59	SUNY PURCHASE	School	Basement	Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.00 ± 0.30	mg / cm ^2	Positive	Jason Fullum
7	2016-03-23 11:01	SUNY PURCHASE ADMIN	School	Basement	0004	Wall	Brown	Wood	< LOD : 0.36	< LOD : 0.36	< LOD : 3.21	mg / cm ^2	Negative	Jason Fullum
8	2016-03-23 11:01	SUNY PURCHASE ADMIN	School	Basement	0004	Door-Interior	Brown	Wood	< LOD : 0.09	< LOD : 0.09	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
9	2016-03-23 11:02	SUNY PURCHASE ADMIN	School	Basement	0004	Door-Interior	Brown	Metal	< LOD : 11.25	0.80 ± 0.40	< LOD : 11.25	mg / cm ^2	Positive	Jason Fullum
10	2016-03-23 11:04	SUNY PURCHASE ADMIN	School	Basement	0009	Door-Interior	White	Wood	< LOD : 0.06	< LOD : 0.06	< LOD : 1.98	mg / cm ^2	Negative	Jason Fullum
11	2016-03-23 11:04	SUNY PURCHASE ADMIN	School	Basement	0009	Door Frame	White	Wood	< LOD : 0.09	< LOD : 0.09	< LOD : 3.30	mg / cm ^2	Negative	Jason Fullum
12	2016-03-23 11:04	SUNY PURCHASE ADMIN	School	Basement	0009	Wal l	White	Plaster	< LOD : 13.05	< LOD : 4.65	< LOD : 13.05	mg / cm ^2	Positive	Jason Fullum
13	2016-03-23 11:05	SUNY PURCHASE ADMIN	School	Basement	0009	Stair Tread	Varnish	Wood	< LOD : 0.38	< LOD : 0.38	< LOD : 3.30	mg / cm ^2	Negative	Jason Fullum
14	2016-03-23 11:06	SUNY PURCHASE ADMIN	School	Basement	0009	Stair Handrail	Varnish	Wood	< LOD : 0.25	< LOD : 0.25	< LOD : 3.45	mg / cm ^2	Negative	Jason Fullum
15	2016-03-23 11:06	SUNY PURCHASE ADMIN	School	Basement	0009	Trim	White	Wood	< LOD : 0.23	< LOD : 0.23	< LOD : 3.60	mg / cm ^2	Negative	Jason Fullum
16	2016-03-23 11:06	SUNY PURCHASE ADMIN	School	Basement	0009	Electrical Panel	White	Metal	< LOD : 0.37	< LOD : 0.37	< LOD : 6.33	mg / cm ^2	Negative	Jason Fullum
17	2016-03-23 11:08	SUNY PURCHASE ADMIN	School	Basement	0001	Wall	White	Concrete	< LOD : 0.07	< LOD : 0.07	< LOD : 1.50	mg / cm ^2	Negative	Jason Fullum
18	2016-03-23 11:09	SUNY PURCHASE ADMIN	School	Basement	0007	Wall	White	Drywall	< LOD : 0.03	< LOD : 0.03	< LOD : 2.22	mg / cm ^2	Negative	Jason Fullum
19	2016-03-23 11:09	SUNY PURCHASE ADMIN	School	Basement	0007	Door Frame	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 3.30	mg / cm ^2	Negative	Jason Fullum
20	2016-03-23 11:10	SUNY PURCHASE ADMIN	School	Basement	0007	Door-Interior	White	Wood	< LOD : 0.07	< LOD : 0.07	< LOD : 3.28	mg / cm ^2	Negative	Jason Fullum
21	2016-03-23 11:10	SUNY PURCHASE ADMIN	School	Basement	0007	Floor	Gray	Concrete	< LOD : 0.28	< LOD : 0.28	< LOD : 3.60	mg / cm ^2	Null	Jason Fullum
22	2016-03-23 11:10	SUNY PURCHASE ADMIN	School	Basement	0007	Floor	Gray	Concrete	< LOD : 0.05	< LOD : 0.05	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
23	2016-03-23 11:12	SUNY PURCHASE ADMIN	School	Basement	0015	Ceiling	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.71	mg / cm ^2	Null	Jason Fullum
24	2016-03-23 11:13	SUNY PURCHASE ADMIN	School	Basement	0015	Ceiling	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.20	mg / cm ^2	Negative	Jason Fullum
25	2016-03-23 11:13	SUNY PURCHASE ADMIN	School	Basement	0015	Wall	White	Plaster	< LOD : 0.04	< LOD : 0.04	< LOD : 6.36	mg / cm ^2	Null	Jason Fullum
26	2016-03-23 11:13	SUNY PURCHASE ADMIN	School	Basement	0015	Wall	White	Plaster	< LOD : 0.05	< LOD : 0.05	< LOD : 7.43	mg / cm ^2	Null	Jason Fullum
27	2016-03-23 11:14	SUNY PURCHASE ADMIN	School	Basement	0015	Wall	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.86	mg / cm ^2	Negative	Jason Fullum
28	2016-03-23 13:05	SUNY PURCHASE ADMIN	School	1st Floor	1004	Wall	White	Plaster	< LOD : 0.44	< LOD : 0.44	< LOD : 7.20	mg / cm ^2	Null	Jason Fullum
29	2016-03-23 13:05	SUNY PURCHASE ADMIN	School	1st Floor	1004	Wall	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.30	mg / cm ^2	Negative	Jason Fullum
30	2016-03-23 13:05	SUNY PURCHASE ADMIN	School	1st Floor	1004	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.89	mg / cm ^2	Negative	Jason Fullum
31	2016-03-23 13:06	SUNY PURCHASE ADMIN	School	1st Floor	1005	Wal l	White	Plaster	< LOD : 27.60	< LOD : 0.04	< LOD : 27.60	mg / cm ^2	Positive	Jason Fullum
32	2016-03-23 13:07	SUNY PURCHASE ADMIN	School	1st Floor	1005	Ceiling	White	Plaster	< LOD : 5.25	< LOD : 0.03	< LOD : 5.25	mg / cm ^2	Positive	Jason Fullum
33	2016-03-23 13:07	SUNY PURCHASE ADMIN	School	1st Floor	1005D	Wal l	White	Plaster	< LOD : 27.45	< LOD : 3.15	< LOD : 27.45	mg / cm ^2	Positive	Jason Fullum
34	2016-03-23 13:08	SUNY PURCHASE ADMIN	School	1st Floor	1005D	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
35	2016-03-23 13:09	SUNY PURCHASE ADMIN	School	1st Floor	1005D	Door-Interior	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 3.73	mg / cm ^2	Negative	Jason Fullum
36	2016-03-23 13:09	SUNY PURCHASE ADMIN	School	1st Floor	1005	Door Frame	White	Wood	< LOD : 0.17	< LOD : 0.17	< LOD : 3.90	mg / cm ^2	Negative	Jason Fullum
37	2016-03-23 13:40	SUNY PURCHASE ADMIN	School	2nd Floor	2018	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.36	mg / cm ^2	Negative	Jason Fullum
38	2016-03-23 13:41	SUNY PURCHASE ADMIN	School	2nd Floor	2018	Door Frame	White	Wood	< LOD : 0.09	< LOD : 0.09	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
39	2016-03-23 13:41	SUNY PURCHASE ADMIN	School	2nd Floor	2018	Door-Interior	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 3.25	mg / cm ^2	Negative	Jason Fullum
40	2016-03-23 13:41	SUNY PURCHASE ADMIN	School	2nd Floor	2018	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.15	mg / cm ^2	Negative	Jason Fullum
41	2016-03-23 13:42	SUNY PURCHASE ADMIN	School	2nd Floor	2018	Window Case	White	Wood	< LOD : 0.05	< LOD : 0.05	< LOD : 4.20	mg / cm ^2	Negative	Jason Fullum
42	2016-03-23 13:42	SUNY PURCHASE ADMIN	School	2nd Floor	2020	Window Case	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
43	2016-03-23 13:43	SUNY PURCHASE ADMIN	School	2nd Floor	2020	Radiator	White	Metal	< LOD : 5.10	< LOD : 3.00	< LOD : 5.10	mg / cm ^2	Positive	Jason Fullum
44	2016-03-23 13:44	SUNY PURCHASE ADMIN	School	2nd Floor	2020	Trin	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.70	mg / cm ^2	Negative	Jason Fullum
45	2016-03-23 13:44	SUNY PURCHASE ADMIN	School	2nd Floor	2020	Door Frame	White	Wood	< LOD : 0.07	< LOD : 0.07	< LOD : 3.27	mg / cm ^2	Negative	Jason Fullum
46	2016-03-23 13:44	SUNY PURCHASE ADMIN	School	2nd Floor	2020	Door-Interior	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
47	2016-03-23 13:45	SUNY PURCHASE ADMIN	School	2nd Floor	2012	Door-Interior	White	Wood	< LOD : 18.75	< LOD : 3.90	< LOD : 18.75	mg / cm ^2	Positive	Jason Fullum
48	2016-03-23 13:45	SUNY PURCHASE ADMIN	School	2nd Floor	2012	Door Frame	White	Wood	7.00 ± 4.10	< LOD : 2.25	7.00 ± 4.10	mg / cm ^2	Positive	Jason Fullum
49	2016-03-23 13:46	SUNY PURCHASE ADMIN	School	2nd Floor	2012	Wal l	Beige	Plaster	< LOD : 20.40	< LOD : 8.55	< LOD : 20.40	mg / cm ^2	Positive	Jason Fullum
50	2016-03-23 14:13	SUNY PURCHASE ADMIN	School	2nd Floor	2010	Wal l	Yellow	Plaster	< LOD : 26.10	< LOD : 0.41	< LOD : 26.10	mg / cm ^2	Positive	Jason Fullum
51	2016-03-23 14:14	SUNY PURCHASE ADMIN	School	2nd Floor	2010	Door Frame	Brown	Wood	< LOD : 46.65	< LOD : 8.40	< LOD : 46.65	mg / cm ^2	Positive	Jason Fullum
52	2016-03-23 14:14	SUNY PURCHASE ADMIN	School	2nd Floor	2010	Door-Interior	Brown	Wood	< LOD : 48.30	< LOD : 8.70	< LOD : 48.30	mg / cm ^2	Positive	Jason Fullum

SUNY Purchase

Index	Time	Site	Space Type	Floor	Room	Component	Color	Substrate	PbC	PbL	PbK	Units	Results	Inspector
53	2016-03-23 14:14	SUNY PURCHASE ADMIN	School	2nd Floor	2011	Wall	Beige	Plaster	< LOD : 28.65	< LOD : 6.45	< LOD : 28.65	mg / cm ^2	Positive	Jason Fullum
54	2016-03-23 14:15	SUNY PURCHASE ADMIN	School	2nd Floor	2011	Door Frame	White	Wood	< LOD : 37.05	< LOD : 6.00	< LOD : 37.05	mg / cm ^2	Positive	Jason Fullum
55	2016-03-23 14:15	SUNY PURCHASE ADMIN	School	2nd Floor	2011	Door-Interior	White	Wood	< LOD : 24.90	< LOD : 22.65	< LOD : 24.90	mg / cm ^2	Positive	Jason Fullum
56	2016-03-23 14:22	SUNY PURCHASE ADMIN	School	2nd Floor	2001	Wall	Purple	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.30	mg / cm ^2	Negative	Jason Fullum
57	2016-03-23 14:23	SUNY PURCHASE ADMIN	School	2nd Floor	2001	Door Frame	White	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 5.65	mg / cm ^2	Negative	Jason Fullum
58	2016-03-23 14:23	SUNY PURCHASE ADMIN	School	2nd Floor	2001	Door-Interior	White	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 3.38	mg / cm ^2	Negative	Jason Fullum
59	2016-03-23 14:24	SUNY PURCHASE ADMIN	School	2nd Floor	2001	Fireplace	White	Wood	< LOD : 0.14	< LOD : 0.14	< LOD : 1.65	mg / cm ^2	Negative	Jason Fullum
60	2016-03-23 14:42	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.27	mg / cm ^2	Negative	Jason Fullum
61	2016-03-23 14:42	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Ceiling	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.27	mg / cm ^2	Negative	Jason Fullum
62	2016-03-23 14:43	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.93	mg / cm ^2	Negative	Jason Fullum
63	2016-03-23 14:43	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Window Sash	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.70	mg / cm ^2	Negative	Jason Fullum
64	2016-03-23 14:43	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Door Frame	White	Wood	< LOD : 0.33	< LOD : 0.33	< LOD : 3.20	mg / cm ^2	Negative	Jason Fullum
65	2016-03-23 14:44	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Door-Exterior	White	Wood	< LOD : 0.06	< LOD : 0.06	< LOD : 3.10	mg / cm ^2	Negative	Jason Fullum
66	2016-03-23 14:44	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Trim	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 8.55	mg / cm ^2	Null	Jason Fullum
67	2016-03-23 14:44	SUNY PURCHASE ADMIN	School	2nd Floor	2004b	Trim	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.90	mg / cm ^2	Negative	Jason Fullum
68	2016-03-23 14:45	SUNY PURCHASE ADMIN	School	2nd Floor	2008a	Wall	Green	Plaster	< LOD : 15.60	< LOD : 13.65	< LOD : 15.60	mg / cm ^2	Positive	Jason Fullum
69	2016-03-23 14:46	SUNY PURCHASE ADMIN	School	2nd Floor	2008a	Door Frame	White	Wood	< LOD : 25.05	< LOD : 10.95	< LOD : 25.05	mg / cm ^2	Positive	Jason Fullum
70	2016-03-23 14:46	SUNY PURCHASE ADMIN	School	2nd Floor	2007	Door Frame	White	Wood	2.10 ± 0.90	< LOD : 0.53	2.10 ± 0.90	mg / cm ^2	Positive	Jason Fullum
71	2016-03-23 14:47	SUNY PURCHASE ADMIN	School	2nd Floor	2007	Door-Interior	White	Wood	< LOD : 23.55	< LOD : 17.25	< LOD : 23.55	mg / cm ^2	Positive	Jason Fullum
72	2016-03-23 15:11	SUNY PURCHASE ADMIN	School	3rd Floor	3005	Door-Interior	White	Wood	< LOD : 0.32	< LOD : 0.32	< LOD : 3.46	mg / cm ^2	Negative	Jason Fullum
73	2016-03-23 15:11	SUNY PURCHASE ADMIN	School	3rd Floor	3005	Door Frame	White	Wood	< LOD : 0.09	< LOD : 0.09	< LOD : 2.70	mg / cm ^2	Negative	Jason Fullum
74	2016-03-23 15:11	SUNY PURCHASE ADMIN	School	3rd Floor	3005	Wall	Beige	Plaster	< LOD : 20.70	< LOD : 3.90	< LOD : 20.70	mg / cm ^2	Positive	Jason Fullum
75	2016-03-23 15:12	SUNY PURCHASE ADMIN	School	3rd Floor	3011	Wall	Beige	Plaster	< LOD : 24.75	< LOD : 8.25	< LOD : 24.75	mg / cm ^2	Positive	Jason Fullum
76	2016-03-23 15:13	SUNY PURCHASE ADMIN	School	3rd Floor	3001	Wall	Beige	Plaster	< LOD : 16.20	< LOD : 1.91	< LOD : 16.20	mg / cm ^2	Positive	Jason Fullum
77	2016-03-23 15:13	SUNY PURCHASE ADMIN	School	3rd Floor	3001	Window Case	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
78	2016-03-23 15:14	SUNY PURCHASE ADMIN	School	3rd Floor	3001	Window Sash	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.45	mg / cm ^2	Negative	Jason Fullum
79	2016-03-23 15:14	SUNY PURCHASE ADMIN	School	3rd Floor	3001	Trim	White	Wood	< LOD : 0.41	< LOD : 0.41	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
80	2016-03-23 15:15	SUNY PURCHASE ADMIN	School	3rd Floor	3001	Ceiling	White	Plaster	7.50 ± 4.80	< LOD : 3.60	7.50 ± 4.80	mg / cm ^2	Positive	Jason Fullum
81	2016-03-23 15:16	SUNY PURCHASE ADMIN	School	3rd Floor	3011d	Stair Handrail	Varnish	Wood	< LOD : 0.10	< LOD : 0.10	< LOD : 3.75	mg / cm ^2	Negative	Jason Fullum
82	2016-03-23 15:17	SUNY PURCHASE ADMIN	School	3rd Floor	3011d	Radiator	Silver	Metal	< LOD : 0.18	< LOD : 0.18	< LOD : 5.85	mg / cm ^2	Negative	Jason Fullum
83	2016-03-23 15:31	SUNY PURCHASE ADMIN			Calibrate				1.00 ± 0.10	1.00 ± 0.10	0.80 ± 0.30	mg / cm ^2	Positive	Jason Fullum
84	2016-03-23 15:32	SUNY PURCHASE ADMIN			Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.00 ± 0.30	mg / cm ^2	Positive	Jason Fullum
85	2016-03-23 15:33	SUNY PURCHASE ADMIN			Calibrate				1.10 ± 0.10	1.10 ± 0.10	0.80 ± 0.40	mg / cm ^2	Positive	Jason Fullum
86	2016-03-24 08:15	SUNY PURCHASE ADMIN	School		Calibrate				1.10 ± 0.10	1.10 ± 0.10	1.30 ± 0.60	mg / cm ^2	Positive	Jason Fullum
87	2016-03-24 08:16	SUNY PURCHASE ADMIN	School		Calibrate				0.90 ± 0.10	0.90 ± 0.10	1.00 ± 0.60	mg / cm ^2	Negative	Jason Fullum
88	2016-03-24 08:17	SUNY PURCHASE ADMIN	School		Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.20 ± 0.30	mg / cm ^2	Positive	Jason Fullum
89	2016-03-24 08:18	SUNY PURCHASE ADMIN	School	1st Floor	1001b	Wall	Varnish	Wood	< LOD : 0.09	< LOD : 0.09	< LOD : 2.37	mg / cm ^2	Negative	Jason Fullum
90	2016-03-24 08:19	SUNY PURCHASE ADMIN	School	1st Floor	1001b	Fireplace	White	Wood	< LOD : 0.06	< LOD : 0.06	< LOD : 2.27	mg / cm ^2	Negative	Jason Fullum
91	2016-03-24 08:19	SUNY PURCHASE ADMIN	School	1st Floor	1001b	Door-Exterior	Varnish	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.10	mg / cm ^2	Negative	Jason Fullum
92	2016-03-24 08:20	SUNY PURCHASE ADMIN	School	1st Floor	1001	Door-Interior	White	Wood	5.60 ± 3.60	< LOD : 4.50	5.60 ± 3.60	mg / cm ^2	Positive	Jason Fullum
93	2016-03-24 08:21	SUNY PURCHASE ADMIN	School	1st Floor	1001	Wall	Brown	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.27	mg / cm ^2	Negative	Jason Fullum
94	2016-03-24 08:22	SUNY PURCHASE ADMIN	School	1st Floor	1001	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.77	mg / cm ^2	Negative	Jason Fullum
95	2016-03-24 08:22	SUNY PURCHASE ADMIN	School	1st Floor	1001	Fireplace	White	Wood	< LOD : 0.07	< LOD : 0.07	< LOD : 2.49	mg / cm ^2	Negative	Jason Fullum
96	2016-03-24 08:33	SUNY PURCHASE ADMIN	School	1st Floor	1001a	Wall	Varnish	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.55	mg / cm ^2	Negative	Jason Fullum
97	2016-03-24 08:33	SUNY PURCHASE ADMIN	School	1st Floor	1001a	Wall	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.97	mg / cm ^2	Negative	Jason Fullum
98	2016-03-24 08:41	SUNY PURCHASE ADMIN	School	1st Floor	1001c	Wall	Beige	Plaster	< LOD : 20.85	< LOD : 8.25	< LOD : 20.85	mg / cm ^2	Positive	Jason Fullum
99	2016-03-24 08:41	SUNY PURCHASE ADMIN	School	1st Floor	1001c	Wall	White	Wood	< LOD : 38.25	< LOD : 10.35	< LOD : 38.25	mg / cm ^2	Positive	Jason Fullum
100	2016-03-24 08:42	SUNY PURCHASE ADMIN	School	1st Floor	1001c	Door Frame	White	Wood	< LOD : 29.85	< LOD : 8.40	< LOD : 29.85	mg / cm ^2	Positive	Jason Fullum
101	2016-03-24 08:42	SUNY PURCHASE ADMIN	School	1st Floor	1001c	Door-Exterior	White	Wood	< LOD : 24.60	< LOD : 435.00	< LOD : 24.60	mg / cm ^2	Positive	Jason Fullum
102	2016-03-24 09:52	SUNY PURCHASE HR	School	3rd Floor	3004	Stair Newel	White	Wood	< LOD : 14.55	< LOD : 21.00	< LOD : 14.55	mg / cm ^2	Positive	Jason Fullum
103	2016-03-24 09:52	SUNY PURCHASE HR	School	3rd Floor	3004	Stair Baluster	White	Wood	< LOD : 14.10	< LOD : 22.95	< LOD : 14.10	mg / cm ^2	Positive	Jason Fullum
104	2016-03-24 09:52	SUNY PURCHASE HR	School	3rd Floor	3004	Wall	White	Plaster	5.80 ± 3.80	< LOD : 6.45	5.80 ± 3.80	mg / cm ^2	Positive	Jason Fullum

SUNY Purchase

Index	Time	Site	Space Type	Floor	Room	Component	Color	Substrate	PbC	PbL	PbK	Units	Results	Inspector
105	2016-03-24 09:53	SUNY PURCHASE HR	School	3rd Floor	3004	Door Frame	White	Wood	< LOD : 19.65	< LOD : 25.95	< LOD : 19.65	mg / cm ^2	Positive	Jason Fullum
106	2016-03-24 09:53	SUNY PURCHASE HR	School	3rd Floor	3004	Door-Interior	White	Wood	< LOD : 15.15	< LOD : 55.50	< LOD : 15.15	mg / cm ^2	Positive	Jason Fullum
107	2016-03-24 09:53	SUNY PURCHASE HR	School	3rd Floor	3004	Ceiling	White	Plaster	< LOD : 4.50	4.60 ± 3.00	< LOD : 4.50	mg / cm ^2	Positive	Jason Fullum
108	2016-03-24 09:54	SUNY PURCHASE HR	School	3rd Floor	3004	Window Case	White	Wood	< LOD : 18.00	< LOD : 13.50	< LOD : 18.00	mg / cm ^2	Positive	Jason Fullum
109	2016-03-24 09:55	SUNY PURCHASE HR	School	3rd Floor	3001	Wall	White	Plaster	< LOD : 0.07	< LOD : 0.07	< LOD : 2.23	mg / cm ^2	Negative	Jason Fullum
110	2016-03-24 09:56	SUNY PURCHASE HR	School	3rd Floor	3001	Wall	White	Plaster	< LOD : 0.04	< LOD : 0.04	< LOD : 1.05	mg / cm ^2	Negative	Jason Fullum
111	2016-03-24 09:56	SUNY PURCHASE HR	School	3rd Floor	3001	Window Case	White	Wood	< LOD : 0.14	< LOD : 0.14	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
112	2016-03-24 09:57	SUNY PURCHASE HR	School	3rd Floor	3002	Window Case	White	Wood	< LOD : 18.30	< LOD : 6.75	< LOD : 18.30	mg / cm ^2	Positive	Jason Fullum
113	2016-03-24 09:57	SUNY PURCHASE HR	School	3rd Floor	3002	Wall	White	Plaster	0.06 ± 0.03	0.06 ± 0.03	< LOD : 0.75	mg / cm ^2	Null	Jason Fullum
114	2016-03-24 09:59	SUNY PURCHASE HR	School	3rd Floor	3002	Wall	White	Plaster	0.10 ± 0.03	0.10 ± 0.03	0.80 ± 0.30	mg / cm ^2	Negative	Jason Fullum
115	2016-03-24 09:59	SUNY PURCHASE HR	School	3rd Floor	3002	Door Frame	White	Wood	< LOD : 13.80	< LOD : 14.25	< LOD : 13.80	mg / cm ^2	Positive	Jason Fullum
116	2016-03-24 09:59	SUNY PURCHASE HR	School	3rd Floor	3002	Door-Interior	White	Wood	< LOD : 19.95	< LOD : 11.55	< LOD : 19.95	mg / cm ^2	Positive	Jason Fullum
117	2016-03-24 10:06	SUNY PURCHASE HR	School	3rd Floor	2001	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.35	mg / cm ^2	Negative	Jason Fullum
118	2016-03-24 10:07	SUNY PURCHASE HR	School	3rd Floor	2001	Door Frame	White	Wood	< LOD : 14.70	< LOD : 12.75	< LOD : 14.70	mg / cm ^2	Positive	Jason Fullum
119	2016-03-24 10:07	SUNY PURCHASE HR	School	3rd Floor	2001	Door-Interior	White	Wood	< LOD : 9.15	< LOD : 9.15	< LOD : 49.35	mg / cm ^2	Null	Jason Fullum
120	2016-03-24 10:07	SUNY PURCHASE HR	School	3rd Floor	2001	Door-Interior	White	Wood	< LOD : 20.70	< LOD : 6.45	< LOD : 20.70	mg / cm ^2	Positive	Jason Fullum
121	2016-03-24 10:08	SUNY PURCHASE HR	School	3rd Floor	2002	Wall	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.14	mg / cm ^2	Negative	Jason Fullum
122	2016-03-24 10:08	SUNY PURCHASE HR	School	3rd Floor	2002	Window Case	White	Wood	< LOD : 16.50	< LOD : 19.65	< LOD : 16.50	mg / cm ^2	Positive	Jason Fullum
123	2016-03-24 10:09	SUNY PURCHASE HR	School	3rd Floor	2002	Trim	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.92	mg / cm ^2	Negative	Jason Fullum
124	2016-03-24 10:10	SUNY PURCHASE HR	School	3rd Floor	2003	Wall	Beige	Plaster	< LOD : 16.50	< LOD : 1.74	< LOD : 16.50	mg / cm ^2	Positive	Jason Fullum
125	2016-03-24 10:10	SUNY PURCHASE HR	School	2nd Floor	2003	Door Frame	White	Wood	< LOD : 20.70	< LOD : 11.10	< LOD : 20.70	mg / cm ^2	Positive	Jason Fullum
126	2016-03-24 10:11	SUNY PURCHASE HR	School	2nd Floor	2003	Door-Interior	White	Wood	< LOD : 19.35	< LOD : 8.25	< LOD : 19.35	mg / cm ^2	Positive	Jason Fullum
127	2016-03-24 10:18	SUNY PURCHASE HR	School	2nd Floor	2006	Wall	Beige	Plaster	< LOD : 0.05	< LOD : 0.05	< LOD : 2.14	mg / cm ^2	Negative	Jason Fullum
128	2016-03-24 10:18	SUNY PURCHASE HR	School	2nd Floor	2006	Wall	Beige	Plaster	< LOD : 0.04	< LOD : 0.04	< LOD : 2.11	mg / cm ^2	Negative	Jason Fullum
129	2016-03-24 10:19	SUNY PURCHASE HR	School	2nd Floor	2006	Ceiling	White	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.88	mg / cm ^2	Negative	Jason Fullum
130	2016-03-24 10:19	SUNY PURCHASE HR	School	2nd Floor	2005	Wall	White	Plaster	< LOD : 0.04	< LOD : 0.04	< LOD : 2.33	mg / cm ^2	Negative	Jason Fullum
131	2016-03-24 10:20	SUNY PURCHASE HR	School	2nd Floor	2005	Door Frame	White	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 5.40	mg / cm ^2	Negative	Jason Fullum
132	2016-03-24 10:20	SUNY PURCHASE HR	School	2nd Floor	2005	Door-Interior	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.20	mg / cm ^2	Negative	Jason Fullum
133	2016-03-24 10:54	SUNY PURCHASE HR	School	2nd Floor	1001	Wall	Beige	Plaster	< LOD : 25.50	< LOD : 3.90	< LOD : 25.50	mg / cm ^2	Positive	Jason Fullum
134	2016-03-24 10:55	SUNY PURCHASE HR	School	1st Floor	1001	Window Case	White	Wood	< LOD : 0.59	< LOD : 0.59	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
135	2016-03-24 10:55	SUNY PURCHASE HR	School	1st Floor	1001	Fireplace	White	Wood	< LOD : 0.13	< LOD : 0.13	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
136	2016-03-24 10:55	SUNY PURCHASE HR	School	1st Floor	1001	Trim	White	Wood	< LOD : 0.84	< LOD : 0.84	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
137	2016-03-24 10:56	SUNY PURCHASE HR	School	1st Floor	1003	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
138	2016-03-24 10:57	SUNY PURCHASE HR	School	1st Floor	1003	Wall	Beige	Plaster	< LOD : 11.25	< LOD : 1.14	< LOD : 11.25	mg / cm ^2	Positive	Jason Fullum
139	2016-03-24 10:58	SUNY PURCHASE HR	School	1st Floor	1003a	Wall	White	Plaster	1.10 ± 0.30	0.30 ± 0.11	1.10 ± 0.30	mg / cm ^2	Null	Jason Fullum
140	2016-03-24 10:59	SUNY PURCHASE HR	School	1st Floor	1003a	Door Frame	White	Wood	< LOD : 15.75	< LOD : 7.50	< LOD : 15.75	mg / cm ^2	Positive	Jason Fullum
141	2016-03-24 10:59	SUNY PURCHASE HR	School	1st Floor	1003a	Door-Interior	White	Wood	< LOD : 20.10	< LOD : 6.60	< LOD : 20.10	mg / cm ^2	Positive	Jason Fullum
142	2016-03-24 11:00	SUNY PURCHASE HR	School	1st Floor	1003a	Ceiling	White	Plaster	0.40 ± 0.20	0.40 ± 0.20	1.10 ± 0.50	mg / cm ^2	Null	Jason Fullum
143	2016-03-24 11:01	SUNY PURCHASE HR	School	1st Floor	1003a	Ceiling	White	Plaster	0.27 ± 0.08	0.27 ± 0.08	0.90 ± 0.30	mg / cm ^2	Negative	Jason Fullum
144	2016-03-24 11:02	SUNY PURCHASE HR	School	1st Floor	1004	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.90	mg / cm ^2	Negative	Jason Fullum
145	2016-03-24 11:02	SUNY PURCHASE HR	School	1st Floor	1004	Door Frame	White	Wood	< LOD : 0.11	< LOD : 0.11	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
146	2016-03-24 11:02	SUNY PURCHASE HR	School	1st Floor	1004	Door-Exterior	Blue	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.70	mg / cm ^2	Negative	Jason Fullum
147	2016-03-24 11:03	SUNY PURCHASE HR	School	1st Floor	1002	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
148	2016-03-24 11:04	SUNY PURCHASE HR	School	1st Floor	1002	Door Frame	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 2.53	mg / cm ^2	Negative	Jason Fullum
149	2016-03-24 11:04	SUNY PURCHASE HR	School	1st Floor	1002	Door-Interior	White	Wood	< LOD : 0.33	< LOD : 0.33	< LOD : 1.88	mg / cm ^2	Negative	Jason Fullum
150	2016-03-24 12:38	SUNY PURCHASE HR	School		Calibrate				1.40 ± 0.40	1.00 ± 0.10	1.40 ± 0.40	mg / cm ^2	Positive	Jason Fullum
151	2016-03-24 12:40	SUNY PURCHASE HR	School		Calibrate				1.50 ± 0.50	1.00 ± 0.10	1.50 ± 0.50	mg / cm ^2	Positive	Jason Fullum
152	2016-03-24 12:41	SUNY PURCHASE HR	School		Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.30 ± 0.30	mg / cm ^2	Positive	Jason Fullum
153	2016-03-24 12:41	SUNY PURCHASE HR	School		Calibrate				1.10 ± 0.10	1.10 ± 0.10	1.40 ± 0.50	mg / cm ^2	Positive	Jason Fullum
154	2016-03-24 12:42	SUNY PURCHASE HR	School		Calibrate				1.10 ± 0.10	1.10 ± 0.10	1.40 ± 0.50	mg / cm ^2	Positive	Jason Fullum
155	2016-03-24 12:46	SUNY PURCHASE ANNEX	School	1st Floor	1001	Wall	White	Plaster	< LOD : 13.20	< LOD : 3.90	< LOD : 13.20	mg / cm ^2	Positive	Jason Fullum
156	2016-03-24 12:46	SUNY PURCHASE ANNEX	School	1st Floor	1002	Wall	Beige	Plaster	< LOD : 0.03	< LOD : 0.03	< LOD : 2.08	mg / cm ^2	Negative	Jason Fullum

SUNY Purchase

Index	Time	Site	Space Type	Floor	Room	Component	Color	Substrate	PbC	PbL	PbK	Units	Results	Inspector
157	2016-03-24 12:47	SUNY PURCHASE ANNEX	School	1st Floor	1002	Wall	Beige	Plaster	< LOD : 11.40	< LOD : 0.03	< LOD : 11.40	mg / cm ^2	Positive	Jason Fullum
158	2016-03-24 12:47	SUNY PURCHASE ANNEX	School	1st Floor	1002	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.83	mg / cm ^2	Negative	Jason Fullum
159	2016-03-24 12:48	SUNY PURCHASE ANNEX	School	1st Floor	1002	Door Frame	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.85	mg / cm ^2	Negative	Jason Fullum
160	2016-03-24 12:48	SUNY PURCHASE ANNEX	School	1st Floor	1002	Ceiling	White	Plaster	< LOD : 9.00	< LOD : 9.00	< LOD : 14.25	mg / cm ^2	Null	Jason Fullum
161	2016-03-24 12:49	SUNY PURCHASE ANNEX	School	1st Floor	1002	Ceiling	White	Plaster	< LOD : 3.90	< LOD : 2.25	< LOD : 3.90	mg / cm ^2	Positive	Jason Fullum
162	2016-03-24 12:50	SUNY PURCHASE ANNEX	School	Basement	0001	Wall	White	Drywall	< LOD : 0.03	< LOD : 0.03	< LOD : 1.65	mg / cm ^2	Negative	Jason Fullum
163	2016-03-24 12:51	SUNY PURCHASE ANNEX	School	Basement	0001	Stair Tread	Gray	Wood	< LOD : 0.11	< LOD : 0.11	< LOD : 3.60	mg / cm ^2	Negative	Jason Fullum
164	2016-03-24 12:51	SUNY PURCHASE ANNEX	School	Basement	0001	Stair Handrail	Gray	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.18	mg / cm ^2	Negative	Jason Fullum
165	2016-03-24 12:55	SUNY PURCHASE ANNEX	School	Basement	0001	Support Beam	Black	Metal	< LOD : 0.09	< LOD : 0.09	< LOD : 3.75	mg / cm ^2	Negative	Jason Fullum
166	2016-03-24 15:34	SUNY PURCHASE GH	School	1st Floor	Living Room	Wall	Yellow	Plaster	< LOD : 19.35	< LOD : 0.67	< LOD : 19.35	mg / cm ^2	Positive	Jason Fullum
167	2016-03-24 15:35	SUNY PURCHASE GH	School	1st Floor	Living Room	Door Frame	Yellow	Wood	< LOD : 27.00	< LOD : 5.10	< LOD : 27.00	mg / cm ^2	Positive	Jason Fullum
168	2016-03-24 15:35	SUNY PURCHASE GH	School	1st Floor	Living Room	Door-Interior	Yellow	Wood	< LOD : 7.65	< LOD : 7.65	< LOD : 33.45	mg / cm ^2	Null	Jason Fullum
169	2016-03-24 15:35	SUNY PURCHASE GH	School	1st Floor	Living Room	Door-Interior	Yellow	Wood	< LOD : 27.15	< LOD : 5.85	< LOD : 27.15	mg / cm ^2	Positive	Jason Fullum
170	2016-03-24 15:36	SUNY PURCHASE GH	School	1st Floor	Kitchen	Wall	Yellow	Plaster	< LOD : 25.65	< LOD : 5.85	< LOD : 25.65	mg / cm ^2	Positive	Jason Fullum
171	2016-03-24 15:36	SUNY PURCHASE GH	School	1st Floor	Kitchen	Window Case	Yellow	Wood	< LOD : 28.20	< LOD : 14.25	< LOD : 28.20	mg / cm ^2	Positive	Jason Fullum
172	2016-03-24 15:37	SUNY PURCHASE GH	School	1st Floor	Kitchen	Window Sash	Yellow	Wood	< LOD : 29.25	< LOD : 9.15	< LOD : 29.25	mg / cm ^2	Positive	Jason Fullum
173	2016-03-24 15:37	SUNY PURCHASE GH	School	1st Floor	Kitchen	Cabinet	Yellow	Wood	< LOD : 24.90	< LOD : 9.15	< LOD : 24.90	mg / cm ^2	Positive	Jason Fullum
174	2016-03-24 15:37	SUNY PURCHASE GH	School	1st Floor	Kitchen	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.65	mg / cm ^2	Negative	Jason Fullum
175	2016-03-24 15:38	SUNY PURCHASE GH	School	1st Floor	Living Room	Wall	White	Plaster	< LOD : 22.35	< LOD : 0.71	< LOD : 22.35	mg / cm ^2	Positive	Jason Fullum
176	2016-03-24 15:39	SUNY PURCHASE GH	School	1st Floor	Living Room	Door-Exterior	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
177	2016-03-24 15:42	SUNY PURCHASE GH	School	2nd Floor	Bedroom #1	Wall	White	Plaster	< LOD : 23.85	< LOD : 0.76	< LOD : 23.85	mg / cm ^2	Positive	Jason Fullum
178	2016-03-24 15:42	SUNY PURCHASE GH	School	2nd Floor	Bedroom #1	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
179	2016-03-24 15:43	SUNY PURCHASE GH	School	2nd Floor	Bedroom #1	Wall	White	Drywall	< LOD : 0.03	< LOD : 0.03	< LOD : 2.30	mg / cm ^2	Negative	Jason Fullum
180	2016-03-24 15:43	SUNY PURCHASE GH	School	2nd Floor	Bathroom #1	Door Frame	White	Wood	< LOD : 25.80	< LOD : 6.60	< LOD : 25.80	mg / cm ^2	Positive	Jason Fullum
181	2016-03-24 15:43	SUNY PURCHASE GH	School	2nd Floor	Bathroom #1	Door-Interior	White	Wood	< LOD : 19.65	< LOD : 13.50	< LOD : 19.65	mg / cm ^2	Positive	Jason Fullum
182	2016-03-24 15:47	SUNY PURCHASE GH	School		Calibrate				1.10 ± 0.10	1.10 ± 0.10	1.40 ± 0.50	mg / cm ^2	Positive	Jason Fullum
183	2016-03-24 15:47	SUNY PURCHASE GH	School		Calibrate				1.20 ± 0.40	1.20 ± 0.40	< LOD : 3.30	mg / cm ^2	Null	Jason Fullum
184	2016-03-24 15:47	SUNY PURCHASE GH	School		Calibrate				0.90 ± 0.50	0.90 ± 0.50	< LOD : 5.10	mg / cm ^2	Null	Jason Fullum
185	2016-03-25 10:29				Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.30 ± 0.30	mg / cm ^2	Positive	Jason Fullum
186	2016-03-25 10:29				Calibrate				0.90 ± 0.10	0.90 ± 0.10	< LOD : 0.90	mg / cm ^2	Negative	Jason Fullum
187	2016-03-25 10:30				Calibrate				1.40 ± 0.30	1.00 ± 0.10	1.40 ± 0.30	mg / cm ^2	Positive	Jason Fullum
188	2016-03-25 10:31				Calibrate				1.00 ± 0.10	1.00 ± 0.10	1.00 ± 0.30	mg / cm ^2	Positive	Jason Fullum
189	2016-03-25 10:33	SUNY PURCHASE FAC	School	2nd Floor	2001a	Wall	White	Wood	< LOD : 20.85	< LOD : 12.00	< LOD : 20.85	mg / cm ^2	Positive	Jason Fullum
190	2016-03-25 10:33	SUNY PURCHASE FAC	School	2nd Floor	2001a	Door Frame	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
191	2016-03-25 10:34	SUNY PURCHASE FAC	School	2nd Floor		Wall	White	Drywall	< LOD : 0.04	< LOD : 0.04	< LOD : 1.50	mg / cm ^2	Negative	Jason Fullum
192	2016-03-25 10:35	SUNY PURCHASE FAC	School	2nd Floor		Ceiling	White	Wood	< LOD : 0.16	< LOD : 0.16	< LOD : 0.75	mg / cm ^2	Negative	Jason Fullum
193	2016-03-25 10:35	SUNY PURCHASE FAC	School	2nd Floor		Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.40	mg / cm ^2	Negative	Jason Fullum
194	2016-03-25 10:36	SUNY PURCHASE FAC	School	2nd Floor		Stair Newel	White	Wood	< LOD : 17.40	< LOD : 9.45	< LOD : 17.40	mg / cm ^2	Positive	Jason Fullum
195	2016-03-25 10:36	SUNY PURCHASE FAC	School	2nd Floor		Stair Baluster	White	Wood	< LOD : 21.75	< LOD : 9.30	< LOD : 21.75	mg / cm ^2	Positive	Jason Fullum
196	2016-03-25 10:38	SUNY PURCHASE FAC	School	1st Floor	1006	Wall	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.49	mg / cm ^2	Negative	Jason Fullum
197	2016-03-25 10:38	SUNY PURCHASE FAC	School	1st Floor	1006	Door Frame	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.24	mg / cm ^2	Negative	Jason Fullum
198	2016-03-25 10:38	SUNY PURCHASE FAC	School	1st Floor	1006	Door-Interior	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.05	mg / cm ^2	Negative	Jason Fullum
199	2016-03-25 10:39	SUNY PURCHASE FAC	School	1st Floor	Corridor	Wall	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.59	mg / cm ^2	Negative	Jason Fullum
200	2016-03-25 10:39	SUNY PURCHASE FAC	School	1st Floor	Corridor	Window Case	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.15	mg / cm ^2	Negative	Jason Fullum
201	2016-03-25 10:39	SUNY PURCHASE FAC	School	1st Floor	Corridor	Window Sash	White	Wood	< LOD : 0.10	< LOD : 0.10	< LOD : 3.00	mg / cm ^2	Negative	Jason Fullum
202	2016-03-25 10:40	SUNY PURCHASE FAC	School	1st Floor	1001	Ceiling	White	Drywall	< LOD : 0.03	< LOD : 0.03	< LOD : 2.27	mg / cm ^2	Negative	Jason Fullum
203	2016-03-25 10:40	SUNY PURCHASE FAC	School	1st Floor	1001	Wall	Yellow	Drywall	< LOD : 0.03	< LOD : 0.03	< LOD : 2.00	mg / cm ^2	Negative	Jason Fullum
204	2016-03-25 10:41	SUNY PURCHASE FAC	School	1st Floor	1001	Window Case	Brown	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
205	2016-03-25 10:44	SUNY PURCHASE FAC	School	1st Floor	Exterior	Door Frame	Gray	Wood	< LOD : 0.16	< LOD : 0.16	< LOD : 2.42	mg / cm ^2	Negative	Jason Fullum
206	2016-03-25 10:45	SUNY PURCHASE FAC	School	1st Floor	Exterior	Door-Exterior	Gray	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.84	mg / cm ^2	Negative	Jason Fullum
207	2016-03-25 10:45	SUNY PURCHASE FAC	School	1st Floor	Exterior	Wall	White	Concrete	< LOD : 5.70	< LOD : 0.09	< LOD : 5.70	mg / cm ^2	Positive	Jason Fullum
208	2016-03-25 10:46	SUNY PURCHASE FAC	School	1st Floor	Exterior	Window Case	Gray	Wood	< LOD : 0.07	< LOD : 0.07	< LOD : 3.22	mg / cm ^2	Negative	Jason Fullum

SUNY Purchase

Index	Time	Site	Space Type	Floor	Room	Component	Color	Substrate	PbC	PbL	PbK	Units	Results	Inspector
209	2016-03-25 10:51	SUNY PURCHASE FAC	School	1st Floor	Exterior	Stair Stringer	Black	Metal	< LOD : 0.11	< LOD : 0.11	< LOD : 5.75	mg / cm ^2	Negative	Jason Fullum
210	2016-03-25 10:51	SUNY PURCHASE FAC	School	1st Floor	Exterior	Stair Handrail	Black	Metal	< LOD : 0.06	< LOD : 0.06	< LOD : 6.08	mg / cm ^2	Negative	Jason Fullum
211	2016-03-25 10:59	SUNY PURCHASE FAC	School	1st Floor	Exterior	Wall	White	Wood	4.20 ± 2.20	4.20 ± 2.20	5.80 ± 3.50	mg / cm ^2	Positive	Jason Fullum
212	2016-03-25 11:05	SUNY PURCHASE ANNEX	School	1st Floor	Exterior	Wall	White	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.70	mg / cm ^2	Negative	Jason Fullum
213	2016-03-25 11:05	SUNY PURCHASE ANNEX	School	1st Floor	Exterior	Window Case	Green	Wood	< LOD : 0.05	< LOD : 0.05	< LOD : 3.15	mg / cm ^2	Negative	Jason Fullum
214	2016-03-25 11:06	SUNY PURCHASE ANNEX	School	1st Floor	Exterior	Door Frame	Green	Wood	< LOD : 0.07	< LOD : 0.07	< LOD : 3.00	mg / cm ^2	Negative	Jason Fullum
215	2016-03-25 11:06	SUNY PURCHASE ANNEX	School	1st Floor	Exterior	Door-Exterior	Green	Metal	< LOD : 0.04	< LOD : 0.04	< LOD : 3.15	mg / cm ^2	Negative	Jason Fullum
216	2016-03-25 11:07	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Door-Exterior	Green	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 2.88	mg / cm ^2	Negative	Jason Fullum
217	2016-03-25 11:07	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Door Frame	Green	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 3.45	mg / cm ^2	Negative	Jason Fullum
218	2016-03-25 11:07	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Wall	White	Wood	< LOD : 46.95	< LOD : 136.50	< LOD : 46.95	mg / cm ^2	Positive	Jason Fullum
219	2016-03-25 11:08	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Window Case	Green	Wood	< LOD : 0.56	< LOD : 0.56	< LOD : 3.83	mg / cm ^2	Negative	Jason Fullum
220	2016-03-25 11:08	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Stair Handrail	Black	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 4.29	mg / cm ^2	Negative	Jason Fullum
221	2016-03-25 11:09	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Wall	White	CMU Block	< LOD : 0.03	< LOD : 0.03	< LOD : 1.35	mg / cm ^2	Negative	Jason Fullum
222	2016-03-25 11:10	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Door Frame	Gray	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 4.31	mg / cm ^2	Negative	Jason Fullum
223	2016-03-25 11:10	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Door-Exterior	Gray	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 3.81	mg / cm ^2	Negative	Jason Fullum
224	2016-03-25 11:11	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Wall	White	Brick	0.12 ± 0.05	0.12 ± 0.05	< LOD : 1.05	mg / cm ^2	Negative	Jason Fullum
225	2016-03-25 11:12	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Wall	White	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 2.97	mg / cm ^2	Negative	Jason Fullum
226	2016-03-25 11:12	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Stair Stringer	Gray	Metal	< LOD : 0.27	< LOD : 0.27	< LOD : 4.48	mg / cm ^2	Negative	Jason Fullum
227	2016-03-25 11:13	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Column	Gray	Metal	1.40 ± 0.30	1.40 ± 0.30	< LOD : 1.80	mg / cm ^2	Positive	Jason Fullum
228	2016-03-25 11:14	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Stair Newel	Gray	Metal	< LOD : 0.03	< LOD : 0.03	< LOD : 4.12	mg / cm ^2	Negative	Jason Fullum
229	2016-03-25 11:15	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Wall	White	Wood	< LOD : 0.22	< LOD : 0.22	< LOD : 2.40	mg / cm ^2	Negative	Jason Fullum
230	2016-03-25 11:15	SUNY PURCHASE ADMIN	School	1st Floor	Exterior	Column	Gray	Wood	< LOD : 0.45	< LOD : 0.45	< LOD : 2.25	mg / cm ^2	Negative	Jason Fullum
231	2016-03-25 11:16	SUNY PURCHASE HR	School	1st Floor	Exterior	Wall	White	Wood	< LOD : 54.75	< LOD : 7.05	< LOD : 54.75	mg / cm ^2	Positive	Jason Fullum
232	2016-03-25 11:16	SUNY PURCHASE HR	School	1st Floor	Exterior	Door Frame	Blue	Wood	< LOD : 56.40	< LOD : 9.30	< LOD : 56.40	mg / cm ^2	Positive	Jason Fullum
233	2016-03-25 11:17	SUNY PURCHASE HR	School	1st Floor	Exterior	Door-Exterior	Blue	Wood	< LOD : 48.75	< LOD : 12.90	< LOD : 48.75	mg / cm ^2	Positive	Jason Fullum
234	2016-03-25 11:17	SUNY PURCHASE HR	School	1st Floor	Exterior	Column	Blue	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
235	2016-03-25 11:18	SUNY PURCHASE HR	School	1st Floor	Exterior	Wall	White	Brick	1.80 ± 0.80	0.60 ± 0.20	1.80 ± 0.80	mg / cm ^2	Positive	Jason Fullum
236	2016-03-25 11:18	SUNY PURCHASE HR	School	1st Floor	Exterior	Window Case	Blue	Wood	4.30 ± 2.30	4.30 ± 2.30	< LOD : 4.50	mg / cm ^2	Positive	Jason Fullum
237	2016-03-25 11:19	SUNY PURCHASE HR	School	1st Floor	Exterior	Door Frame	Blue	Wood	2.80 ± 1.70	< LOD : 1.05	2.80 ± 1.70	mg / cm ^2	Positive	Jason Fullum
238	2016-03-25 11:23	SUNY PURCHASE GH	School	1st Floor	Exterior	Door Frame	Gray	Wood	< LOD : 0.03	< LOD : 0.03	< LOD : 2.16	mg / cm ^2	Negative	Jason Fullum
239	2016-03-25 11:23	SUNY PURCHASE GH	School	1st Floor	Exterior	Door-Exterior	Gray	Wood	< LOD : 0.04	< LOD : 0.04	< LOD : 2.95	mg / cm ^2	Negative	Jason Fullum
240	2016-03-25 11:24	SUNY PURCHASE GH	School	1st Floor	Exterior	Window Case	Gray	Wood	< LOD : 0.07	< LOD : 0.07	< LOD : 1.80	mg / cm ^2	Negative	Jason Fullum
241	2016-03-25 11:24	SUNY PURCHASE GH	School	1st Floor	Exterior	Wall	White	Wood	< LOD : 0.56	< LOD : 0.56	< LOD : 1.95	mg / cm ^2	Negative	Jason Fullum
242	2016-03-25 11:25	SUNY PURCHASE GH	School	1st Floor	Exterior	Wall	White	Wood	0.50 ± 0.30	0.50 ± 0.30	< LOD : 2.70	mg / cm ^2	Negative	Jason Fullum
243	2016-03-25 11:34				Calibrate				1.10 ± 0.10	1.10 ± 0.10	0.90 ± 0.50	mg / cm ^2	Positive	Jason Fullum
244	2016-03-25 11:36				Calibrate				1.00 ± 0.10	1.00 ± 0.10	0.80 ± 0.30	mg / cm ^2	Positive	Jason Fullum
245	2016-03-25 11:36				Calibrate				1.10 ± 0.10	1.10 ± 0.10	0.80 ± 0.50	mg / cm ^2	Positive	Jason Fullum

APPENDIX C

PERSONNEL AND LABORATORY CERTIFICATIONS

New York State – Department of Labor

Division of Safety and Health
License and Certificate Unit
State Campus, Building 12
Albany, NY 12240

ASBESTOS HANDLING LICENSE

Adelaide Environmental Health Associates, Inc.
Suite C24
1511 Route 22
Brewster, NY 10509

FILE NUMBER: 99-0656
LICENSE NUMBER: 29305
LICENSE CLASS: RESTRICTED
DATE OF ISSUE: 06/11/2015
EXPIRATION DATE: 07/31/2016

Duly Authorized Representative – John Soter:

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.



Eileen M. Franko, Director
For the Commissioner of Labor

United States Environmental Protection Agency

This is to certify that



Adelaide Environmental Health Associates, Inc

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 745.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires

December 05, 2017

NAT-15081-1

Certification #

November 21, 2012

Issued On



Michelle Price

Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch

NEW YORK
state department of
HEALTH

Nirav R. Shah, M.D., M.P.H.
Commissioner

Sue Kelly
Executive Deputy Commissioner

Adelaide Environmental Health
Associates, Inc.
1511 Route 22, Suite C24
Brewster, New York 10509

SEP 18 2013

Attention: John W. Soter
Radiation Safety Officer

RE: NYS Dept. of Health Radioactive
Materials License No. C2587
DH No. 13-583

Dear Mr. Soter:

Enclosed is Amendment No. 6 to New York State Department of Health Radioactive Materials License No. C2587, which makes changes to Condition Nos. 6, 7 and 8. These changes authorize your company to possess and use Cadmium 109 in a Thermo Niton XLp 303A lead-in-paint analyzer.

If I may be of assistance, please contact this office at (518) 402-7590 or:

New York State Department of Health
Bureau of Environmental Radiation Protection
Radioactive Materials Section
ESP, Corning Tower – Room 1245
Albany, New York 12237


Sincerely,



Michael G. Harmon
Associate Radiological Health Specialist

RED/MGH:ks

Enclosure: Amendment No. 6



NEW YORK STATE DEPARTMENT OF HEALTH

RADIOACTIVE MATERIALS LICENSE


Pursuant to the Public Health Law, Part 16 of the New York State Sanitary Code, Industrial Code Rule 38, and in reliance on statements and representations heretofore made by the licensee designated below, a license is hereby issued authorizing radioactive material(s) for the purpose(s), and at the place(s) designated below. The license is subject to all applicable rules, regulations, and orders now or hereafter in effect of all appropriate regulatory agencies and to any conditions specified below.

1. NAME OF LICENSEE FEIN 16-1232927 Adelaide Environmental Health Associates, Inc. Phone (845) 287-7710	3. LICENSE NUMBER C2587
2. ADDRESS OF LICENSEE 1511 Route 22, Suite C24 Brewster, New York 10509	4. EXPIRATION DATE April 17, 2018
	5a. REFERENCE DH 13-583
	b. AMENDMENT NO. 6

6. Radioactive Materials (elements in mass number)	7. Chemical and/or physical form	8. Maximum quantity licensee may possess at any one time
A. Cobalt 57	A. Sealed source	A. 24 millicuries
B. Cadmium 109	B. Sealed source	B. 80 millicuries

9. Authorized use.

- A. The licensee is authorized to use any sealed source or associated portable x-ray fluorescence device which has been manufactured and distributed in accordance with a specific license issued by an Agreement State or the United States Nuclear Regulatory Commission. Combinations of sources and devices must be compatible for use as stated in a Sealed Source and Device Registration Certificate (i.e., stated in the registration certificate for the source or device).
- B. No single source may exceed the maximum activity specified for that nuclide in the Sealed Source and Device Registration Certificate for any device in which the source is to be used.



NEW YORK STATE DEPARTMENT OF HEALTH
RADIOACTIVE MATERIALS LICENSE

3. License Number C2587

5a. Reference DH 13-583

b. Amendment No. 6

9. C. Only portable x-ray fluorescence devices which require continuous activation by the operator, and which incorporate a mechanism to automatically return the source to its shielded position (e.g., a “dead-man” switch) may be obtained and used under this license. Devices which rely upon positive action by the operator to shield the source, such as operation of a key switch, or which do not require continuous operator activation during exposure, are not authorized under this license.
10. A. The Radiation Safety Officer (RSO) for this License is John W. Soter.
- B. Licensed material shall be used by, or under the supervision of, the Radiation Safety Officer, by licensee personnel trained and certified by the manufacturer. The licensee shall maintain a complete and accurate record of the qualifications of each person permitted to use radiation sources under this license.
11. Except as specifically provided otherwise in this License, the licensee shall conduct its program in accordance with the statements, representation and procedures contained in the documents, including any enclosures, listed below. The Department’s Regulations shall govern, unless the statements, representation and procedures in the licensee’s application and correspondence are more restrictive than the Regulations.
- A. License Renewal Request dated January 31, 2008, signed by Stephanie Soter, President.
- B. Renewal Application dated March 12, 2008, signed by John Soter, with attachments.
- C. Letter dated March 25, 2008, signed by Kerry McGuinness, with attachments.
- D. License Renewal Application dated March 28, 2011, signed by John W. Soter.
- E. **Letter dated August 9, 2013, signed by John Soter.**
12. A. Licensed material shall be stored at the location indicated in Condition 2 and may be used at temporary job sites of the licensee anywhere within the State of New York, where the Department of Health exercises jurisdiction.



NEW YORK STATE DEPARTMENT OF HEALTH
RADIOACTIVE MATERIALS LICENSE

3. License Number C2587

5a. Reference DH 13-583

b. Amendment No. 6

12. B. Overnight storage at other locations shall be in accordance with statements referenced in Condition 11 of the license, provided that such storage may not be in a residence, or in an attached garage except within a vehicle. Any vehicle used for storage shall be driven only for purposes associated with use or transport of the contained radioactive material, by a person qualified to use the material, and no passengers shall be carried unless they are also involved in work under this license. Vehicular storage shall only be allowed if no other storage is possible and shall not exceed five (5) consecutive nights unless authorization to exceed this limit is obtained from the Department.
- C. Under no circumstances shall radioactive material authorized by this license be transferred to the custody of any person or firm other than the licensee, or be used or stored by another person or firm or its employees; unless that person or firm possesses a valid license to possess and use such radioactive material.
13. Sealed sources containing radioactive materials shall not be opened or removed from devices.
14. A. The licensee is not authorized to dismantle, repair or affect any changes in the source holders/devices.
- B. The licensee shall not alter labels attached to source holders or devices, and shall maintain labels in legible condition at all times.
15. The licensee shall instruct persons who engage in work under the license, in accordance with 10 NYCRR 16.13(c). Such instruction shall include the licensee's operating and emergency procedures, and other information contained in documents incorporated in Condition 11.
16. The licensee shall conduct a physical inventory every six (6) months to account for all devices received and possessed under the License. The records of the inventories shall be maintained for three (3) years from the date of the inventory for inspection by the Department, and shall include the quantities and kinds of licensed material, manufacturer's name and model number, location of devices, the date of the inventory, and the name of the person who performed it.
17. A. The licensee shall maintain a utilization log containing the identification of devices used, dates removed and returned to storage, the location of use, and the identity of user.



NEW YORK STATE DEPARTMENT OF HEALTH
RADIOACTIVE MATERIALS LICENSE

3. License Number C2587

5a. Reference DH 13-583

b. Amendment No. 6

17. B. The log shall be kept at the location of storage and shall contain sufficient detail to enable the licensee to inform the Department, at any time, of the exact location of each device.
18. Current copies of the following documents shall be maintained at temporary job sites for Department inspection:
- A. The manufacturer's instruction manual and the licensee's operating and emergency procedures.
 - B. A copy of the results of the latest test for leakage and/or contamination performed on the sealed sources.
 - C. A copy of this license.
19. In the event that a theft, loss or other serious incident does occur, the Department shall be notified immediately by telephone, and subsequent information acquired by the licensee shall be reported as it is received. All device users must carry the NYSDOH's current telephone number in their emergency procedures.
20. The licensee shall ensure that all persons authorized to use portable devices comply with safe use and maintenance procedures and that they do not leave a device unattended or unsecured at any time, even for a few minutes.

FOR THE NEW YORK STATE DEPARTMENT OF HEALTH

Date: **SEP 18 2013**

RED/MGH:ks

By Robert E. Dansereau
Robert E. Dansereau
Assistant Director
Bureau of Environmental Radiation Protection

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER



Expires 12:01 AM April 01, 2017
Issued April 01, 2016

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. MICHELLE MCGOWAN
EMSL ANALYTICAL, INC.
528 MINEOLA AVE.
CARLE PLACE, NY 11514

NY Lab Id No: 11469

is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE
All approved subcategories and/or analytes are listed below:

Miscellaneous

Asbestos in Friable Material	Item 198.1 of Manual EPA 600/M4/82/020
Asbestos in Non-Friable Material-PLM	Item 198.6 of Manual (NOB by PLM)
Asbestos in Non-Friable Material-TEM	Item 198.4 of Manual
Asbestos-Vermiculite-Containing Material	Item 198.8 of Manual
Lead in Dust Wipes	EPA 7000B
Lead in Paint	EPA 7000B



Sample Preparation Methods

EPA 3050B

Serial No.: 54283

Property of the New York State Department of Health. Certificates are valid only at the address shown, must be conspicuously posted, and are printed on secure paper. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify the laboratory's accreditation status.

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



JASON P FULLUM
CLASS(EXPIRES)
C ATEC(02/17) D INSP(02/17)
H PM (02/17) I PD (02/17)

CERT# 97-20574
DMV# 375065936

MUST BE CARRIED ON ASBESTOS PROJECTS

01213 000729880 56

EYES BLU
HAIR BRO
HGT 5' 11"

IF FOUND RETURN TO:
NYSDEL - L&C UNIT
ROOM 161A BUILDING 12
STATE OFFICE CAMPUS
ALBANY NY 12240

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



ROBERT A SEE

CLASS(EXPIRES)

C ATEC(04/17) D INSP(04/17)

E MGPL(04/17) H PM (04/17)

CERT# 06-09124
DMV# 805716986

MUST BE CARRIED ON ASBESTOS PROJECTS



01213 000752113 16

EYES BRO

HAIR BRO

HGT 5' 09"

IF FOUND RETURN TO:

NYSOL - L&C UNIT

ROOM 161A BUILDING 12

STATE OFFICE CAMPUS

ALBANY NY 12240

New York
RISK ASSESSOR



**Certified Lead-Based
Paint Professional**

Certification No. NY-R-12098-4	
Date of Birth 02/26/1974	Expiration Date 07/11/2017
Address 3 Calmer Place Hyde Park, NY 12538	
Badge Holder's Name Jason Pierre Fullum	
Badge Holder's Signature 	




If found, drop in any mailbox
Postmaster: Please return to:

**US EPA
1200 Pennsylvania Ave, NW
(MC-7404T)
Washington, DC 20460
or Call 1-800-424-LEAD**

New York
RISK ASSESSOR



**Certified Lead-Based
Paint Professional**

Certification No. NY-R-101137-1	
Date of Birth 04/09/1965	Expiration Date 07/22/2017
Address 15 Boyce Street Beacon, NY 12508	
Badge Holder's Name Robert Alan See	
Badge Holder's Signature 	




If found, drop in any mailbox
Postmaster: Please return to:

US EPA
1200 Pennsylvania Ave, NW
(MC-7404T)
Washington, DC 20460
or Call 1-800-424-LEAD



APPENDIX D



SAMPLE LOCATION MAPS

AND PHOTOS






ADMINISTRATION BUILDING 1/8" SCALE @ 24"X36"





BUSINESS ANNEX
1/8" scale






212-213 2nd FLOOR

214-215

212-213

2nd FLOOR



1st FLOOR

180-193

196-197


174-179

198-199

194-195

270-273

274-275



BASEMENT

200-201




298-299

202-207

210-211

208-209


GATEHOUSE 1/8" Scale



SUNY Purchase

Human Resources Basement

PGA:15100.02-IN





**Sample #10 – Plaster Wall Base Coat – 1.48%
Chrysotile**



**Sample #24 – Plaster Ceiling Base Coat – 1.54%
Chrysotile**



Sample #39 – Joint Compound – 2.11% Chrysotile



Sample #49 – Material Behind Heat Shield – 50% Chrysotile



Sample #52 - Pipe Insulation Debris - 19.10% Chrysotile



Sample #154 - Pipe Insulation - 22.20% Chrysotile



Sample #157 - Debris on Metal Support - 28.60% Chrysotile



Sample #196 – Linoleum and Mastic – 11.4% Chrysotile



**Sample #202 and 205 – Pipe Insulation and Mudded Fitting –
80.00% and 40.00% Chrysotile**



Sample #211 – Flue Sealant – 1.4% Chrysotile



Sample #212 – 9x9 Floor Tile and Mastic – 1.2% Chrysotile



Sample #216 – Floor Tile – Beige with Streaks – 1.4% Chrysotile



Sample #226 – Cement Board – 36.40% Chrysotile



Sample #228 - Flue Sealant - 1.75% Chrysotile



Sample #246 - Cementitious Siding - 33.30% Chrysotile




Sample #250 – Pipe Insulation – 50.00% Chrysotile



Sample #253 – Debris – 57.10% Chrysotile


APPENDIX E
AFFECTED AREA MAPS



Asbestos Plaster and/or Joint Compound



Asbestos Behind Heat Shields



Pipe Insulation Debris








Asbestos Plaster






FACILITIES BUILDING
1/8" scale


-  Asbestos Floor Tile
-  Asbestos Cement Board and Flue Sealant
-  Asbestos Pipe Insulation and Debris

** All exterior siding is asbestos




Asbestos 9x9 Floor Tile and Mastic

2nd FLOOR



Asbestos Linoleum and Mastic

1st FLOOR



Asbestos Flue Sealant

BASEMENT






Asbestos Pipe Insulation


GATEHOUSE 1/8" Scale

SUNY Purchase

Human Resources Basement

PGA:15100.02-IN

-  Asbestos Pipe Insulation
-  Asbestos Debris on Metal Support
-  Assumed Boiler Flue Sealant



APPENDIX F

NYS DOL GUIDELINES FOR CONTAMINATED AREAS

56-1.5 Responsibility for Cleanup of Uncontrolled Disturbance. If there is an incidental disturbance or other disturbance (not as part of a controlled asbestos project) of ACM, PACM, asbestos material, or suspect miscellaneous ACM assumed to be ACM at a building or structure, upon discovery of the disturbance, the property owner shall be responsible for contracting with a licensed asbestos contractor for immediate isolation of the disturbance and cleanup in accordance with all provisions of this Part.

DOL Guidance Document

56-1.5 Question: Responsibility for Cleanup of Uncontrolled Disturbance. Are property owners subject to a potential violation of ICR 56 if ACM or PACM is disturbed by a trade's contractor or other entity unbeknownst to the owner and the damaged material or debris fallout is subsequently discovered by an Asbestos Control Bureau inspector? Is the party who disturbed the ACM or PACM required to notify the property owner, to aid the owner in complying with this requirement?

Answer/Guidance: Similar to US OSHA, any contractor performing a general supervisory role on any renovation, remodeling, demolition, or repair project is responsible for informing all contractors under their direct general supervision and control that any disturbance to ACM, PACM and asbestos material (known or assumed) at the site is prohibited by any contractor other than the asbestos contractor.

Also, the contractor performing the general supervisory role shall require all asbestos contractors under their direct general supervision and control to be in compliance with Code Rule 56. (This requirement does not include entering asbestos project work areas to check on the asbestos contractor.)

In addition, Section 1.4 includes contractor notification requirements to the building/structure owner or their representative for newly discovered materials and any disturbances to ACM, PACM or suspect miscellaneous materials.

Once a disturbance is discovered, it must be cleaned up as soon as possible. For all disturbances, the room/space/area must be vacated and isolated immediately, and an asbestos contractor must be hired for appropriate cleanup of affected room/area/space. A site-specific variance is necessary for cleanup of any disturbance other than a Minor size incidental disturbance.