


# SU-081523 Campus Security Upgrades – Addendum #3

## Photos of Existing Conditions


### Music Building




View of Telecom Racks in Sub-Basement (South End)




View of Telecom Cable Tray (South End)




View of Ceiling Above Telecom Racks (South End)



View of Ceiling in Sub-Basement (South End)



View of Telecom Racks in Sub-Basement (North End)



View of Telecom Rack & Cable Tray (North End)



# SU-081523 Campus Security Upgrades – Addendum #3

## Photos of Existing Conditions

### Music Building



View of Telecom Rack (North End)



View of Cable Tray & Risers (North End)




View of Lower Level Entrance at West 2 Parking Lot



View at Lower Level Lobby Looking Northeast



View Looking Towards West 2 Entrance Lobby



View of Corridor Outside at Doors #0041 & #0040

**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Music Building**



View of Corridor Outside of Suite #0050




View at Corridor of Door #0107



View at Corridor of Door #0058



View of Suite #0058



View of Basement Corridor Looking Towards Doors #0119



View of Suite 0089 Looking North



# SU-081523 Campus Security Upgrades – Addendum #3

## Photos of Existing Conditions

### Music Building



View of Main Plaza Entrance Vestibule



View of Main Entrance Doors at Plaza Level



View of Plaza Level Lobby



View of Music Admin. Suite



View of Existing Cable Pass-thru Conduits in Admin. Suite



View of 1<sup>st</sup> Floor Corridor Looking North



# SU-081523 Campus Security Upgrades – Addendum #3

## Photos of Existing Conditions

### Dance Building



View of Plaza Entry Doors Vestibule




View of Typical Plaza Level West Side Corridor



View at Typical Water Fountain – Plaza Level



Typical Entrance Door into Studio



View Inside Typical Studio Space



View Inside Typical Studio Space



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Dance Building**



View of Plaza Level Rear Entrance



View of Typical Plaza Level East Side Corridor



View of Typical Stairwell Exit Doors



View at Mid-Building Breezeway Looking West



View of Lower Level Entrance at Breezeway



View of Cross-Corridor Along Breezeway



# SU-081523 Campus Security Upgrades – Addendum #3

## Photos of Existing Conditions

### Dance Building



View of Lower Level East Side Corridor




View of Lower Level East Side Corridor



View Entering Lower Level Main Lobby



View of Lower Level Main Lobby



View Looking at Doors #0054 & #0055



View of Dance Admin. Suite - Lower Level



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Dance Building**



View of Southwest Entrance at Lower Level




View of Tunnel Entrance on West Side




View of West Corridor on Lower Level



View Inside Mechanical Room at Door #0045



View inside Mechanical Room Looking East



View of West Corridor at Door #0042



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Dance Building**



View of Corridor Outside of Room #0038



View of Corridor at Elevator – Lower Level



View of Corridor Outside of Room #0036



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Social Science Building**



View of Plaza Level Lobby Looking South



View of Plaza Level Lobby Looking North



View of Corridor Next to Stairwell #1



View of Corridor Outside Door #1004



Plaza Level East Corridor Looking North



View of Corridor at Door #1039B



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Social Science Building**



View of Cross-Corridor at Plaza Level



View of Cross-Corridor at 2<sup>nd</sup> Floor




View of West Corridor at 2<sup>nd</sup> Floor Looking South



View Looking Towards 2<sup>nd</sup> Floor Lobby



View of West Exterior Entrance into SS Bldg.



View of SS Lower Level Entrance Vestibule



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Social Science Building**



View of Lower Level Entry Lobby




View of Lower Level Entry Lobby




View of Corridor Outside of Door #0048



View of East Corridor Looking South



View of Corridor at Lower Level Near Stair #1



View of Corridor Next to Elevator at Lower Level



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Social Science Building**



View of Corridor at Door #0003



View at Corridor Leading to Stairwell #1



View of Exterior Exit Door in Stairwell #1



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Humanities Building**



View of Plaza Level East Entrance Lobby




View of Plaza Level East Corridor Looking South



View of Plaza Level Cross-Corridor on North Side



View of Plaza Level Main Lobby



View of Plaza Level Corridor at Main Stairs



View of Corridor Outside of Doors #1030C & #1032A



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Humanities Building**



View of West Corridor Looking Toward Main Lobby



View of Cross-Corridor at Plaza Level



View of Plaza Level West Corridor Looking South



View of Corridor Outside of Doors #1044B & #1043A



View of Plaza Level South Lobby



View of Plaza Level South Lobby



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**



View of Exterior South Entrance Doors



View of South Entrance Vestibule




View of Door #1077A from South Entry Vestibule



View of Doors #1077A & 1057A



View of Plaza Level Corridor at South Entrance



View of Plaza Level Corridor - South Wing



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**



View of Door #1060A from Corridor




View of Door #1060A From Room Side




View of Sliding Doors #1050



View of Doors #1050A



View Looking Towards Stairwell Door #1076B



View Looking Towards Stairwell Door #1074B



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**



View From Corridor of Doors #1029A



View of Doors #1029A from Room Side




View of Door #1028 from Corridor Side



View of Door #1028 from Room Side



View of Doors #1027 from Room Side



View of Corridor at Doors #1027 Looking North



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**


**Visual Arts Building**



View of Mid-Building Entry Vestibule Looking North



View of Doors #137 from Corridor Looking South




View of Corridor #1075 Looking North



View of Doors #1009 from Corridor



View from Inside Printmaking Suite



View of Door Leading into Stairwell Vestibule #1013A



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**




View North from North Wing Plaza Level Corridor



View from Corridor #1072 Looking East



View of Doors #1072A from Corridor



View of Corridor #1072 Looking North



View at New Wall Location at East Side of Room #1018




View of Corridor Near Stairwell #2 Looking North



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**



View of Door #1063 at Stairwell #2




View of Doors #1041




View of Doors #1062



View of 2<sup>nd</sup> Floor Corridor #2042 Looking South



View of 2<sup>nd</sup> Floor Corridor at Door #2012



View of 2<sup>nd</sup> Floor Corridor Outside of IT Closet



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**



View of Doors #2014A from Corridor




View of Corridor #2014A Looking East



View of Doors #2014B



View of Door #2014C



View Across Walkway Looking at New Door & Wall Location



View from Other Side Looking North



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Visual Arts Building**



View of Door #2021A from Room Side



View of 2<sup>nd</sup> Floor Corridor Looking South



View of Doors #2028A for Corridor



View of Room #2028 Looking East



View of 3<sup>rd</sup> Floor Elevator Lobby



View of Door #3003B



# SU-081523 Campus Security Upgrades – Addendum #3

## Photos of Existing Conditions

### Visual Arts Building



View of Doors #3001 from Elevator Lobby




View of Doors #3001 from Room Side



View of Corridor Near Basement Elevator Lobby



View of Corridor #0054 Looking East



View of Corridor #0050 Looking North



**SU-081523 Campus Security Upgrades – Addendum #3**  
**Photos of Existing Conditions**

**Fort Awesome**



View Inside of Main Classroom Lobby #146



View of Classroom #137 Looking West



View of Classroom #138 Looking West



View of Classroom #136 Looking East



View of Classroom #135 Looking East



View of Classroom #142 Looking East